



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

TP Budget Direct.
Xiao Chen.

Vehicle No. SLT3771R

WBAXG120000W34198

BMW 520i

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR BUMPER <i>dent</i>		1558.00	✓
2	REAR BUMPER SIDE HOLDER @105 <i>new</i>		210.00	+
3	REAR BUMPER REFLECTOR @45 <i>RH cruld</i>		90.00	45
4	REAR BUMPER TOW COVER <i>missing</i>		34.00	✓
5	REAR BUMPER REINFORCEMENT <i>Dented</i>		697.00	✓
6	REAR BUMPER REINFORCEMENT COVER <i>cruld</i>		205.00	✓
7	REAR BUMPER CENTRE GUIDE <i>cruld</i>		197.00	✓
8	REAR BUMPER HANDSFREE SESNOR <i>3AP</i>		394.00	+
9	REAR BUMPER HANDSFREE SESNSOR MODULE <i>new</i>		410.00	+
10	REAR BUMPER UNDERCOVER <i>cruld</i>		137.00	✓
11	REVERSE SENSOR @250 <i>2 pieces done</i>		1000.00	510
12	REVERSE SENSOR HOLDER @25 <i>new</i>		100.00	✓
13	REAR END PANEL <i>new</i>		945.00	x
14	REAR END PANEL TOP GARNISH <i>new</i>		225.00	+
15	TAILLAMP @634 <i>new</i>		1268.00	x.
16	BOOTLID <i>Dented</i>		1642.00	✓
17	BOOTLID LOCK <i>new</i>		345.00	✓
18	BOOTLID WEATHERSTRIPE <i>new</i>		210.00	x.
19	BOOTLID REFLECTOR @385 <i>RH cruld</i>		770.00	385
20	BMW LOGO <i>new</i>		75.00	✓
21	520i EMBLEM <i>new</i>		89.00	✓
			10601.00	
less			51%	5%
			530.05	
			10070.95	
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE <i>new</i>		30.00	+
2	REAR NUMBER PLATE HOLDER <i>new</i>		30.00	+
3	REAR BUMPER CLIPS <i>new</i>		50.00	✓
4	REAR BUMPER UNDERCOVER CLIPS <i>new</i>		20.00	✓
5	REAR END PANEL TOP GARNISH CLIPS <i>new</i>		20.00	+
6	REAR END PANEL SEALANT <i>new</i>		60.00	x.
Total Parts			210.00	



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

Vehicle No. SLT3771R

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	OUR ASSESSMENT (\$)
	LABOUR		
1	PANEL BEATING	1200.00	750
2	SPRAY PAINTING	1200.00	750
3	WIRING	50.00	30
4	TO APPLY TUFF COAT	150.00	40
5	TO REMOVE UPHOLSTERY	150.00	30
6	TO TRANSFER BOOTLID FITTINGS	150.00	60
7	TO REMOVE REVERSE SENSOR	100.00	50
	& To perform diagnostic test 200		
	Labour Total :	3000.00	
	TOTAL (PARTS & LABOUR):	13280.95	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total. 7668.55
L/s: 6.1K.
05 Days