

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: QBE	DATE	: 06/09/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SGW4128K	<i>Justin.</i>	
MODEL	: HONDA STREAM 1.8A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>	DATE : 4-Sep-21		
	TIME : 09:45HRS		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,250.30	\$ 1,250.30
2	TAILGATE LOGO <i>new</i>	1	\$ 62.00	\$ 62.00
3	TAILGATE EMBLEM 'STREAM' <i>new</i>	1	\$ 55.00	\$ 55.00
4	TAILGATE INNER LOCK <i>Dent</i>	1	\$ 194.60	\$ 194.60
5	TAILGATE WEATHER STRIP <i>nt</i>	1	\$ 157.80	\$ 157.80
6	TAILGATE INNER BOARD <i>cracked</i>	1	\$ 211.00	\$ 211.00
7	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 133.00	\$ 133.00
8	REAR BUMPER <i>Dented</i>	1	\$ 633.20	\$ 633.20
9	REAR BUMPER TOWING COVER <i>Dented</i>	1	\$ 50.00	\$ 50.00
10	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 62.40	\$ 124.80
11	TAILLAMP LH <i>cracked</i>	1	\$ 412.00	\$ 412.00
12	REAR FENDER INNER TRIM LH <i>cracked</i>	1	\$ 466.80	\$ 466.80
13	REAR END PANEL <i>Dented</i>	1	\$ 580.00	\$ 580.00
14	REAR END PANEL TOP GARNISH <i>cracked</i>	1	\$ 160.00	\$ 160.00

TOTAL PRICE \$ 4,490.50

LESS 20% \$ 898.10

SUB TOTAL PRICE \$ 3,592.40

SPECIAL NETT ITEMS

803.

358.

285

3845.40

3076.32

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Abc u</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS(SET) <i>M</i>	1	\$ 20.00	\$ 20.00
3	TAILGATE INNER BOARD CLIP(SET) <i>M</i>	1	\$ 20.00	\$ 20.00
4	TAILGATE WINDSCREEN SEALANT <i>M</i>	1	\$ 100.00	\$ 100.00
5	REAR FENDER INNER TRIM CLIP(SET) <i>M</i>	1	\$ 20.00	\$ 20.00
6	TAILLAMP CLIP(SET) <i>M</i>	1	\$ 20.00	\$ 20.00
7	REAR END PANEL TOP GARNISH CLIPS(SET) <i>M</i>	1	\$ 20.00	\$ 20.00
8	REAR END PANEL INSULATION SEAL <i>M</i>	1	\$ 80.00	\$ 80.00
9	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00

420

TOTAL

\$

550.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,400.00	800	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	800	
3	TUFF COAT	\$ 250.00	60	
4	WIRING AND BULB CHECK	\$ 180.00	30	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 150.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 150.00	50	
7	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 140.00	120	
8	TRANSFER TAILGATE MECHANISM	\$ 120.00	60	

1980

TOTAL

\$3,790.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,142.40

TOTAL LABOUR COST : \$ 3,790.00

TOTAL REPAIR COST : \$ 7,932.40

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM

NO OF DAYS :

LKK Auto Consultants hence notify the Repairer of the following: **FAX**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lily
E/S 08/09/21.

06 Days
Label: 547632

E/S: 4K (Nett Value)

Nett Value (4K)