

ASS. REC. BY: marcus

REF:

CS/EG/21009462/uf3

ASSIGNMENT

From:

Date:

Veh No:

F3L 4241H

Yr Regn:

14/12/16

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

F3L 4241H
RF.

Make:

Yamaha MT-09A ABS c 847

at Workshop m/s

Colour

Grey

A/C: Insured / Std / NI / NA

of

Sp. Reading

61419

T/Radio: Insured / Std / NI / NA

Insured:

SDS 8999T

Eng/No:

Policy No.

C/No:

JYARN295000004672

Claims No.

CDMPG21001492

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Locked / Jammed / Leaked / Burnt or affected


(Client's Record)

Brake: Locked / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$15K.

Tyre Size:

F:

120 / 70-24 17

R:

180 / 55-24 17

IDAC Accident Report:

Consistent?: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /

GIA / PR Seen:

Consistent?: Yes or No

TOYO / YOKO or

Est. Repairs:

6

days

Res.: Yes or No

Front

6

Rear

6

Lum Sum:

20

%

3 Val.: Yes or No

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

12/8/21

D.O.I.

9/9/21

Survey held at

CA / REV / REP. / 24 HRS

395e

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

LTA 54314

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Sol 544. 2nth. Rep 2800

Nett \$10686

L/S \$9500 confirmed with AGen. 6 repair days

(RED \$13792; 59%)

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 6

1) 1/12 TYPIST

☐

Final Report

Resurvey No. of Trip: 2

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

Site Insp (\$

) \$ + RS \$ SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format: TP

Lump Sum L/S: (\$ 9500

TOTAL

* Submit to insurance.

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE No: FBL 4241H

1PC	FRONT FENDER	cut	185		\$325.00	—
1PC	HEADLAMP	scr	449		\$1,100.00	—
1PC	FRONT WINDSHIELD	scr/cr	210		\$280.00	—
1PC	FRONT SIGNAL LAMP O/S	cut	60		\$160.00	—
1PC	FRONT FORK ASSY N/S	scr			\$1,990.00	X
1PC	FRONT FORK ASSY O/S	scr/tw	1600		\$1,990.00	X
1PC	FRONT FORK UNDER BRACKET	scr	520		\$685.00	—
1PC	FRONT FORK UPPER STEM	scr	645		\$690.00	—
1PC	FRONT SPORT RIM	scr/mixed	980		\$1,450.00	—
1PC	FRONT BRAKE DISC O/S	scr/mixed	450		\$515.00	—
1PC	BRAKE LEVER	scr	90		\$140.00	—
1PC	HANDLE BAR	scr	425		\$520.00	—
1PC	HANDLER BAR BALANCE O/S	cut	45		\$60.00	—
1PC	HANDLE BAR GRIP O/S	n			\$85.00	X
1PC	MIRROR O/S	cut			\$100.00	—
1PC	FUEL TANK	scr/scr	1480		\$1,680.00	—
1SET	FUEL TANK PAD	scr/scr	280		\$300.00	—
1PC	FUEL TANK LOWER GARNISH O/S	cut	290		\$420.00	—
1PC	RADIATOR	scr	1120		\$980.00	—
1PC	RADIATOR CAP	cut			\$38.00	—
1PC	RADIATOR OUTER PROTECTOR	cut/tw	285		\$420.00	—
1PC	BODY FRAME	R			\$3,500.00	X
1PC	CLUTCH OUTER COVER O/S	cut	460		\$490.00	—
1PC	FRONT FOOT BRAKE PEDAL	cut/scr			\$165.00	—
1PC	FRONT FOOT REST O/S	cut			\$90.00	—
1PC	FRONT FOOT REST BRACKET O/S	scr			\$205.00	X
1PC	FRONT SIDE GARNISH O/S	cut	200		\$260.00	—
1PC	EXHAUST ASSY	R			\$1,200.00	X
1PC	REAR FOOT REST O/S	n			\$180.00	X
1PC	REAR SLIDER O/S	cut			\$120.00	—
1PC	REAR SEAT CUSHION	scr	300		\$450.00	—
1PC	REAR SEAT COVER	cut	520		\$600.00	—
1PC	REAR BOX	cut			\$500.00	—
1PC	REAR BOX BRACKET	scr			\$180.00	X
1PC	REAR LICENCE PLATE	cut			\$12.00	10 S/N
1PC	FRONT LICENCE PLATE STICKER	scr			\$12.00	10 S/N
					\$21,892.00	

TO CHECK WIRING

TO STRAIGHTEN & REPAIR BODY FRAME

LABOUR FOR PANEL BEATING & REPLACED PARTS

To spray painting

11 \$50.00 X
\$450.00 300
\$400.00 300
\$500.00 380

P-12/103

108
10897.7

1181.7

7940923,292