

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009470/KEA3Q2**Date:** 17/05/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SFH1818M **Insured Vehicle No :** SME4116T
 Date of Loss: 02/09/2021 Nature of Claim: TP Claim No: 9810932366SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFH1818M**
 Make & Model: INFINITI Q60, 2.0 T COUPE (A) Engine No: 274AE125730A
 Reg. Date: 28/08/2020 (Man. Year: 2019) Chassis No: JN1GCAV37Z0480023
 Colour: Metallic Blue Odometer: 17744 km
 Engine Capacity: 1991 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40 R19 Rear Tyre Size: 255/40 R19
 Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
 Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,559.60	1,193.58	6,366.02	84.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,140.00	615.00	2,525.00	80.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,699.60	1,808.58	8,891.02	83.10
Approved Total (Overridden) (S\$)		1,450.00		
(S\$)	10,699.60	1,450.00	9,249.60	86.45
+ GST 7.00/7.00% (S\$)	748.97	101.50	647.47	86.45
Nett Amount (S\$)	11,448.57	1,551.50	9,897.07	86.45
+ Car Rental (5.0 x S\$160.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		2,380.50		
Global Sum Settlement (S\$)		2,380.00		

INSPECTION

Date of Assignment: 08/09/2021
 Date Inspected: 09/09/2021 Inspected At: Yee Auto Pte Ltd (HQ)
 160 SIN MING DRIVE, #02-17 SIN MING
 AUTOCITY
 Singapore 575722
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Mtg Cracked	1,996.10 F	*800.10 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	80.00 F	*80.00 FL
3	1		*REAR BUMPER INNER GARNISH	Serviceable	288.10 F	*- FL
4	1		*REAR BUMPER LOWER GARNISH	Mtg Cracked	298.10 F	*298.10 FL
5	1		*REAR BUMPER REINFORCEMENT	Repair	588.00 F	*- FL
6	1		*REAR END PANEL	Repair	710.50 F	*- FL
7	1		*REAR EXHAUST CHROME -LH	Serviceable	330.00 F	*- FL
8	1		*REAR EXHAUST CHROME -RH	Serviceable	330.00 F	*- FL
9	1		*REAR EXHAUST MUFFLER	Repair	2,033.00 F	*- FL
10	1		*REAR BUMPER SPONGE	Cracked	175.20 F	*98.00 FL
11	1		*REVERSE SENSOR CENTRE -LH	Serviceable	325.30 FS	*- FS
12	1		*REVERSE SENSOR CENTRE -RH	Serviceable	325.30 FS	*- FS
13	1		*REAR NUMBER PLATE	Bent	80.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,559.60	1,321.20
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	127.62
Total Parts (\$)	7,559.60	1,193.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	1,200.00	200.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	1,200.00	400.00
3	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL	New	200.00	0.00
4	COMPUTER DIAGNOSTIC RESET	New	480.00	0.00
5	TO CHECK WIRING FUNCTIONS	New	60.00	15.00
Gross Labour Cost (\$\$)			3,140.00	615.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >