



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 02/09/2021
TP Veh Reg No: SME4116T

Estimate No: ES2100081

Date: 08 Sep 2021

Policy No:

Veh Reg No: SFH1818M

Make/Model: INFINITI Q60 2.0T
COUPE

Chassis No: JN1GCAV37Z0480023

Engine No: 274AE125730A

Reg. Date: 28/08/2020

Not Authorized

Resurvey After Paint

*L1 Spmp @ 1450/pc
3 days*

Estimate Repair Cost to Vehicle No :SFH1818M

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REVERSE SENSOR CENTRE - LH	325.30	1 PC	<i>P_L</i> 325.30	X
2 REVERSE SENSOR CENTRE - RH	325.30	1 PC	<i>P_R</i> 325.30	X
3 REAR NUMBER PLATE	80.00	1 PC	<i>P_N</i> 80.00	<i>455m</i>
			730.60	730.60
Spare Parts				
4 REAR BUMPER	1,996.10	1 PC	<i>mjcm</i> 1,996.10	<i>2</i>
5 REAR BUMPER CLIPS	80.00	1 SET	<i>m</i> 80.00	<i>2</i>
6 REAR BUMPER INNER GARNISH	288.10	1 PC	<i>su</i> 288.10	X
7 REAR BUMPER LOWER GARNISH	298.10	1 PC	<i>mjcm</i> 298.10	<i>2</i>
8 REAR BUMPER REINFORCEMENT	588.00	1 PC	<i>n</i> 588.00	X
9 REAR END PANEL	710.50	1 PC	<i>n</i> 710.50	X
10 REAR EXHAUST CHROME - LH	330.00	1 PC	<i>P_L</i> 330.00	X
11 REAR EXHAUST CHROME - RH	330.00	1 PC	<i>P_R</i> 330.00	X
12 REAR EXHAUST MUFFLER	2,033.00	1 PC	<i>n</i> 2,033.00	X
<i>13 Rear bumper Sponge \$175.30 can</i>		<i>98.00</i>	6,653.80	6,653.80
Labour				
13 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,200.00	1 JOB	1,200.00	<i>200</i>
14 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,200.00	1 JOB	1,200.00	<i>400</i>
15 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	<i>m</i> 200.00	X
16 COMPUTER DIAGNOSTIC RESET.	480.00	1 JOB	480.00	X
17 TO CHECK WIRING FUNCTIONS.	60.00	1 JOB	60.00	<i>15</i>
			3,140.00	3,140.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 02/09/2021
TP Veh Reg No: SME4116T

Estimate No: ES2100081
Date: 08 Sep 2021
Policy No:
Veh Reg No: SFH1818M
Make/Model: INFINITI Q60 2.0T
COUPE
Chassis No: JN1GCAV37Z0480023
Engine No: 274AE125730A
Reg. Date: 28/08/2020

Estimate Repair Cost to Vehicle No :SFH1818M

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 10,524.40
			Add GST @ 7%	516.91
			Total Amount Payable	SS 11,041.31

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND FORTY ONE AND CENTS THIRTY ONE ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE