



Accident Reference & Bus No: E/3829/2021 - SBS8342L with SMV8670T

Activated date: Monday, 6 September 2021 3:31 PM

Activated by: Yao Tianhao <yaoth@sbstransit.com.sg>

Estimate for

Stock Code	Description	Quantity	Total Material cost(S\$)
30122044	SIDE PANEL.O/S&N/S.ALUM <i>bt</i>	1	\$79.00
30122012	RADIATOR GRILL JL~KL;SIDE PANEL ASSY <i>bt</i>	1	\$612.00
30311401	BUMPER.REAR.F/G <i>one</i>	1	\$248.00
(MO Number : BN2108003622 )		Sub Total S\$:	939.00

- Parts cost: \$ 939
- Contractor Labour cost: \$ 800 + GST
- Workshop Labour cost: NOT REQUIRED BY SURVEYOR *Xan*
- Advertisement Cost: \$ 0
- Repair period: 3 day

- Tow Cost: \$ 0 *Xan*
- Loss of use: NOT REQUIRED BY SURVEYOR *Xan* 1815.90
- Overheads: \$ 576.90 *Xan*

*Tanfiki 97495749*  
*9/9/21 @ 3pm*  
*Resurvey before paint*  
*tanfiki@lkkauto.com*  
*• 3 days*  
*\* ORR not final with w/s*

**LKK Auto Consultants** hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: