

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

9-Sep-21

ESTIMATE REPAIR BILL FOR NISSAN TEANA REGN NO: SLN 6160 R

1 pc Front o/s fender
1 pc Front o/s rim

\$ 280.00 / Dec
\$ 950.00 / Scr
\$ 1,230.00
\$ 369.00
\$ 861.00

Less 30%

S/N

1 set Front bumper clips
1 set o/s rocker panel garnish clips

\$ 48.00 / nec
\$ 38.00 / ~~part~~ X
NA

Sundry

\$ 50.00 X SUV

To check front o/s wheel alignment

\$ 80.00 60

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, front o/s door, o/s rocker panel garnish, etc

\$ 1,200.00 ~~450~~ 500

To putty and spray painting on front bumper, front o/s fender, front o/s door, o/s rocker panel garnish

\$ 1,000.00 600

To apply rustproofing on the repaired and replaced panels.

\$ 120.00
\$ 3,397.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

thuvan LKH
82235769
thuvan@Lkhauto.com
9/9/21 1430
3 days w p

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date: