



ID:AA5

TAX INVOICE

GST Reg No:M90364005A

Trans Eurokars Mazda (CPW)

CODE: C0006 INS-CHI

CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LTD

ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL NO: 6389 6111

MODEL: MAZDA6 2.5L WAGON BLACK LS

CHASSIS NO: JM6GL103100109929

ENGINE NO: PY20873071

DESCRIPTION: Body repair

PAGE NO : 1

INVOICE NO: I 30024731

DEPT/POS ID: I / 12

DATE IN 16/09/2021

DATE PRINTED: 22/12/2021

JOB NO : 41578

CSO/OP CODE: Yvonne Chew

REGN NO : SFY9655Z

REGN DATE : 02/06/2017

MILEAGE : 52459

REQUISITION NO: JESS

NOTES	CHINA TAI TP CLAIM	0.00
SUB	REPLACE REAR BUMPER, RHR DOOR, RH SIDE SILL. REPAIR RHF DOOR, RHR FENDER AND AREAS AFFECTED BY THE ACCIDENT.	2,640.00
SUB	SPRAY REAR BUMPER, RHR DOOR AND RH ROCKER PANEL. 168459	1,890.00
MZ-BR-SE	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREA	180.00
MZ-BR-DO	TO TRANSFER THE DOOR MECHANISM.	330.00
MZ-BR-WH	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	560.00
MZ-BR-WH	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	80.00
MZ-BR-RE	TO TRANSFER REVERSE SENSORS.	330.00
MZ-BR-EL	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONIN	150.00
MZ-BR-RE	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	190.00
MZ-BR-CA	TO CARRY-OUT BODY CAVITY PRESERVATION.	160.00
MZ-BR-SU	Sundries	20.00
SUB	RESPRAY RHF DOOR, RHR FENDER.	1,260.00



ID:AA5

TAX INVOICE

GST Reg No:M90364005A

Trans Eurokars Mazda (CFW)

CODE: C0006 INS-CHI
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LTD
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL NO: 6389 6111
MODEL: MAZDA6 2.5L WAGON BLACK LS
CHASSIS NO: JM6GL103100109929
ENGINE NO: PY20873071
DESCRIPTION: Body repair

PAGE NO : 2
INVOICE NO: I 30024731
DEPT/POS ID: I / 12
DATE IN: 16/09/2021
DATE PRINTED: 22/12/2021
JOB NO: 41578
CSO/OP CODE: Yvonne Chew
REGN NO: SFY96552
REGN DATE: 02/06/2017
MILEAGE: 52459
REQUISITION NO: JESS

BEM4-56-061	COVER, HOLE GL/BN	2.0	11.40	22.80
GHP9-50-4P2A	GUARD STONE RHR GJ	1.0	17.40	17.40
GHY0-72-02XD	RHR DOOR GJ/GL	1.0	1111.60	1111.60
GRN1-50-8V4A	STRIPE NO.4 (R), BODY	1.0	23.10	23.10
GRV1-50-8V2A	STRIPE NO.2 (R), BODY	1.0	15.50	15.50
GHP9-72-762	FASTENER (R), WEATHERS	1.0	12.30	12.30
BC1D-58-762	FASTENER	10.0	3.40	34.00
BF67-51-261	GROMMET	1.0	2.40	2.40
GS1D-58-315A	CLIP	1.0	2.40	2.40
GD7A-50-EA1	FASTENER	1.0	3.20	3.20
GJ6A-58-975	GROMMET, SCREW	10.0	3.00	30.00
9991-00-503	GROMMET, SCREW	1.0	3.80	3.80
GJ6A-68-AB1	FASTENER	9.0	7.20	64.80
GJN8-50-M50A	GARNISH (R)	1.0	95.00	95.00
GJR9-50-M30B	MGJR9-50-M30C/GARNIS	1.0	102.90	102.90
KD53-50-M38	CLIP, GARNISH	6.0	12.30	73.80
GHP9-50-480	GUARD (R), STONE-REAR	1.0	177.60	177.60
BP4L-51-SJ3	CLIP	10.0	10.00	100.00



ID:AA5

TAX INVOICE

GST Reg No:M90364005A

Trans Eurokars Mazda (CPW)

CODE: C0006 INS-CHI
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LTD
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL NO: 6389 6111
MODEL: MAZDA6 2.5L WAGON BLACK LS
CHASSIS NO: JM6GL103100109929
ENGINE NO: PY20873071
DESCRIPTION: Body repair

PAGE NO : 3
INVOICE NO: I 30024731
DEPT/POS ID: I / 12
DATE IN: 16/09/2021
DATE PRINTED: 22/12/2021
JOB NO : 41578
CSO/OP CODE: Yvonne Chew
REGN NO : SFY9655Z
REGN DATE : 02/06/2017
MILEAGE : 52459
REQUISITION NO: JESS

G18K-51-SJ3	CLIP	2.0	6.50	13.00
GHR2-50-221ABE	REAR BUMPER GJ/GL	1.0	1230.30	1230.30
GS1D-50-EM1A	TAPE, PROTECTOR	2.0	8.60	17.20
GJE8-51-153	GASKET(R), RR.COMB GJ	1.0	27.70	27.70
GJE8-51-163	GASKET(L), RR.COMB GJ	1.0	27.70	27.70
9965-20-7590	WHEEL, DISC 19X7.5 GL	1.0	1497.80	1497.80
9963-60-4140	VALVE, AIR TYRE S/ACT	1.0	6.70	6.70
GHP9-50-340D	SHIELD(R), SPLASH-R.B	1.0	53.90	53.90
B45A-56-146A	FASTENER	6.0	3.00	18.00
GHY6-70-271	PANEL(R), S	1.0	1071.00	1071.00

Parts 5,855.90
Surcharge 0.00
Labour 7,780.00
Menus 0.00

Sub Total 13,635.90
G.S.T. 7% 954.51
Total 14,590.41
Paid 0.00
Amount Due 14,590.41