



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS SERVICES

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN.: MOTOR CLAIMS FAX:		NAME: ADDRESS: TEL:		WIP: 41578 EXCESS: DATE: 7-Sep-21			
VEH NO:	SFY9655Z	DATE IN:		CONTACT PERSON:	JESS		
CHASSIS NO:	JM6GL103100109929	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM		
MODEL:	MAZDA 6	DATE REG.:	2-Jun-17	POLICY NO.:			
NATURE OF WORKS							
Parts Description							
NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1	ROCKER PANEL RH / <i>MC</i>	1			MGHY6-70-271		\$ 1,071.00
2	COVER,HOLE / <i>MC</i>	2			MBBM4-56-061		\$ 22.80
3	GUARD STONE RH / <i>MC</i>	1			MGHP9-50-4P2A		\$ 17.40
4	REAR DOOR RH / <i>MC</i>	1			MGHY0-72-02XD		\$ 1,111.60
5	STRIPE NO.4(R),BODY SIDE / <i>MC</i>	1			MGRN1-50-8V4A		\$ 23.10
6	STRIPE NO.2(R),BODY SIDE / <i>MC</i>	1			MGRV1-50-8V2A		\$ 15.50
7	MOULD BELTLINE REAR DOOR RH / <i>MC</i>	1	<i>x nn</i>		MGHP9-50-660D		\$ 72.20
8	WEATHERSTRIP REAR DOOR RH / <i>X nh</i>	1			MGHP9-72-760C		\$ 143.70
9	FASTENER(R),WEATHERS / <i>MC</i>	1			MGHP9-72-762		\$ 12.30
10	FASTENER / <i>MC</i>	10			MBC1D-58-762		\$ 34.00
11	CHECKER,DOOR RR RH / <i>X nh</i>	1			MGHP9-72-270A		\$ 65.70
12	GROMMET / <i>MC</i>	1			MBF67-51-261		\$ 2.40
13	CLIP / <i>MC</i>	1			MG51D-58-315A		\$ 2.40
14	FASTENER / <i>MC</i>	1			MGD7A-50-EA1		\$ 3.20
15	GROMMET,SCREW / <i>MC</i>	10			MGJ6A-58-975		\$ 30.00
16	GROMMET,SCREW / <i>MC</i>	1			M9991-00-503		\$ 3.80
17	FASTENER / <i>MC</i>	9			MGJ6A-68-AB1		\$ 64.80
18	GARNISH REAR DOOR RH / <i>MC (Black)</i>	1			MGJN8-50-M50A		\$ 95.00
19	GARNISH(R),REAR DOOR / <i>MC (Black)</i>	1			MGJR9-50-M30B		\$ 102.90
20	CLIP,GARNISH / <i>MC</i>	6			MKD53-50-M38		\$ 73.80
21	BRACKET SIDE STEP RH / <i>MC</i>	1			MGHP9-50-480		\$ 177.60
22	CLIP / <i>MC</i>	10			MBP4L-51-SJ3		\$ 100.00
23	CLIP / <i>MC</i>	2			MG18K-51-SJ3		\$ 13.00
24	REAR BUMPER / <i>CR4</i>	1			MGHR2-50-221ABB		\$ 1,230.30
25	TAPE,PROTECTOR / <i>MC</i>	2			MG51D-50-EM1A		\$ 17.20
26	SPLASH SHIELD RH REAR / <i>CR4</i>	1			MGHP9-50-340D		\$ 53.90
27	FASTENER / <i>MC</i>	6			MB45A-56-146A		\$ 18.00
28	GASKET TAIL LAMP RH / <i>MC</i>	1			MGJE8-51-153		\$ 27.70
29	GASKET TAIL LAMP LH / <i>MC</i>	1			MGJE8-51-163		\$ 27.70
30	REAR DAMPER RH / <i>MC</i>	1	<i>x nn</i>		MGML8-28-910E		\$ 322.00

31	ARM UPPER REAR RH	x nn	1		MGBFN-28-C10	\$ 241.10
32	TARAILING ARM REAR RH	x nn	1		MG46E-28-200D	\$ 258.50
33	LATERAL ARM REAR RH	x nn	1		MGHP9-28-500	\$ 138.00
34	KNUCKLE REAR RH	x nn	1		MGHR1-26-11XB	\$ 631.10
35	HUB WHEEL BEARING REAR RH	x nn	1		MKD31-26-15XB	\$ 480.40
36	WHEEL,DISC 19X7.5	✓ (wt)	1		M9965-20-7590	\$ 1,497.80
37	VALVE,AIR TYRE	✓ n/c	1		M9963-60-4140	\$ 6.70

		TOTAL PARTS	\$ 8,208.60
		TOTAL PARTS COST	\$ 8,208.60

SUPPLEMENTARY

SOFT ELEMENT PART							
NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1							
2							
3							
					TOTAL PARTS		\$ -
					TOTAL PARTS COST		\$ -

Labour Description

			REVISED	PRICES
1		TO REPLACE REAR BUMPER, REAR DOOR RH AND ROCKER PANEL RH. 660 x 4	2640	\$ 3,960.00
2		TO RESPRAY REAR BUMPER, REAR DOOR RH AND ROCKER PANEL RH. 630 x 34	1890	\$ 2,520.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	NETT	\$ 180.00
4	MZ-BR-DOORM	TO TRANSFER THE DOOR MECHANISM.		\$ 330.00
5	MZ-BR-AXNSU	TO REPLACE AXLE AND SUSPENSION MECHANISM.	?	\$ 630.00
6	MZ-BR-WHEAL	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT	\$ 560.00
7	MZ-BR-WHEBA	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING. 80	NETT	\$ 120.00
8	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	330	\$ 660.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 300.00

11	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION (INCLUDING NEW PARTS AND CAOUTCHOU)	160	\$ 150.00 \$160
12	MZ-BR-SUNDR	SUNDRIES.	20	\$ 50.00
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.			TOTAL LABOUR	\$ - \$ 9,710.00
			TOTAL PARTS	\$ - \$ 8,208.60
			TOTAL	\$ - #####
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ - \$ 17,918.60
			GST 7%	\$ - \$ 1,254.30
			GRAND TOTAL	\$ - #####
SUPPLEMENTARY LABOUR DESCRIPTION				
			REVISED	PRICES
1		#N/A		
2		#N/A		
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.			TOTAL LABOUR	\$ - \$ -
			TOTAL PARTS	\$ - \$ -
			TOTAL	\$ - \$ -
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ - \$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

Steve (LKK) Mr AL
 9/9/21, 3pm P/P
 My B/L by
 9 ~~7-8~~ days

TRANS EUROKARS PTE LTD

 Authorised Signature

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: