



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZE COST OF REPAIRS



CHINA TAIPING INSURANCE P/L			NAME :			WIP : 41578		
3 ANSON ROAD			ADDRESS :			EXCESS :		
#16-00 SPRINGLEAF TOWER						DATE: 7-Sep-21		
SINGAPORE 079909								
ATTN. : MOTOR CLAIMS			TEL :					
FAX :								
VEH NO :	SFY9655Z	DATE IN :		CONTACT PERSON : JESS				
CHASSIS NO :	JM6GL103100109929	MILEAGE :		TYPE OF CLAIM : THIRD PARTY CLAIM				
MODEL :	MAZDA 6	DATE REG.	2-Jun-17	POLICY NO. :				
NATURE OF WORKS								
Parts Description								
NO	DESCRIPTION	QTY	UNIT PRICE	DISC %	1st	Supp	REVISED	PRICES
1	ROCKER PANEL RH	1	1,071.00	-	✓	MGHY6-70-271	1,071.00	1,071.00
2	COVER,HOLE	2	11.40	-	✓	MBBM4-56-061	22.80	22.80
3	GUARD STONE RH	1	17.40	-	✓	MGHP9-50-4P2A	17.40	17.40
4	REAR DOOR RH	1	1,111.60	-	✓	MGHY0-72-02XD	1,111.60	1,111.60
5	STRIPE NO.4(R),BODY SIDE	1	23.10	-	✓	MGRN1-50-8V4A	23.10	23.10
6	STRIPE NO.2(R),BODY SIDE	1	15.50	-	✓	MGRV1-50-8V2A	15.50	15.50
7	MOULD BELTLINE REAR DOOR RH	1	72.20	-		MGHP9-50-660D		72.20
8	WEATHERSTRIP REAR DOOR RH	1	143.70	-		MGHP9-72-760C		143.70
9	FASTENER(R),WEATHERS	1	12.30	-	✓	MGHP9-72-762	12.30	12.30
10	FASTENER	10	3.40	-	✓	MBC1D-58-762	34.00	34.00
11	CHECKER,DOOR RR RH	1	65.70	-		MGHP9-72-270A		65.70
12	GROMMET	1	2.40	-	✓	MBF67-51-261	2.40	2.40
13	CLIP	1	2.40	-	✓	MGS1D-58-315A	2.40	2.40
14	FASTENER	1	3.20	-	✓	MGD7A-50-EA1	3.20	3.20
15	GROMMET,SCREW	10	3.00	-	✓	MGJ6A-58-975	30.00	30.00
16	GROMMET,SCREW	1	3.80	-	✓	M9991-00-503	3.80	3.80
17	FASTENER	9	7.20	-	✓	MGJ6A-68-AB1	64.80	64.80
18	GARNISH REAR DOOR RH	1	95.00	-	✓	MGJN8-50-M50A	95.00	95.00
19	GARNISH(R),REAR DOOR	1	102.90	-	✓	MGJR9-50-M30B	102.90	102.90
20	CLIP,GARNISH	6	12.30	-	✓	MKD53-50-M38	73.80	73.80
21	BRACKET SIDE STEP RH	1	177.60	-	✓	MGHP9-50-480	177.60	177.60
22	CLIP	10	10.00	-	✓	MBP4L-51-SJ3	100.00	100.00
23	CLIP	2	6.50	-	✓	MG18K-51-SJ3	13.00	13.00
24	REAR BUMPER	1	1,230.30	-	✓	MGHR2-50-221ABB	1,230.30	1,230.30
25	TAPE,PROTECTOR	2	8.60	-	✓	MGS1D-50-EM1A	17.20	17.20
26	SPLASH SHIELD RH REAR	1	53.90	-	✓	MGHP9-50-340D	53.90	53.90
27	FASTENER	6	3.00	-	✓	MB45A-56-146A	18.00	18.00
28	GASKET TAIL LAMP RH	1	27.70	-	✓	MGJE8-51-153	27.70	27.70
29	GASKET TAIL LAMP LH	1	27.70	-	✓	MGJE8-51-163	27.70	27.70
30	REAR DAMPER RH	1	322.00	-		MGML8-28-910E		322.00
31	ARM UPPER REAR RH	1	241.10	-		MGBFN-28-C10		241.10
32	TARAILING ARM REAR RH	1	258.50	-		MG46E-28-200D		258.50
33	LATERAL ARM REAR RH	1	138.00	-		MGHP9-28-500		138.00
34	KNUCKLE REAR RH	1	631.10	-		MGHR1-26-11XB		631.10
35	HUB WHEEL BEARING REAR RH	1	480.40	-		MKD31-26-15XB		480.40
36	WHEEL,DISC 19X7.5	1	1,497.80	-	✓	M9965-20-7590	1,497.80	1,497.80
37	VALVE,AIR TYRE	1	6.70	-	✓	M9963-60-4140	6.70	6.70

SUPPLEMENTARY									
NO	DESCRIPTION	QTY	UNIT PRICE	% DISC	1st	Supp		REVISED	PRICES
1									
2									
3									
							TOTAL PARTS	5,855.90	-
								-	
							TOTAL PARTS COST	5,855.90	-
Labour Description									
								REVISED	PRICES
1		REPLACE REAR BUMPER, RHR DOOR, RH SIDE SILL. REPAIR RHF DOOR, RHR FENDER AND AREAS AFFECTED BY THE ACCIDENT. 168459						2,640.00	3,960.00
2		SPRAY REAR BUMPER, RHR DOOR AND RH ROCKER PANEL.						1,890.00	2,520.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING						180.00	180.00
4	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.						330.00	330.00
5	MZ-BR-AXNSUP	TO REPLACE AXLE AND SUSPENSION MECHANISM.						-	630.00
6	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.						560.00	560.00
7	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.						80.00	120.00
8	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.						330.00	660.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.						150.00	250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.						180.00	300.00
11	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU)						160.00	150.00
12	MZ-BR-SUNDRI	SUNDRIES.						20.00	50.00
SUPPLEMENTARY LABOUR DESCRIPTION									
								REVISED	PRICES
1		SPRAY RHR FENDER, RHF DOOR.						1,260.00	1,260.00
2		#N/A							
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES							TOTAL LABOUR	7,780.00	1,260.00
							TOTAL PARTS	5,855.90	-
							TOTAL	13,635.90	1,260.00
							LESS EXCESS	-	-
							TOTAL AFTER EXCESS	13,635.90	
							GST 7%	954.51	-
							GRAND TOTAL	14,590.41	-

SURVEYED BY : STEVE OF LKK ON 9-9-2021

REPAIR DAYS : 9 DAYS

TRANS EUROKARS PTE LTD

Authorised Signature