

ASS. REC. BY: *Marcus*

REF:

CS/CT121009480/Ugc

ASSIGNMENT

From:

Date:

Veh No:

SLC2927E

Yr Regn:

09/05/16

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLC2927E

Make:

Honda Jazz

C.C.

1318

at Workshop m/s

PA ubi

Colour:

Red

A/C:

Insured / Std / NI / NA

of

Sp. Reading

125/50

T/Radio:

Insured / Std / NI / NA

Insured:

SM11283X

Eng/No:

Policy No.

C/No:

JHMGK38506X 236450

Claims No.

SNM21D205061/C02

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:


F:

175/65 R15

R:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$46k.

Front

6

Rear

6

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

4

days

Res.:

Yes or No

D.O.A.

5/9/21

D.O.I.

27/9/21

Lump Sum:

20

%

3 Val.:

Yes or No

Survey held at

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 629185

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2 vehicle amendment only 2 vehicle rear portion
 1 vehicle left hand plate dent.

7/10/21

rep \$2550 confirmed with Roy (Red \$2238.84, 47%)

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

4

1) 07/10 Typist

☐

Final Report

Resurvey No. of Trip:

1

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

Site Insp (\$)

) __ \$ + RS __ \$

☐

Interview (\$)

) Photos

☐

Tech. Invs (\$)

) Others

☐

Weekend (\$)

)

Report Format: MER-TP

Lump Sum ~~4.4k~~ (\$ 2550)

TOTAL

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

*Not Allowed
back
27/9/21
2/5 \$2550
the price is 4 days.*

M/S : PETRINA LO LENG

BLK 18 TELOK BLANGAH CRESCENT #05-162
SINGAPORE 090018

Estimate No: EST1507279
Date: 06 Sep 2021
Policy No: 7210039415
Veh Reg No: SLC2927E
Make/Model: HONDA JAZZ 1.3 CVT
ABS D/AIRBAG 2WD
Chassis No: JHMGK3850GX236450
Engine No: L13B11010285
Reg. Date: 09/05/2016

ATTN: CHINA

Your Ref No: TP 0921-6484
Claim Type: Third Party
Accident Date: 05/09/2021
TP Veh Reg No: SMM 1283 X

Estimate Repair Cost to Vehicle No :SLC2927E

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BOOT	851.8000	1 PCS	851.80	—
2 REAR BOOT GLASS MOULDING	118.6000	1 PCSET	118.60	—
3 REAR BOOT RUBBER	92.3000	1 PCS	92.30	—
4 REAR BOOT TOP LOCK	183.5000	1 PCS	183.50	—
5 REAR BOOT BOTTOM LOCK	25.7000	1 PC	25.70	X
6 REAR BOOT JAZZ WORDING	20.9000	1 PCS	20.90	—
7 REAR BUMPER	529.0000	1 PC	529.00	—
8 REAR BUMPER CLIPS	3.8000	10 PC	38.00	—
9 REAR BUMPER SIDE HOLDER - LH	14.7000	1 PCS	14.70	—
10 REAR BUMPER SIDE HOLDER - RH	14.7000	1 PCS	14.70	—
11 REAR BUMPER LOWER GARNISH, BLACK	14.6000	1 PC	14.60	X
12 REAR PANEL	390.2000	1 PCS	390.20	X
13 REAR PANEL TOP GARNISH	60.8000	1 PCS	60.80	X
			2,354.80	
	Less 20%		470.96	1,883.84
Special Net				
14 REAR NUMBER PLATE WITH CASING	35.0000	1 PC	35.00	X
15 SEALANT <i>Rear wind screen</i>	20.0000	2 PC	40.00	✓
16 SPONGE TAPE <i>Rear wind screen</i>	20.0000	1 PCS	20.00	✓
			95.00	95.00
Labour				
17 TO KNOCK OUT DENTS,CUT/WELD, REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	1,000.000	1 JOB	1,000.00	600
18 TO RESPRAY PAINT ON ACCIDENT PORTIONS (PEARL)	1,200.000	1 JOB	1,200.00	800
19 TO CHECK WIRING	50.0000	1 JOB	50.00	20
20 TO TUFF-KOTE	120.0000	1 JOB	120.00	30
21 TO REMOVE, REFIX REAR WINDSCREEN	120.0000	1 JOB	120.00	✓
22 TO REMOVE, REFIX REAR GARNISH,CARPET, CUSHION & RELATED PARTS	150.0000	1 JOB	150.00	80
23 TO RESET CHECK LIGHT	70.0000	1 JOB	70.00	X
24 TO TRANSFER REAR BUMPER SENSOR	100.0000	1 JOB	100.00	50
			2,810.00	2,810.00

*P-179050
232
1432.72
2182.72*

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : PETRINA LO LENG
BLK 18 TELOK BLANGAH CRESCENT #05-162
SINGAPORE 090018

ATTN: CHINA

Your Ref No: TP 0921-6484
Claim Type: Third Party
Accident Date: 05/09/2021
TP Veh Reg No: SMM 1283 X

Estimate No: EST1507279
Date: 06 Sep 2021
Policy No: 7210039415
Veh Reg No: SLC2927E
Make/Model: HONDA JAZZ 1.3 CVT
ABS D/AIRBAG 2WD
Chassis No: JHMGK3850GX236450
Engine No: L13B11010285
Reg. Date: 09/05/2016

Estimate Repair Cost to Vehicle No :SLC2927E

Description	U/Price	Quantity	Price	Amount
			SS	SS
			Total	SS 4,788.84
			Add GST @ 7%	335.22
			Total Amount Payable	SS 5,124.06

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND ONE HUNDRED TWENTY FOUR AND CENTS SIX ONLY

For Progressive Car Care Pte Ltd

LKIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AUTHORISED SIGNATURE