

TK MOTOR WORKSHOP
1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL : 96273323 FAX 68442641
CO.REG NO: 53049097-L

TP Direct Asia (Independent)

Veron

TAN JUN WEN

DATE : 28/09/2021

BLK 308C, PUNGGOL WALK, #16-344
SINGAPORE 823304

KNAFZ411MH5666355

ACCIDENT DATE : 03/09/2021

MODEL : KIA FORTE K3 1.6 A SEDAN

ESTIMATE COST OF REPAIR BILL TO KIA CAR NO : SLJ8589X

1 PC REAR BOOTLID	Repair	S\$702.00	X
4 PC REAR BOOTLID EMBLEM	New	184.00	✓
1 PC REAR BOOTLID LOCK	Damaged	246.00	✓
1 PC REAR BOOTLID RUBBER	cut	104.00	✓
1 PC REAR BUMPER	Deformed	756.00	✓
8 PC REAR BUMPER CLIPS	new	32.00	✓
2 PC REAR BUMPER SIDE RETAINER	new	92.00	✓
5 PC REAR BUMPER HOLDER BRACKET	Damaged	75.00	✓
1 PC REAR BUMPER LOWER GARNISH	Deformed	296.00	✓
2 PC REAR BUMPER REFLECTOR	RH cut	76.00	38. ✓
2 PC REAR BUMPER REVERSE SENSOR	Damaged	310.00	✓
1 PC REAR BUMPER REINFORCEMENT BEAM	cracked	412.00	344 ✓
1 PC REAR END PANEL	Repair	512.00	X
1 PC REAR END PANEL GARNISH	Deformed	129.00	✓
1 PC REAR SPAREWHEEL TOP COVER GARNISH	torn	371.00	178. ✓
1 PC REAR EXHAUST PIPE CHROME COVER	cut	180.00	✓

2965

2668.50

TK MOTOR WORKSHOP
1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL : 96273323 FAX 68442641
CO.REG NO: 53049097-L

ESTIMATE COAST OF REPAIR BILL TO KIA CAR NO : SLJ8589X

LABOUR CHARGE

WIRING

~~S\$50.00~~ 30.

TO SPRAY PAINTING

~~650.00~~ 600.

TO REMOVE AND REFIX REAR EXHAUST PIPE & CHROME COVER

80.00 X

TO REMOVE AND REFIX REAR INTERIOR UPHOLSTERY

~~80.00~~ 50

TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED

PANEL FOR RUST PROTECTION

~~80.00~~ 50

TO MEASURE, DRILL THE REPLACED REAR BUMPER, POSITION & REINSTALL

REVERSE SENSOR, CONTROL UNIT, CAMERA ASSY & TEST FOR FUNCTIONING

~~80.00~~ 50. 1380

LABOUR CHARGE FOR PANEL BEATING KIA & WELDING, REMOVING ALL DAMAGE

~~650.00~~ 600.

PARTS AND REPLACING OF THE NEW PARTS ETC.

TOTAL : S\$5815.00

6147.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4048.50

h/s: 3.2K.

04 Days

3.2K