



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SJH7050Z

Model: Toyota Allion

Damaged Area: (Rear Damaged)

Repairer Estimation Cost of Repair:

Supplementary may be included during the cost of repair:

TP China.

N2T2603025504

Veron.

Parts / Material:

1	Rear Bumper	Damaged	\$	1,490.50	968.40
2	Rear Bumper Side Retainer @ 65.00	LH Dented	\$	130.00	65
3	Rear Bumper Bracket @ 78.00	LH Dented	\$	156.00	78.
4	Rear Bumper Reflector @ 128.00	new	\$	256.00	x
5	Rear Bumper Corner Bracket @ SGD 25.00	new	\$	50.00	x
6	Rear Bumper Clips	new	\$	60.00	30.
7	Rear Bootlid Panel	Dented	\$	1,086.20	951.60
8	Rear Bootlid Inner Lock	Damaged	\$	395.40	225
9	Rear Bootlid Logo	new	\$	75.40	-
10	Rear Bootlid Emblem (Allion)	new	\$	72.80	-
11	Rear Bootlid Weather Strip	new	\$	286.70	x
12	Rear Bootlid Detector Sensor	new	\$	494.10	x
13	Rear Taillamps @ 586.40	LH cracked	\$	1,172.80	378.20
14	Rear End Panel	Dented	\$	598.70	-
15	Rear End Panel Top Garnish	Dented	\$	257.40	-
16	Rear End Panel Top Garnish Clips	new	\$	60.00	10.
17	Rear Spare Tyre Top Garnish	new	\$	298.40	x
18	Rear Spare Tyre Panel	new	\$	1,270.80	x
			Parts :	\$	8,211.20
			Less Parts 25% :	\$	2,052.80
			Total Parts :	\$	6,158.40

3710.50

less 25% : 2782.87

Special Net Items:

Rear End Panel Sealant	new		\$	80.00	60
Rear Spare Tyre Panel Sealant	new		\$	80.00	x
Rear Spare Tyre Panel Insulator		340	\$	250.00	+
Reverse Sensor Set (4-Eyes)	Damaged		\$	380.00	280.
Rear Number Plate W/Base Garnish	Not New		\$	55.00	x
Total S/N Parts :			\$	845.00	

340

Labour:

To Remove, Repair & Renew Rear Affected Accident Areas	\$	1,400.00	800
To Putty, Spray Paint on Affected Accident Areas	\$	1,400.00	800
To Check & Re-Connect all electrical wiring	\$	50.00	30

To Remove & Install Rear Bootlid Components Trim & Garnish
To Remove & Install Spare Tyre Compartment Trim, Garnish
To Drill, Re-Position Reverse Sensor & Align
To Conduct Water Leakage Test
To Rust Proof Affected Areas

\$ 150.00 80
\$ 150.00 60
\$ 150.00 50
\$ 150.00
\$ 200.00 80

1900

Total Labour : \$ 3,650.00

TOTAL PARTS : \$ 6,158.40
TOTAL SPECIAL NET ITEM : \$ 845.00
TOTAL LABOUR : \$ 3,650.00
TOTAL REPAIR COST : \$ 10,653.40

total: 5022-87
L/S: 4K.

DATE OF SURVEY / INSPECTED:
RECOMMENDED PART BY PART / LUMP SUM :
RECOMMENDED NUMBER OF DAYS :
SURVEY BY / SURVEYOR FIRM :
RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :
FINALISED AMOUNT :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: