



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SMT9725Z

Model : Honda Civic

Damaged Area: (Rear RH Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

TP ALG.

MRHFC S6SOLT000058

Xiao Tony

Parts / Material :

1	Rear Bumper	behind	\$	956.40	617.50
2	Rear Bumper Side Retainer RH	new	\$	112.40	28.60
3	Rear Bumper Side Bracket RH	new	\$	68.70	X
4	Rear Bumper Lower	new	\$	486.20	X
5	Rear Bumper Sensor @ SGD 275.60	new	\$	275.60	X
6	Rear Bumper Sensor Bracket Set	new	\$	97.30	X
7	Rear Bumper Clips	new	\$	60.00	30
8	Rear Fender RH	new	\$	1,086.20	X
9	Rear Fender Inner Shield RH	new	\$	295.80	X
10	Rear Fender Inner Shield Clips	new	\$	60.00	X
11	Rear Fender Air-Vent RH	new	\$	78.50	X
12	Rear Fender Quarter Glass W/Moulding	new	\$	986.70	X
13	Rear Door RH	new		Repair	X

Parts : \$ 4,563.80

Less Parts 20% : \$ 912.76

Total Parts : \$ 3,651.04

Special Net Items :

Rear Fender Sealant	new	\$	80.00	X
Rear Windscreen Glass Inner Seal	new	\$	118.50	X
Rear Windscreen Glass Sealant	new	\$	60.00	X
Rear Sport Rim RH	new	\$	950.00	X

Total S/N Parts : \$ 1,208.50

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas	\$	1,400.00	300
To Putty, Spray Paint on Affected Accident Areas	\$	1,200.00	400
To Check & Re-Connect all electrical wiring	\$	50.00	X
To Remove & Install Rear Windscreen Glass	\$	150.00	X
To Remove & Install Rear Spare Tyre Components, Trim & Garnish	\$	150.00	X
To Conduct All Wheel Alignment	\$	150.00	X
To Remove, Replace & Install Rear Tyre & Balance	\$	150.00	X
To Re-Position, Drill & Install Reverse Sensor	\$	150.00	50
To Conduct Water Leakage Test	\$	150.00	X
To Rust Proof Affected Areas	\$	200.00	30

Total Labour : \$ 3,750.00

TOTAL PARTS : \$ 3,651.04
TOTAL SPECIAL NET ITEM : \$ 1,208.50
TOTAL LABOUR : \$ 3,750.00
TOTAL REPAIR COST : \$ 8,609.54

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

total : 1320.88

L/S : 1050.

03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: