Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16 Singapore 079120 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur Date: 09 Sep 2021

Preliminary Advice

Vehicle No : SKC85J Accident Date : 03/09/2021 Policy No. Make : MERCEDES-BENZ C200 : 1900246338 Assignment Date : 09/09/2021 Excess : S\$0.00 Date of Inspection : 09/09/2021 Est. Duration of Repair : 5

Inspection At : HIAP LEK AUTOMOBILE TRADING

BLK 14 #01-19 SECTOR B, SIN MING INDUSTRIAL EST

SINGAPORE 575658

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,788.20
Revised Amount	:S\$	8,863.55
Check Items (Estimated)	:S\$	6,327.89
Total	:S\$	15,191.44

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 109,000.00 COE / PARF Rebate :S\$ 70,815.00

Salvage Value :S\$

Margin for Repair :S\$ 38,185.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	ylk
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Please note the the preliminary advice amount (Revised & Check items) stated are subject to part prices and labour cost.