

HIAP LEK AUTOMOBILE TRADING

160 SIN MING DRIVE

SIN MING AUTOCITY

#05-17

SINGAPORE 575658

TEL:64531743 FAX:62668605

Email: hiaplek@hotmail.com

Not Authorized
Person B4 print
5 day

ESTIMATE

TO: AIG AISIA PACIFIC INSURANCE PTE LTD

78 Shenton Way

#09-16 AIG BUIDLING

Singapore 079120

DATE:07/09/2021

POLICY #:1900246338-01

YOUR REF#: SKC 85J

RE: VEHICLE NO : SKC 85J MERCEDES C200

S \$

TO SUPPLY:

✓ ①	1PC	FRT BONNET	\$1198.40	Bu	2300.50	✓
✓ ②	1PC	FRT BONNET EMBLEM		na	42.80	✓
✓ ③	1PC	FRT BONNET INSULATOR		na	160.50	X
✓ ④	10PCS	FRT BONNET INSULATOR CLIPS @1.82		na	18.20	X
✓ ⑤	2PCS	FRT BONNET CATCH LH/RH @21.40		na	42.80	X
✓ ⑥	2PCS	FRT BONNET CATCH STOPPER LH/LH @19.26		na	38.52	X
✓ ⑦	1PC	FRT BONNET CENTER LOCK		na	39.57	X
✓ ⑧	2PCS	FRT BONNET LOCK LH/RH @38.52			77.04	?
✓ ⑨	2PCS	FRT BONNET LOCK SWITCH LH/RH @24.61			49.22	?
✓ ⑩	2PCS	FRT BONNET STOPPER LH/RH @5.35		na	10.37	X
✓ ⑪	2PCS	FRT BONNET SHOCK ABSORBER LH/RH @62.06		na	124.12	X
✓ ⑫	2PCS	FRT BONNET HINGE LH/RH @104.86		na	209.72	X
✓ ⑬	2PCS	FRT BONNET HINGE PINS LH/RH @109.14		na	218.28	X
✓ ⑭	1PC	FRT BUMPER		na/cm	813.20	✓
✓ ⑮	8PCS	FRT BUMPER CLIPS @2.14	\$17.1	na	17.12	✓
✓ ⑯	1PCS	FRT BUMPER TOP WEATHER STRIP		na	18.19	✓
✓ ⑰	4PCS	FRT BUMPER PARKING SENSOR @99.51			398.04	?
✓ ⑱	2PCS	FRT BUMPER LOWER GRILLE LH/RH @35.31		na	70.62	X
✓ ⑲	2PCS	FRT BUMPER LOWER GRILLE SENSOR LH/RH @29.96		na	59.92	X
✓ ⑳	1PC	FRT BUMPER LOWER GRILLE CENTER		na	72.76	X
✓ ㉑	2PCS	FRT BUMPER LOWER CHROME MOULDING LH/RH @94.16			188.32	?
✓ ㉒	1PCS	FRT BUMPER LOWER CHROME CENTER MOULDING	\$105.85		187.25	?
✓ ㉓	1PC	FRT BUMPER TOP FRAME CENTER	\$49.22		51.36	?
✓ ㉔	2PCS	FRT BUMPER SIDE BRACKET LH/RH @41.73	\$40.66		83.46	?
✓ ㉕	1PC	FRT RADIATOR GRILLE BASE		cm	77.04	✓
✓ ㉖	1PC	FRT RADIATOR GRILLE CENTER CHROME			117.70	?
✓ ㉗	2PCS	FRT RADIATOR GRILLE OUTER CHROME LH TOP @38.52		na	77.04	X
✓ ㉘	2PCS	FRT RADIATOR GRILLE OUTER CHROME RH BOTOM @48.15			96.30	?
✓ ㉙	1PC	FRT RADIDATOR MERCEDES EMBLEM CHROME			43.87	?
✓ ㉚	1PCS	FRT RADITOR GRILLE STAR		cm	74.90	✓
✓ ㉛	1PC	FRT RADIAITOR GRILLER INNER SHEILD			72.76	?
✓ ㉜	1PC	FRT BUMPER RE-INFORCEMENT		na	246.10	✓
✓ ㉝	1PC	FRT SUPPORT PANEL		na	395.90	✓
✓ ㉞	2PCS	FRT ANGLE BRACKET LH/RH @34.24			68.48	?
✓ ㉟	1PC	FRT STRUT			24.61	?
✓ ㊱	1PC	FRT BUMPER SPONGE CENTER			94.16	?
✓ ㊲	1PC	FRT BUMPER INSIDE PART CENTER			72.76	?
✓ ㊳	2PCS 1PC	FRT BUMPER INSIDE PARTS LH/RH @44.94	RH	\$44.94	89.88	?
✓ ㊴	1PC	FRT MOUNTING CONSOLE		\$160.50	139.10	?
✓ ㊵	1PC	FRT BUMPER TOP FRAME			51.36	?
✓ ㊶	24a 1PC	FRT Bumper Side Bracket RH @ \$47.08			\$47.08	
✓ ㊷	21a 1PC	FRT Bumper lower chrome LH @ \$98.84			\$98.84	
BALANCE BRING FORWARD					7033.84	

S \$

7033.84

BALANCE BROUGHT FORWARD

41	1PC	FRT FENDER LH	567.10	X
42	1PC	FRT FENDER RH	460.10	X
43	1PC	FRT FENDER INNER SHIELD INNER LH	71.69	X
44	1PC	FRT FENDER INNER SHIELD INNER RH	80.25	X
✓ 45	1PC	FRT FENDER INNER SHIELD OUTER LH RH	69.55	X
✓ 46	1PC	FRT FENDER INNER SHIELD OUTER RH	69.55	X
47	10PCS	FRT FENDER INNER SHIELD CLIPS @1.71	17.12	X
✓ 48	1PC	FRT HEAD LAMP LH	2407.50	?
✓ 49	1PC	FRT HEAD LAMP RH	2514.50	✓
✓ 50	2PC	FRT RADIATOR	567.10	?
✓ 51	1PC	FRT RADIATOR FAN ASSY \$ 995.10	1016.50	?
✓ 52	1PC	AIRCON CONDENSOR \$ 749	1102.10	?
✓ 53	1PC	FRT NUMBER PLATE BASE	80.25	✓
✓ 54	4PCS	COOLANT @8.03 \$11.24	\$33.71 32.12	?
			16089.27	
		COST PLUS 10%	1608.93	
			17698.20	

SPECIAL NET ITEM

NUMBER PLATE AND CASING

70.00

LABOUR CHARGES

1	CHECKING OF WIRING AND FOCUS HEADLAMPS.	200.00	201
2	TO REMOVE AND REPLACE FRONT DAMAGED PARTS, STRAIGHTEN, ALIGN FRONT AFFECTED AREAS, FLUSH COOLANT. STRAIGHTEN FRONT CHASIS MEMBER.	1800.00	600
3	TO REMOVE AND REFIT FRONT AIRCON GASES, CHECK FAN MOTOR WIRING	120.00	100
4	TO DO RESETTING FOR BUMPER SENORS AND AFFECTED AREA AND CHECK WIRING.	200.00	60
5	TO PUTTY AND SPRAY PAINTING ON AFFECTED PORTIONS.	1500.00	800
6	TO RUST PROOF AFFECTED AREAS	200.00	X

TOTAL

21788.20

*REMARK: SUPPLEMENTARY PARTS EXPECTED
ESTIMATE PREPARE BY MR ONG, HP:96601347

協力汽車貿易
HIAP LEK AUTOMOBILE TRADING

Qing

HIAP LEK AUTOMOBILE TRADING

160 SIN MING DRIVE

SIN MING AUTOCITY

#05-17

SINGAPORE 575658

TEL:64531743 FAX:62668605

Email: hiaplek@hotmail.com

SUPPLEMENTARY

TO: AIG AISA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#09-16 AIG BUILDING
Singapore 079120

DATE:14/09/2021

POLICY #:1900246338-01

YOUR REF#: SKC 85J

RE: VEHICLE NO : SKC 85J MERCEDES C200

S \$

TO SUPPLY:

✓ ①	1PC	FRT RADIATOR LOWER PRESURE		R ₁	492.20	✓
✓ ②	1PC	FRT RADIATOR SPARE TANK FRONT PIPE	\$50.29	CM	51.36	✓
✓ ③	1PC	FRT BUMPER RADAR SENSOR BOX		CM	620.60	✓
4	2PCS	FRT HEAD LAMP BURLAS CONTROL LED LH/RH @732.95		Sm	1465.90	X
5	2PCS	FRT HEAD LAMP BARLAS CONTROL RH/LH @609.90		Sm	1219.80	X
					3849.86	
COST PLUS 10%					384.99	

TOTAL

4234.85

SUPPLEMENTARY PREPARED BY MR ONG, HP:96601347

協力汽車貿易
HIAP LEK AUTOMOBILE TRADING

Ory