

HIAP LEK AUTOMOBILE TRADING

160 SIN MING DRIVE
SIN MING AUTOCITY
#05-17
SINGAPORE 575658
TEL:64531743 FAX:62668605
Email: hiaplek@hotmail.com

Not Authorized
Resony B4 point

814640.53 5 days
B4 excess

TO: AIG AISIA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#09-16 AIG BUIDLING
Singapore 079120

ESTIMATE

DATE:07/09/2021
POLICY #:1900246338-01
YOUR REF#: SKC 85J

RE: VEHICLE NO : SKC 85J MERCEDES C200

S \$

TO SUPPLY:

- 1 1PC FRT BONNET
- 2 1PC FRT BONNET EMBLEM
- 3 1PC FRT BONNET INSULATOR
- 4 10PCS FRT BONNET INSULATOR CLIPS @1.82
- 5 2PCS FRT BONNET CATCH LH/RH @ 21.40
- 6 2PCS FRT BONNET CATCH STOPPER LH/LH @19.26
- 7 1PC FRT BONNET CENTER LOCK
- 8 2PCS FRT BONNET LOCK LH/RH @38.52
- 9 2PCS FRT BONNET LOCK SWITCH LH/RH @24.61
- 10 2PCS FRT BONNET STOPPER LH/RH @5.35
- 11 2 PCS FRT BONNET SHOCK ABSORBER LH/RH @62.06
- 12 2PCS FRT BONNET HINGE LH/RH @104.86
- 13 2PCS FRT BONNET HINGE PINS LH/RH @109.14
- 14 1PC FRT BUMPER
- 15 8PCS FRT BUMPER CLIPS @2.14
- 16 1PCS FRT BUMPER TOP WEATHER STRIP
- 17 4PCS FRT BUMPER PARKING SENSOR @99.51
- 18 2PCS FRT BUMPER LOWER GRILLE LH/RH @35.31
- 19 2PCS FRT BUMPER LOWER GRILLE SENSOR LH/RH @29.96
- 20 1PC FRT BUMPER LOWER GRILLE CENTER
- 21 2PCS FRT BUMPER LOWER CHROME MOULDING LH/RH @94.16
- 22 1PCS FRT BUMPER LOWER CHROME CENTER MOULDING
- 23 1PC FRT BUMPER TOP FRAME CENTER
- 24 2PCS FRT BUMPER SIDE BRACKET LH/RH @41.73 N/S 38
- 25 1PC FRT RADIATOR GRILLE BASE
- 26 1PC FRT RADIATOR GRILLE CENTER CHROME
- 27 2PCS FRT RADIATOR GRILLE OUTER CHROME LH TOP @38.52
- 28 2PCS FRT RADIATOR GRILLE OUTER CHROME RH BOTOM @48.15
- 29 1PC FRT RADIDATOR MERCEDES EMBLEM CHROME
- 30 1PCS FRT RADITOR GRILLE STAR
- 31 1PC FRT RADIAITOR GRILLER INNER SHEILD
- 32 1PC FRT BUMPER RE-INFORCEMENT
- 33 1PC FRT SUPPORT PANEL
- 34 2PCS FRT ANGLE BRACKET LH/RH @34.24
- 35 1PC FRT STRUT
- 36 1PC FRT BUMPER SPONGE CENTER
- 37 1PC FRT BUMPER INSIDE PART CENTER
- 38 2PCS FRT BUMPER INSIDE PARTS LH/RH @44.94
- 39 1PC FRT MOUNTING CONSOLE
- 40 1PC FRT BUMPER TOP FRAME

R	2300.50	✓	1120
R	42.80	✓	40
R	160.50	X	
R	18.20	X	
R	42.80	X	
R	38.52	X	
R	39.57	X	
R	77.04	X	
R	49.22	X	
R	10.37	X	
R	124.12	X	
R	209.72	X	
R	218.28	X	
R	813.20	✓	760
R	17.12	✓	1280
R	18.19	✓	17
R	398.04	X	
R	70.62	X	
R	59.92	X	
R	72.76	X	
R	188.32	✓	72+88
R	187.25	✓	155
R	51.36	✓	46
R	83.46	✓	72
R	77.04	✓	72
R	117.70	✓	72
R	77.04	✓	72
R	96.30	✓	72+88
R	43.87	✓	41
R	74.90	✓	70
R	72.76	✓	86
R	246.10	✓	230
R	395.90	✓	370
R	68.48	X	
R	24.61	X	
R	94.16	✓	288
R	72.76	X	
R	89.88	✓	42
R	139.10	✓	150
R	51.36	X	

BALANCE BRING FORWARD

7033.84

BALANCE BROUGHT FORWARD	
41 1PC	FRT FENDER LH
42 1PC	FRT FENDER RH
43 1PC	FRT FENDER INNER SHIELD INNER LH
44 1PC	FRT FENDER INNER SHIELD INNER RH
45 1PC	FRT FENDER INNER SHIELD OUTER LH
46 1PC	FRT FENDER INNER SHIELD OUTER RH
47 10PCS	FRT FENDER INNER SHIELD CLIPS @1.71
48 1PC	FRT HEAD LAMP LH 2250
49 1PC	FRT HEAD LAMP RH 2350
50 2PC	FRT RADIATOR
51 1PC	FRT RADIATOR FAN ASSY
52 1PC	AIRCON CONDENSOR
53 1PC	FRT NUMBER PLATE BASE
54 4PCS	COOLANT @8.03

COST PLUS 10%

S \$
7033.84

2	567.10	X
2	460.10	X
2	71.69	X
2	80.25	X
CM	69.55	85
2	69.55	X
2	17.12	X
2	2407.50	
2	2514.50	
CM	567.10	530
CM	1016.50	930
2	1102.10	700
2	80.25	75
2	32.12	3150
	16089.27	
	1608.93	
	17698.20	

SPECIAL NET ITEM

NUMBER PLATE AND CASING

6500
70.00

LABOUR CHARGES

1	CHECKING OF WIRING AND FOCUS HEADLAMPS.	200.00	200
2	TO REMOVE AND REPLACE FRONT DAMAGED PARTS, STRAIGHTEN, ALIGN FRONT AFFECTED AREAS, FLUSH COOLANT. STRAIGHTEN FRONT CHASSIS MEMBER.	1800.00	600
3	TO REMOVE AND REFIT FRONT AIRCON GASES, CHECK FAN MOTOR WIRING	120.00	100
4	TO DO RESETTING FOR BUMPER SENORS AND AFFECTED AREA AND CHECK WIRING.	200.00	60
5	TO PUTTY AND SPRAY PAINTING ON AFFECTED PORTIONS.	1500.00	800
6	TO RUST PROOF AFFECTED AREAS	200.00	X

TOTAL

21788.20

*REMARK: SUPPLEMENTARY PARTS EXPECTED
ESTIMATE PREPARE BY MR ONG, HP:96601347

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

協力汽車貿易
HIAP LEK AUTOMOBILE TRADING

[Signature]

