

HIAP LEK AUTOMOBILE TRADING

160 SIN MING DRIVE

SIN MING AUTOCITY

#05-17

SINGAPORE 575658

TEL:64531743 FAX:62668605

Email: hiaplek@hotmail.com

Not Autherized
Penalty B4 paim

814640.53 5 day
B4 excess

TO: AIG AISA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#09-16 AIG BUIDLING
Singapore 079120

ESTIMATE

DATE:07/09/2021

POLICY #:1900246338-01

YOUR REF#: SKC 85J

RE: VEHICLE NO : SKC 85J MERCEDES C200

S \$

TO SUPPLY:

- 1 1PC FRT BONNET
- 2 1PC FRT BONNET EMBLEM
- 3 1PC FRT BONNET INSULATOR
- 4 10PCS FRT BONNET INSULATOR CLIPS @1.82
- 5 2PCS FRT BONNET CATCH LH/RH @ 21.40
- 6 2PCS FRT BONNET CATCH STOPPER LH/LH @19.26
- 7 1PC FRT BONNET CENTER LOCK
- 8 2PCS FRT BONNET LOCK LH/RH @38.52
- 9 2PCS FRT BONNET LOCK SWTICH LH/RH @24.61
- 10 2PCS FRT BONNET STOPPER LH/RH @5.35
- 11 2 PCS FRT BONNET SHOCK ABSORBER LH/RH @62.06
- 12 2PCS FRT BONNET HINGE LH/RH @104.86
- 13 2PCS FRT BONNET HINGE PINS LH/RH @109.14
- 14 1PC FRT BUMPER
- 15 8PCS FRT BUMPER CLIPS @2.14
- 16 1PCS FRT BUMPER TOP WEATHER STRIP
- 17 4PCS FRT BUMPER PARKING SENSOR @99.51
- 18 2PCS FRT BUMPER LOWER GRILLE LH/RH @35.31
- 19 2PCS FRT BUMPER LOWER GRILLE SENSOR LH/RH @29.96
- 20 1PC FRT BUMPER LOWER GRILLE CENTER
- 21 2PCS FRT BUMPER LOWER CHROME MOULDING LH/RH @94.16
- 22 1PCS FRT BUMPER LOWER CHROME CENTER MOULDING
- 23 1PC FRT BUMPER TOP FRAME CENTER
- 24 2PCS FRT BUMPER SIDE BRACKET LH/RH @41.73
- 25 1PC FRT RADIATOR GRILLE BASE
- 26 1PC FRT RADIATOR GRILLE CENTER CHROME
- 27 2PCS FRT RADIATOR GRILLE OUTER CHROME LH TOP @38.52
- 28 2PCS FRT RADIATOR GRILLE OUTER CHROME RH BOTOM @48.15
- 29 1PC FRT RADIDATOR MERCEDES EMBLEM CHROME
- 30 1PCS FRT RADITOR GRILLE STAR
- 31 1PC FRT RADIAITOR GRILLER INNER SHEILD
- 32 1PC FRT BUMPER RE-INFORCEMENT
- 33 1PC FRT SUPPORT PANEL
- 34 2PCS FRT ANGLE BRACKET LH/RH @34.24
- 35 1PC FRT STRUT
- 36 1PC FRT BUMPER SPONGE CENTER
- 37 1PC FRT BUMPER INSIDE PART CENTER
- 38 2PCS FRT BUMPER INSIDE PARTS LH/RH @44.94
- 39 1PC FRT MOUNTING CONSOLE
- 40 1PC FRT BUMPER TOP FRAME

Bu	2300.50	✓ 1120
na	42.80	✓ 40
su	160.50	X
na	18.20	X
na	42.80	X
su	38.52	X
na	39.57	X
B	77.04	X
su	49.22	X
su	10.37	X
su	124.12	X
na	209.72	X
su	218.28	X
na/cm	813.20	✓ 780
na	17.12	✓ 1280
na	18.19	✓ 17
su	398.04	X
su	70.62	X
su	59.92	X
su	72.76	X
na	188.32	✓ 92+88
na	187.25	✓ 155
cm	51.36	✓ 48
dis	83.46	✓ 72
cm	77.04	✓ 72
na	117.70	✓ 110
na	77.04	✓ 72
na	96.30	✓ 45+45
na	43.87	✓ 41
cm	74.90	✓ 70
na	72.76	✓ 86
Bu	246.10	✓ 230
Bu	395.90	✓ 370
R	68.48	X
su	24.61	X
cm	94.16	✓ 88
su	72.76	X
cm	89.88	✓ 42
cm	139.10	✓ 150
su	51.36	X

BALANCE BRING FORWARD

7033.84

BALANCE BROUGHT FORWARD

S \$

7033.84

41	1PC	FRT FENDER LH	
42	1PC	FRT FENDER RH	
43	1PC	FRT FENDER INNER SHIELD INNER LH	
44	1PC	FRT FENDER INNER SHIELD INNER RH	
45	1PC	FRT FENDER INNER SHIELD OUTER LH	
46	1PC	FRT FENDER INNER SHIELD OUTER RH	
47	10PCS	FRT FENDER INNER SHIELD CLIPS @1.71	
48	1PC	FRT HEAD LAMP LH	2250
49	1PC	FRT HEAD LAMP RH	2350
50	2PC	FRT RADIATOR	
51	1PC	FRT RADIATOR FAN ASSY	
52	1PC	AIRCON CONDENSOR	
53	1PC	FRT NUMBER PLATE BASE	
54	4PCS	COOLANT @8.03	

COST PLUS 10%

567.10	X
460.10	X
71.69	X
80.25	X
69.55	X
69.55	X
17.12	X
2407.50	X
2514.50	X
567.10	X
1016.50	X
1102.10	X
80.25	X
32.12	X
16089.27	
1608.93	
17698.20	

SPECIAL NET ITEM

NUMBER PLATE AND CASING

DU 70.00

LABOUR CHARGES

1	CHECKING OF WIRING AND FOCUS HEADLAMPS.	200.00	200
2	TO REMOVE AND REPLACE FRONT DAMAGED PARTS, STRAIGHTEN, ALIGN FRONT AFFECTED AREAS, FLUSH COOLANT. STRAIGHTEN FRONT CHASSIS MEMBER.	1800.00	600
3	TO REMOVE AND REFIT FRONT AIRCON GASES, CHECK FAN MOTOR WIRING	120.00	100
4	TO DO RESETTING FOR BUMPER SENORS AND AFFECTED AREA AND CHECK WIRING.	200.00	60
5	TO PUTTY AND SPRAY PAINTING ON AFFECTED PORTIONS.	1500.00	800
6	TO RUST PROOF AFFECTED AREAS	200.00	X

TOTAL

21788.20

***REMARK: SUPPLEMENTARY PARTS EXPECTED
ESTIMATE PREPARE BY MR ONG, HP:96601347**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

協力汽車貿易
HIAP LEK AUTOMOBILE TRADING

Qing

2. BY:

REF:

AIG/

HIAP LEK AUTOMOBILE TRADING

160 SIN MING DRIVE

SIN MING AUTOCITY

#05-17

SINGAPORE 575658

TEL:64531743 FAX:62668605

Email: hiaplek@hotmail.com

SUPPLEMENTARY

DATE:14/09/2021

POLICY #:1900246338-01

YOUR REF#: SKC 85J

AIG AISA PACIFIC INSURANCE PTE LTD

78 Shenton Way

#09-16 AIG BUILDING

Singapore 079120

VEHICLE NO : SKC 85J MERCEDES C200

S \$

TO SUPPLY:

1PC	FRT RADIATOR LOWER PRESURE
1PC	FRT RADIATOR SPARE TANK FRONT PIPE
1PC	FRT BUMPER RADAR SENSOR BOX
2PCS	FRT HEAD LAMP BURLAS CONTROL LED LH/RH @732.95
2PCS	FRT HEAD LAMP BARLAS CONTROL RH/LH @609.90

460
47
580

R	492.20	✓
CM	51.36	✓
CM	620.60	✓
SM	1465.90	X
SM	1219.80	X
	3849.86	
	384.99	

COST PLUS 10%

TOTAL

4234.85

SUPPLEMENTARY PREPARED BY MR ONG, HP:96601347

協力汽車貿易
HIAP LEK AUTOMOBILE TRADING

Ong