

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: IN.514351.KC Date: 26th Oct 2021

Our Ref: CS1/LAW21009492/Gqf3e2

M/s Riaz LLC

133 New Bridge Road #09-09 Chinatown Point Singapore 059413

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FX 9487Y INSURED VEHICLE: SJG 7710H

ACCIDENT DATE: 30/07/2018

We thank you for your instruction on 09/09/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FX 9487Y from M/s Advanced Automotive Consultancy Pte Ltd.
- b) Survey report by AJAX Inspection Services Pte Ltd with colour photographs.
- c) Final Repair Bill of FX 9487Y from M/s Equator Brotherhood.
- d) Singapore Accident Statement and Police Report of Vehicles FX 9487Y.
- e) Colour damaged vehicle photographs of FX 9487Y.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FX 9487Y Make & Model : Honda CB400M

Chassis Number : NC391051123

Year of Registration : 2004 Engine Capacity : 399 cc

- 2. We recommend that the repairs of the entire damage require about <u>2 (Two)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.