



HUA HONG PRIVATE LIMITED

10 Kaki Bukit Avenue 4 #04-63 Premier@Kaki Bukit Singapore 415874
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

13 September 2021

QUOT202109-000003
HHTPCCLAIMS21-53

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET, #04-00 / #05-00
IOB BUILDING
SINGAPORE 049711

Attn: Motor Claims Department

TP III.
Cecil.

ACCIDENT INVOLVING SLJ4863E & GBH6743J ON 07/09/2021 ALONG UNITY STREET AT ABOUT 0955 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No. : SLJ4863E
Vehicle Make : HONDA
Vehicle Model : JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Vehicle Chassis No. : JHMGK5850HX200960
Policy No. : 5109921641-02-000042
Date of Accident : 07/09/2021

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper <i>Dehd</i>		\$ 1,379.00 497
2	10	Rear Bumper Clips <i>Neu</i>	\$ 5.00	\$ 50.00 30
3	2	Rear Bumper Side Retainer (LH/RH) <i>Neu</i>	\$ 37.50	\$ 75.00
4	1	Rear Tailgate <i>Distorted</i>		\$ 2,005.00 755
5	1	Rear Tailgate Lock <i>Dist.</i>		\$ 525.00 157
6	1	Rear Tailgate Chrome <i>at</i>		\$ 686.70 234
7	1	Rear Tailgate Emblem <i>Neu</i>		\$ 64.75 40
8	1	Rear Tailgate Logo (Jazz) <i>Neu</i>		\$ 68.25 42
9	1	Rear Windscreen Moulding <i>Neu</i>		\$ 420.00 85
10	1	Rear Tail Lamp (RH) <i>Neu</i>		\$ 785.10
11	1	Rear End Panel <i>Rep</i>		\$ 1,054.80
12	1	Rear End Panel Top Garnish <i>Neu</i>		\$ 227.50
				\$ 7,341.10
				Less 20% \$ 1,468.22
				\$ 5,872.88
13	1	Rear Number Plate <i>Neu</i>	200	NETT \$ 35.00
14	1	Rear Reverse Sensor <i>Dist</i>		NETT \$ 200.00
				\$ 800.00 500
				\$ 50.00 600.30
				\$ 80.00 60
				\$ 120.00
				\$ 800.00 600

To cut & weld rear end panel. Change rear bumper, rear tailgate. Knocking all area affected by accident

To perform wire checking

To transfer rear tailgate mechanism to new tailgate

To remove & refit rear windscreen

To spray rear end panel, rear bumper, rear tailgate and all affected area

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

10 Kaki Bukit Avenue 4 #04-63 Premier@Kaki Bukit Singapore 415874
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

13 September 2021

QUOT202109-000003
HHTPCLAIMS21-53

ACCIDENT INVOLVING SLJ4863E & GBH6743J ON 07/09/2021 ALONG UNITY STREET AT
ABOUT 0955 HOURS

Estimate Repair List for vehicle SLJ4863E - HONDA JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD

S/N	Quantity	Description	Unit Price S\$	Amount S\$
				\$ 7,957.88
			7% GST	\$ 557.05
			Total	\$ 8,514.93

Adrian L
2/S 15/09/21.
05pm>

total: 3042.
2/S: 2.4K.



Authorised by Claims Dept

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: