

AUTHORISE REPAIR GBF9421D AIG OWN DAMAGE

Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Thu 23/9/2021 5:19 PM

To: AIM PTE LTD <automim.claim@gmail.com>

Cc: SUR <sur@lkkauto.com>

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBF 9421D** (Excess \$600/-). **PART BY PART cost plus 15%**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

Re-inspection to be done for damage check and supplementary items / labour with clear photos.

FRONT BUMPER TOP BEAM, FRONT GRILLE – TOP, FRONT GRILLE BASE – Retake damage photos.
FRONT SUPPORT PANEL – To repair.

All old parts to be taken with the new parts during before paint photos. Part by part repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)