

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17022248/GRBS2
Date: 05/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1711421700
Claimant Vehicle No :	JSG6387	Insured Vehicle No :	GBE6930B
Date of Loss:	16/11/2017	Nature of Claim:	TP
			Claim No: SNM17D06665C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JSG6387	Engine No:	590617949
Make & Model:	KTM 200 EGS, 193cc (M)	Chassis No:	PNGJYC40XFK027301
Reg. Date:	14/08/2017 (Man. Year: 2017)	Odometer:	5948 km
Colour:	Black		
Engine Capacity:	199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/70R17	Rear Tyre Size:	150/60R17
Front Left Side:	MRF 5 mm	Rear Left Side:	MRF 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,120.00	2,356.28	6,763.72	74.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	250.00	1,600.00	86.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,970.00	2,606.28	8,363.72	76.24
Approved Total (Overridden) (S\$)		2,050.00		
Nett Amount (S\$)	10,970.00	2,050.00	8,920.00	81.31

INSPECTION

Date of Assignment:	22/11/2017		
Date Inspected:	23/11/2017	Inspected At:	Our Bro's Workshop (s) Pte Ltd (HQ) 10 Kaki Bukit Road 2, #03-37/38 First East Centre Singapore 417868
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Nov 2018)	
Parts:	N/A	KTM 200 EGS 193cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/JSG6387/05/12/2018 14:03	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PAIR FRONT FORK ASSY	Not Necessary	1,400.00 F	*- FL
2	1		*FRONT BRAKE DISC	Not Necessary	325.00 F	*- FL
3	1		*FRONT UNDER BRACKET	Not Necessary	395.00 F	*- FL
4	1		*FRONT UPPER CLAMP	Not Necessary	315.00 F	*- FL
5	1		*FRONT WINDSHIELD	Broken	255.00 F	*66.00 FL
6	1		*HEADLAMP ASSY	Broken	900.00 F	*181.00 FL
7	1		*HEAD FAIRING	Broken	650.00 F	*54.00 FL
8	1		*INSTRUMENTAL PANEL	Cracked	565.00 F	*265.20 FL
9	1		*PAIR HANDLEBAR	Bent	78.00 F	*78.00 FL
10	1		*PAIR HANDLEBAR GRIP	Cut	56.00 F	*56.00 FL
11	1		*PAIR HANDLEBAR BALANCER	Not Necessary	40.00 F	*- FL
12	1		*LH CLUTCH CONTROL LEVER	Not Necessary	37.00 F	*- FL
13	1		*RH BRAKE CONTROL LEVER	Not Necessary	39.00 F	*- FL
14	1		*PAIR WING MIRROR W/ARM	Broken	320.00 F	*125.00 FL
15	1		*FRONT FENDER	Cut	210.00 F	*79.00 FL
16	2		*FRONT (SIDE) FAIRING	Cut	900.00 F	*520.00 FL
17	1		*PAIR FRONT (UNDER) FAIRING	Cracked	440.00 F	*280.00 FL
18	1		*SET REAR FAIRING	Repair	450.00 F	*- FL
19	1		*PAIR PILLION RIDER FOOT REST	Broken	80.00 F	*40.00 FL
20	1		*PAIR PILLION RIDER FOOT REST SUPPORT BRACKET	Buckled	270.00 F	*135.00 FL
21	1		*FRONT WHEEL RIM	Cut	650.00 FS	*350.00 FS
22	1		*FRONT TYRE	Scratched	360.00 FS	*100.00 FS
23	1		*SET DECORATIVE STICKERS	Necessary	350.00 FS	*200.00 FS
24	1		*FRONT NO. PLATE STICKER	Necessary	35.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,120.00	2,544.20
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	187.92

Total Parts (\$\$)	9,120.00	2,356.28
---------------------------	-----------------	-----------------

LKK Auto Consultants Pte Ltd/JSG6387/05/12/2018 14:03. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND REPLACE DAMAGED PARTS.	New	800.00	150.00
2	TO CHECK WIRING AND REWIRE.	New	100.00	0.00
3	TO REALIGN FRONT FORK.	New	200.00	60.00
4	TO DO BODY FRAME ALIGNMENT.	New	180.00	0.00
5	TOWING CHARGES.	New	100.00	40.00
6	TO ANTI-RUST.	New	120.00	0.00
7	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.	New	350.00	0.00
Gross Labour Cost (\$\$)			1,850.00	250.00

LKK Auto Consultants Pte Ltd/JSG6387/05/12/2018 14:03. Not valid without Reference section.

< END OF ESTIMATES >