



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2107482

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 29/10/2021
Reference CC3/CTI21009502/Vea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 3125D
Insured Veh. SLH 8112Z
Claim No. SNM21D205109/C02
Policy No.
Accident Date 31/08/2021
Inspection Date 02/09/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21009502/Vea3q2	
			Date: 29/10/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLH 8112Z	Veh. Inspected	SHA 3125D	
Policy No.		Coverage (\$)	0.00	
Claim No.	SNM21D205109/C02	Excess (\$)	0.00	
Assign From		Assign Date	02/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHC851CVKU107455	Colour	BLUE	
Odometer	309820 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/08/2021	Inspection Date	02/09/2021	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3125D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	459.40	459.40
1	REAR BUMPER CENTRE MOULDUING	CUT	451.25	451.25
1	REAR BUMPER REINFORCEMENT	DENTED	394.80	394.80
2	REAR BUMPER STAY LH/RH @\$138.10	SERVICEABLE	276.20	-
1	REAR BUMPER LOWER CENTRE MOULDING	DISTORTED	155.00	155.00
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	BOOTLID COVER	DEFORMED	2,480.40	2,480.40
1	BOOTLID LOCK UPPER	SERVICEABLE	224.00	-
1	BOOTLID H EMBLEM	NECESSARY	38.00	38.00
1	BOOTLID EMBLEM IONID	NECESSARY	31.80	31.80
1	BOOTLID EMBLEM HYBRID	NECESSARY	24.30	24.30
1	BUMPER FOG LAMP	CUT	201.00	201.00
2	BUMPER NUMBER PLATE LH/RH @\$85.30	SERVICEABLE	170.60	-
2	REAR REFLECTOR LH/RH @\$41.45	SERVICEABLE	63.53	-
1	REAR BUMPER TOW COVER	SERVICEABLE	98.80	-
1	REAR END PANEL	SERVICEABLE	532.00	-
1	REAR PANEL GARNISH	SERVICEABLE	346.80	-
1	REAR ANTENNA -SMART KEY	CUT	40.50	40.50
2	REAR BUMPER BRACKET LH/RH @\$55.80	TO REPAIR SEE LABOUR	111.60	-
	LESS 20% DISCOUNT		-1,224.40	-859.69
			4,897.58	3,438.76
<u>SPECIAL NETT ITEMS</u>				
1	BOOTLID COMFORT APP STICKER (SN)	NECESSARY	40.00	40.00
2	BOOTLID COMFORT /TEL NUMBER STICKER @\$30.00 (SN)	NECESSARY	60.00	60.00
1	REAR NUMBER PLATE W/HOLDER (SN)	CRACKED	55.00	55.00
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	BOOTLID ADVERTISEMENT (SN)	NECESSARY	100.00	100.00
1	REAR REVERSE SENSOR (SN)	CUT	180.00	180.00
			485.00	485.00

Report Ref No. CC3/CTI21009502/Vea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET LH/RH .		900.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK WIRING AND LIGHTING.		60.00	30.00
	REMOVE/REFIX REAR WINDSCREEN.		120.00	120.00
	TUFF KOTE.		90.00	20.00
	REMOVE/REFIX REVERSE SENSOR .		60.00	20.00
			1,830.00	1,390.00
	GRAND TOTAL		7,212.58	5,313.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,250.00

Report Ref No. CC3/CTI21009502/Vea3q2

THEVAN THOMAS KARTHIKESAVAN

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 3125D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 3125D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

