

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 06/09/2021
TP Veh Reg No: SBD24L

Estimate No: EST2100234
Date: 08 Sep 2021
Veh Reg No: SMN396E
Make/Model: HONDA FIT HYBRID
1.5AUTO
Chasis No: GP51341972
Reg. Date: 23/07/2019
Your Ref No: SBD24L

Xiao Tony

Estimate Repair Cost to Vehicle No :SMN396E

Quantity	Description	List Price SS	Amount SS
1	1 PC REAR BUMPER <i>Delhd</i>	505.10	✓
		505.10	
	Less 20%	101.02	404.08
2	1 SET REAR BUMPER CLIPS <i>xc</i>	60.00 <i>30</i>	60.00
		60.00	60.00
3	1 (REAR) TO SPRAY PAINTING	600.00 <i>200</i>	
4	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	450.00 <i>200</i>	
	<i>To remove & refix reverse sensor</i>	1,050.00	1,050.00
	<i>\$80/-</i>	Total	S\$ 1,514.08
	<i>50</i>	Add GST @ 7%	105.99
		Total Amount Payable	S\$ 1,620.07

TOTAL: SINGAPORE DOLLAR ONE THOUSAND SIX HUNDRED TWENTY AND CENTS SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Admin
P/P 09/09/21
02 Pyp

AUTHORISED SIGNATURE

total: 884.08 (P/P)