

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0736/2021/KS
DATE : 8-Sep-21
WIP : 43251

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/9/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR KHOO RONGWEN (QIU YONGWEN)
ADDRESS : 73 ANCHORVALE CRESCENT
#09-07
SINGAPORE 544661
TELEPHONE : HP +65 96282254
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900108509-01
VEHICLE NO : **SML 9740 X**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 13/6/2019
ENGINE NO : CHZ C27820
CHASSIS NO : WAUZZZ8V0K1025220
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Sep-21
PLACE OF ACCIDENT : ALONG BKE(PIE) CLOSE TO EXIT 3 (BUKIT PANJANG RD)

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICL. SML 9740 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING ATD.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓ ✓	\$ 3,500.00 1000	
4	TO RESPRAY FRONT BUMPER, BONNET, HINGES BOTH FRONT FENDER AND BOTH UPPER A-PILLARS.	\$ 5,500.00 1100	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,252.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 9740 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Deh-d</i>	1	\$ 1,987.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 187.00	+
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 78.00	+
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 160.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 536.00	+
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2	\$ 594.00	+
7	FRONT BUMPER ADAPTOR - LH / RH <i>new</i>	2	\$ 76.00	+
8	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,406.00	✓
9	RADIATOR GRILLE CLOSING ELEMENT ? <i>cracked</i>	1	\$ 191.00	? ✓
10	A/C STICKER ? <i>new</i>	1	\$ 8.00	✓
11	"CAUTION" STICKER	1	\$ 14.00	✓
12	FOAM FILLER PIECE ?	1	\$ 189.00	?
13	FRONT BUMPER TOP COVER ? <i>deformed</i>	1	\$ 122.00	? ✓
14	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$ 795.00	?
15	BONNET <i>Buckled</i>	1	\$ 3,134.00	✓
16	BONNET HINGE - LH / RH ?	2	\$ 124.00	+
17	BONNET CATCH HOOK ? <i>new</i>	1	\$ 90.00	+
18	BONNET STRIKER - LH / RH	2	\$ 220.00	+
19	BONNET LOCK WITH MICRO SWITCH - LH / RH <i>new</i>	2	\$ 427.00	+
20	BONNET EDGE PROTECTION <i>new</i>	1	\$ 28.00	✓
SUB TOTAL SPARE PARTS		:	\$ 10,366.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9101 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BOWDEN CABLE CENTER	1	\$ 28.00	X
23	PLENUM CHAMBER COVER	1	\$ 179.00	X
23	BOWDEN CABLE COVER	1	\$ 10.00	X
24	FRONT FENDER - LH / RH	2	\$ 1,702.00	X
25	FRONT FENDER ATTACHMENT PARTS	1	\$ 72.00	X
26	FRONT FENDER BRACKET - LH / RH	2	\$ 78.00	X
27	FRONT FENDER BRACE - LH / RH	2	\$ 192.00	X
28	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 338.00	X
29	LED HEADLIGHT - LH / RH	2	\$ 10,910.00	X
30	HEADLIGHT HOSE	1	\$ 68.00	X
31	WATER DEFLECTOR STRIP - LH / RH	2	\$ 186.00	X
32	RADIATOR AIR GUIDE UPPER - CENTRE	1	\$ 12.00	X ✓
TOTAL SPARE PARTS		:	\$ 24,141.00	
TOTAL LABOUR CHARGES		:	\$ 10,252.00	
GRAND TOTAL		:	\$ 34,393.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *09/09/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT