

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

Veron.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0736/2021/KS

28-Sep-21

CHANG

1 of 1

SML 9740 X

AUDI A3 SEDAN 1.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	✓
2	TO REMOVE AND RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 2,800.00	1250. ✓
Parts			
1	RADIATOR AIR GUIDE - LH/RH <i>behind</i>	2 \$ 50.00	✓
2	RADIATOR AIR GUIDE SEAL - RH OUTER <i>David</i>	\$ 8.00	✓
3	COOLANT <i>new</i>	\$ 266.00	✓
4	FRONT LOCK CARRIER <i>checked.</i>	\$ 727.00	✓
5	FRONT NUMBER PLATE <i>new</i>	S/N \$ 60.00	✓
6	SUNDRIES <i>?</i>	\$ 300.00	✓
GRAND TOTAL		\$ 5,611.00	

For Premium Automobiles Pte Ltd

Adrian Ling
Reneyed-
HS



Authorised Signature

Car-in 28/9/21-

wip. 43251.

PREMIUM AUTOMOBILES

kiam /



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PRFMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 9740 X

AIG-Adrian
-4 days


DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Dehnd</i>	1	S	1,987.00 ✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	S	187.00 ✗
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	S	78.00 ✗
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	S	160.00 ✗
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	S	536.00 ✗
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2	S	594.00 ✗
7	FRONT BUMPER ADAPTOR - LH / RH <i>new</i>	2	S	76.00 ✗
8	RADIATOR GRILLE <i>Cracked</i>	1	S	1,406.00 ✓
9	RADIATOR GRILLE CLOSING ELEMENT <i>cracked</i>	1	S	191.00 ✓
10	A/C STICKER <i>new</i>	1	S	8.00 ✓
11	"CAUTION" STICKER	1	S	14.00 ✓
12	FOAM FILLER PIECE	1	S	189.00 ?
13	FRONT BUMPER TOP COVER <i>Dehnd</i>	1	S	122.00 ✓
14	FRONT BUMPER REINFORCEMENT BEAM	1	S	795.00 ?
15	BONNET <i>Buckled</i>	1	S	3,134.00 ✓
16	BONNET HINGE - LH / RH	2	S	124.00 ✗
17	BONNET CATCH HOOK <i>new</i>	1	S	90.00 ✗
18	BONNET STRIKER - LH / RH	2	S	220.00 ✗
19	BONNET LOCK WITH MICRO SWITCH - LH / RH <i>new</i>	2	S	427.00 ✗
20	BONNET EDGE PROTECTION <i>new</i>	1	S	28.00 ✓
SUB TOTAL SPARE PARTS		:	\$	10,366.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 9740 X
SMV 9101 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BOWDEN CABLE CENTER	1	\$ 28.00	X
23	PLENUM CHAMBER COVER	1	\$ 179.00	X
23	BOWDEN CABLE COVER	1	\$ 10.00	X
24	FRONT FENDER - LH / RH	2	\$ 1,702.00	X
25	FRONT FENDER ATTACHMENT PARTS	1	\$ 72.00	X
26	FRONT FENDER BRACKET - LH / RH	2	\$ 78.00	X
27	FRONT FENDER BRACE - LH / RH	2	\$ 192.00	X
28	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 338.00	X
29	LED HEADLIGHT - LH / RH	2	\$ 10,910.00	X
30	HEADLIGHT HOSE	1	\$ 68.00	X
31	WATER DEFLECTOR STRIP - LH / RH	2	\$ 186.00	X
32	RADIATOR AIR GUIDE UPPER - CENTRE	1	\$ 12.00	X
TOTAL SPARE PARTS		:	\$ 24,141.00	
TOTAL LABOUR CHARGES		:	\$ 10,252.00	
GRAND TOTAL		:	\$ 34,393.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Supp

For. No Plate