

TPA 16.
Veron.

MCS Garage

10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868

Tel: 9270 0917 / 6538 4322

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle number: SMA8060P

Vehicle Made & Model: CHEVROLET CRUZE

	<u>List Items</u>	<u>Amount \$</u>
1	Front bonnet <i>Dented.</i>	1,362.00 ✓
1	Front bonnet seal - CTR	58.00 x
2	Front bonnet seals - L/R @ 56	112.00 x
1	Front bonnet insulator	189.00 x
2	Front bonnet hinges - L/R @ 55	110.00 x
1	Front bonnet lock	132.00 x
1	Front bumper <i>Distorted.</i>	1,075.00 ✓
1	Front bumper logo <i>NEC</i>	105.00 ✓
1	Front bumper fog lamp - RH <i>3 new NEC</i>	285.00 x
1	Front bumper fog lamp cover	89.00 x.
1	Front bumper lower seal <i>Distorted</i>	116.00 ✓
1	Front bumper sponge <i>crackd</i>	132.00 ✓
1	Front bumper reinforcement <i>Best.</i>	895.00 ✓
2	Front bumper side retainers - L/R @ 45 <i>Rit Dand</i>	90.00 45
1	Front bumper undercover <i>new NEC</i>	189.00 x.
1	Front fender - RH <i>Distorted</i>	786.00 ✓
1	Front fender inner shield <i>torn</i>	146.00 ✓
1	Front fender wheel housing assy <i>Buckd.</i>	1,150.00 ✓
1	Front fender top garnish <i>Crackd.</i>	82.00 ✓
1	Front door - RH <i>Repair</i>	1,580.00 x.
1	Front door side mirror <i>Dashed.</i>	635.00 ✓
1	Front door side mirror cover <i>Missing</i>	182.00 ✓
2	Front lower arms - L/R @ 580 <i>Best.</i>	1,160.00 ✓
2	Front knuckle arms @ 543 <i>Dand</i>	1,086.00 ✓
2	Front wheel hubs @ 289 <i>Dand</i>	578.00 ✓
2	Front wheel bearings @ 185 <i>Dand</i>	370.00 ✓
1	Front drive shaft - RH <i>3 new</i>	1,360.00 x
1	Front anti roll bar	365.00 x
2	Front anti roll bar links @ 105 <i>3 new</i>	210.00 x
1	Front steering rack assy	1,892.00 x
1	Front steering rack crossmember <i>new</i>	1,865.00 x.
1	Front grille - Top <i>Crackd.</i>	265.00 ✓
1	Front grille - Lower <i>3 new</i>	282.00 x
1	Air cleaner resonator	195.00 x.

Vehicle number: SMA8060P

Vehicle Made & Model: CHEVROLET CRUZE

1	Front headlamp - RH <i>cracked.</i>	935.00 ✓
1	Rear door - RH <i>dent</i>	1,560.00 ✓
1	Rear door outer handle <i>Repair</i>	192.00 x
1	Rear fender - RH <i>Distorted</i>	1,895.00 ✓
1	Rear axle beam	2,650.00 x
2	Rear wheel hub bearings @ 455 <i>2 NP New</i>	910.00 x
1	Rear windscreen moulding	132.00 x
1	Rear bumper	1,075.00 x
Sub-total		28,477.00
Less 10%		2,847.70
Total List		25,629.30

13000
11700.

Special Nett Items

1 set	F/R sport shock absorber assy <i>Best</i>	1,500.00 <i>1000.</i>
2	Front sport wheels - L/R @ 450 <i>LH Best, RH ut</i>	900.00 ✓
2	Front tyres - L/R @ 300 <i>RH punched, RH ut</i>	600.00 <i>250 400.</i>
1 Tin	Auto TX Fluid <i>New</i>	120.00 <i>50</i>
1 Bot	Power steering fluid <i>New</i>	60.00 <i>40</i>
1 set	Rear windscreen sealant <i>New</i>	80.00 <i>60.</i>
2	Rear sport wheels - L/R @ 450 <i>New</i>	900.00 x
2	Front tyres - L/R @ 300 <i>Repeated</i>	600.00 x
		4,760.00

2450

Labour charges

To check front & rear electrical wiring	80.00 <i>30.</i>
Towing charges - 2 trips	240.00 <i>60.</i>
To remove, refix front undercarriage	650.00 <i>500</i>
To remove, refix rear undercarriage	350.00 x
To check wheel alignment	120.00 <i>80.</i>
To remove, refix rear interior trims to assit repair	120.00 <i>60.</i>
To remove, refix A/C condenser & Refill A/C gas	180.00 x
To respray undercoating	60.00 ✓
To respray painting and etc	1,800.00 <i>1400.</i>
Panel beating, cut, weld remove & replacing above parts	3,000.00 <i>1600</i>
Total Labour	6,600.00

3790.

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 36,989.30

total: 17440.
n/s: 12K ✓
(Nett Value)
14 Days