



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI21009520/Uqf3e2 Date: 11/10/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMT 1661B	Veh. Inspected	SJY 4717P
Policy No.		Coverage (\$)	0.00
Claim No.	C10011592/EE	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	10/09/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH 2.0 (A)	c.c	1987
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JTDGJ20W705002469	Colour	BLUE
Odometer	125801 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	DUNLOP	5 mm
L/H Front Tyre	205/55 R16	DUNLOP	5 mm
R/H Rear Tyre	205/55 R16	DUNLOP	5 mm
L/H Rear Tyre	205/55 R16	DUNLOP	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND O/S BODY. THE UNDERCARRIAGE AND CHASSIS FRAME AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/09/2021	Inspection Date	14/09/2021
Survey held at	NPH AUTO SERVICE BLK 9005 TAMPINES STREET 93 #01-246/254 SINGAPORE 528839		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		20 Working Days	