

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 5JY 4717Pat Workshop m/s NPH

of _____

Insured: SM T 1661B

Policy No. _____


Claims No. C10011592/EE

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 61k.

IDAC Accident Report: _____

GIA / PR Seen: _____

Est. Repairs: 20 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 5286Veh No: 5JY 4717PYr Regn: 06/09/10Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA /Make: Toyota wish2.0 c.c. 1987Colour: blueA/C: Insured / Std / NI / NASp. Reading: 125801T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDGJ20W705002469Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or afterBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55-216

R: _____

BS / BUM / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mm

Rear

R/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 6/9/21D.O.I. 14/9/21

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orThe U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/9/21 wksp MR NG cell Do not come for survey because h/s wksp have suspect covid-19
 call up at 30-6-2030 LTA \$29521
 not more than 31k. Note \$31k79

4/10/21 compressor cracked
 4/5 \$31,000 confirmed with MR NG (Red \$37950.21, 55%)

Note: MV:\$61K(est); LTA:\$29521, NV:\$31479

Date/Time, File Pass to?

☐

Preli. Report

1) 05/10 Typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 20Resurvey No. of Trip: 2

Survey Fee:

Transportation: _____

) __ \$ + RS __ \$

) Photos

) Others

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$Report Format : TPLump Sum TP: (\$ 31000

TOTAL



NPH AUTO SERVICE



Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg

Your Ref :
Our Ref : TP0062/09/21

Page : 1/5
Date : 09/09/2021

THIRD PARTY CLAIM
M/S : ZHUANG SHIRON
BLK 608B TAMPINES NORTH DRIVE 1
#06-316
SINGAPORE 522608

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SJY4717P - TOYOTA WISH
INSURED : ZHUANG SHIRON
DATE OF ACCIDENT : 06/09/2021
POLICY NO : 5117735284-01

ENGINE# :
CHASSIS# :

not Authorized
OK
14/9/21
1/5531.000!
Abdul Halim
20 Days

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

		Qty	U/Cost \$	U/Price \$	Total \$
Replacement of Parts					
1	front bonnet <i>one ✓</i>	10	977.80	977.80	977.80 ✓
2	front bonnet hinge L&R <i>one ✓</i>	20	55.00	55.00	110.00 ✓
3	front bonnet front rubber <i>one ✓</i>	10	44.10	44.10	44.10 ✓
4	front bonnet front rubber stopper <i>one ✓</i>	30	10.00	10.00	30.00 ✓
5	front bonnet sponge <i>one ✓</i>	10	395.00	395.00	395.00 ✓
6	front bonnet sponge clips <i>one ✓</i>	160	5.50	5.50	88.00 ✓
7	front bonnet logo <i>one ✓</i>	10	72.20	72.20	72.20 ✓
8	front bonnet lock lower rubber <i>one ✓</i>	10	35.00	35.00	35.00 ✓
9	front bonnet wiper nozzle L&R <i>one ✓</i>	20	32.00	32.00	64.00 ✓
10	front grille <i>one ✓</i>	10	185.00	185.00	185.00 ✓
11	front grille top clips <i>one ✓</i>	40	5.00	5.00	20.00 ✓
12	front grille top garnish <i>one ✓</i>	10	100.00	100.00	100.00 ✓
13	front grille top garnish clips <i>one ✓</i>	40	5.00	5.00	20.00 ✓
14	front bumper <i>one ✓</i>	10	584.70	584.70	584.70 ✓
15	front bumper fog lamp L&R <i>one/m/s ✓</i>	20	425.00	425.00	850.00 ✓
16	front bumper fog lamp grille L&R <i>one ✓</i>	20	124.30	124.30	248.60 ✓
17	front fog lamp side grille L&R <i>one ✓</i>	20	46.62	46.62	93.24 ✓
18	front bumper sponge <i>one ✓</i>	10	100.00	100.00	100.00 ✓
19	front bumper side retainer L&R <i>one ✓</i>	20	59.57	59.57	119.14 ✓
20	front bumper reinforcement <i>one ✓</i>	10	305.20	305.20	305.20 ✓
21	front fender L&R <i>one ✓</i>	20	851.20	851.20	1,702.40 ✓
22	front fender inner cowling L&R <i>one ✓</i>	20	172.70	172.70	345.40 ✓
23	front fender signal lamp L&R <i>one ✓</i>	20	98.00	98.00	196.00 ✓
24	front fender 1/4 glass with rubber L&R <i>one ✓</i>	20	165.00	165.00	330.00 ✓
25	front wiper grille <i>one ✓</i>	10	603.00	603.00	603.00 ✓
26	front wiper grille side joint L&R <i>one ✓</i>	20	44.40	44.40	88.80 ✓

1942.54



NPH AUTO SERVICE



Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

GST Reg No: MX-0869103-NO Business Reg No: 394773/00D

E-mail: nphauto@pacific.net.sg

Your Ref :
Our Ref : TP0062/09/21

Page : 2/5
Date : 09/09/2021

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

		Qty	U/Cost \$	U/Price \$	Total \$
27	front headlamp support panel w/radiator top panel	1pc	1289.00	1289.00	1,289.00 ✓
28	front air con condenser	1pc	1507.40	1507.40	1,507.40 X
29	front air con condenser to compressor pipe	1pc	400.00	400.00	400.00 X
30	front air con condenser to cooling coil pipe with drier pipe	1pc	680.00	680.00	680.00 X
31	front horn	1pc	110.00	110.00	110.00 ✓
31	front battery top bracket	1pc	30.00	30.00	30.00 ✓
32	front radiator assy	1pc	1507.40	1507.40	1,507.40 ✓
32	front radiator top bracket L&R	2pc	50.80	50.80	101.60 X
33	front wiper reserve tank	1pc	69.10	69.10	69.10 ✓
34	front wiper reserve tank hose	1pc	18.00	18.00	18.00 X
35	front radiator reserve tank	1pc	190.10	190.10	190.10 ✓
36	front radiator reserve tank top hose	1pc	52.20	52.20	52.20 X
37	front wiper motor	1pc	242.00	242.00	242.00 ✓
38	front brake oil tank	1pc	205.00	205.00	205.00 ✓
39	front ABS pump assy	1pc	7630.00	7630.00	7,630.00 ✓
40	front ABS pipe metal	6pc	41.00	41.00	246.00 X
41	front radiator top hose joint	1pc	75.00	75.00	75.00 X
42	front air cleaner front hose LH	1pc			0.00 X
43	front air cleaner box hose	1pc	166.15	166.15	166.15 X
44	front wheel house panel RH	1pc	550.00	550.00	550.00 ✓
45	front chassis member RH	1pc	1785.00	1785.00	1,785.00 X
46	front chassis member front joint	1pc	55.00	55.00	55.00 X
47	front air con condenser side cowling RH	1pc	56.00	56.00	56.00 ✓
48	front engine mounting top RH	1pc	416.00	416.00	416.00 ✓
49	front engine mounting bracket RH	1pc	157.00	157.00	157.00 ✓
50	front gear box mounting LH	1pc	260.00	260.00	260.00 X
51	front gear box mounting bracket LH	1pc	125.00	125.00	125.00 X
52	centre engine mounting front	1pc	181.09	181.09	181.09 X
53	center engine mounting bracket front	1pc	78.20	78.20	78.20 X
54	center engine mounting rear	1pc	185.00	185.00	185.00 X
55	center engine mounting bracket rear	1pc	125.00	125.00	125.00 X
56	front windscreen	1pc	1429.60	1429.60	1,429.60 ✓
57	front windscreen rubber moulding	1pc	89.95	89.95	89.95 ✓
58	front door L&R	2pc	1395.00	1395.00	2,790.00 ✓
59	front door black sticker	1 set	65.00	65.00	65.00 ✓
60	front door hinge top RH	1pc	85.00	85.00	85.00 X
61	front door hinge bottom RH	1pc	75.50	75.50	75.50 X

19772 92



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

GST Reg No: MX-0869103-NO Business Reg No: 394773/00D

E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0062/09/21

Page : 3/5
Date : 09/09/2021

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

		Qty	U/Cost	U/Price	Total
			\$	\$	\$
62	front door central lock check RH	11	183.80	183.80	183.80 ✓
63	front side mirror with glass	11	988.50	988.50	988.50 ✓
64	front door w/strip rubber L&R	20	175.00	175.00	350.00 ✓
65	running board spoiler L&R	20	1090.00	1090.00	2,180.00 ✓
66	front door pillar RH	11	465.00	465.00	465.00 ✓
67	front door inner transparent water proof plastic L&R	11	85.00	85.00	170.00 ✓
68	front door inner lock	11	560.00	560.00	560.00 ✓
69	rear door RH	11	1280.00	1280.00	1,280.00 ✓
70	rear door black sticker RH	1 set	46.40	46.40	46.40 ✓
71	rear transparent water proof plastic RH	11	85.00	85.00	85.00 ✓
72	rear door w/strip rubber	11	195.00	195.00	195.00 ✓
73	rear fender RH	11	955.00	955.00	955.00 ✓
74	rear fender inner cowling	11	75.00	75.00	75.00 ✓
75	rear fender inner cowling clip RH	11	5.00	5.00	10.00 ✓
76	front fender inner cowling clip	160	5.00	5.00	80.00 ✓
77	rear lamp assy RH	11	245.00	245.00	245.00 ✓
78	rear boot lamp assy RH	11	195.00	195.00	195.00 ✓
79	rear bumper	11	595.00	595.00	595.00 ✓
80	rear bumper reflector lamp RH	11	58.00	58.00	58.00 ✓
81	rear bumper side retainer RH	11	95.00	95.00	95.00 ✓
82	rear fender 1/4 glass rubber moulding	11	425.00	425.00	425.00 ✓
83	rear fender inner garnish top RH	11	166.00	166.00	166.00 ✓
84	rear fender inner garnish lower RH	11	157.04	157.04	157.04 ✓
85	front roof top air bag L&R	20	2260.32	2260.32	4,520.64 ✓
86	roof top upholstery assy	11	2466.20	2466.20	2,466.20 ✓
87	front steering air bag	11	2960.00	2960.00	2,960.00 ✓
88	front steering air bag sensor	11	715.30	715.30	715.30 ✓
89	front dashboard air bag LH	11	3975.00	3975.00	3,975.00 ✓
90	front dashbord assy	11	1105.50	1105.50	1,105.50 ✓
91	front air bag contril unit	11	599.97	599.97	599.97 ✓
92	front seat belt L&R	20	825.00	825.00	1,650.00 ✓
93	front seat belt tensioner	11	220.00	220.00	220.00 ✓
94	rear bearing with hub RH	11	715.20	715.20	715.20 ✓
95	rear ABS sebsor RH	11	543.90	543.90	543.90 ✓
96	rear shock absorber RH	11	401.51	401.51	401.51 ✓
97	rear centre crossmember	11	2645.00	2645.00	2,645.00 ✓
98	centre crossmember	11	585.00	585.00	585.00 ✓
99	rear exhaust box	11	1010.00	1010.00	1,010.00 ✓

899.10

DD



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
 GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
 E-mail: nphauto@pacific.net.sg



Your Ref :
 Our Ref : TP0062/09/21

Page : 4/5
 Date : 09/09/2021

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total	
		\$	\$	\$	
100 front towing hook chassis bracket	2	185.00	185.00	185.00	X
101 front engine cowling RH	1	120.00	120.00	120.00	/
102 front engine cowling clip	2	5.00	5.00	10.00	/
103 front shock absorber RH	1	401.50	401.50	401.50	/
104 front shock absorber top mounting	1	212.80	212.80	212.80	X
105 front shock absorber top mounting bearing	1	45.00	45.00	45.00	X
106 front knuckle arm RH	1	628.40	628.40	628.40	/
107 front knuckle arm bearing RH	1	167.30	167.30	167.30	/
108 front lower arm RH	1	760.00	760.00	760.00	/
109 front ABS sensor RH	1	543.90	543.90	543.90	X
110 front lower arm ball joint RH	1	238.40	238.40	238.40	/
111 front power steering & rack pinion	1	2044.10	2044.10	2,044.10	/
112 front power steering ball joint	1	186.70	186.70	186.70	X
113 front brake roto	1	492.00	492.00	492.00	X
114 front brake roto plate inner	1	65.00	65.00	65.00	X
115 front drive shaft RH	1	1493.70	1493.70	1,493.70	/
116 front anti-roll-bar	1	395.00	395.00	395.00	/
117 front ainti roll bar link L&R	2	237.10	237.10	474.20	/
118 front power steering lower crossmember	1	2138.00	2138.00	2,138.00	/
119 front engine center crossmember	1	415.00	415.00	415.00	X
120 front power steering crossmember inner bracket joint	1	75.02	75.02	75.02	X
121 front fender lower bracket joint	1	16.10	16.10	16.10	/

75,514.95

-18,878.74

Less 25%

Total Material

\$56,636.21

Special Nett Items

122 front number plate w/casing	1	45.00	45.00	45.00	40
123 front battery	1	180.00	180.00	180.00	80
124 front windscreen sealant	1	40.00	40.00	40.00	/
125 ERP IU bracket	1	20.00	20.00	20.00	12
126 front door rain visior	1 set	320.00	320.00	320.00	100
127 rear fender 1/4 glass sealant L&R	1	35.00	35.00	70.00	X
128 front fender 1/4 glass sealant L&R	1	35.00	35.00	70.00	X
129 sport rims	4	350.00	350.00	1,400.00	3pc
130 tyre	4	230.00	230.00	690.00	100 12
131 brake fluid	1	40.00	40.00	40.00	20
132 coolant	1	50.00	50.00	50.00	30



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0062/09/21

Page : 5/5
Date : 09/09/2021

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total	
		\$	\$	\$	
133 gear oil	11	18	120.00	120.00	X
				3,045.00	
				0.00	
Total S/Nett				\$3,045.00	
Labour & Misc					
1 Remove & install front windscre.				180.00	120
2 Remove & install 1/4 glass L&R.			11	150.00	X
3 Remove & install r/fender 1/4 glass.			11	100.00	X
4 Remove & install f/dashboard assy with console box.				320.00	250
5 Remove & install seat, carpet and roof top upholstery.				280.00	100
6 Remove & install air bag, roof top air bag, steering air bag and air bag control unit.				250.00	✓
7 Reset air bag control unit.				350.00	300
8 Towing fee with bend.				150.00	120
9 Vacuum & top up gas.				100.00	✓
10 Check wiring system and re wiring system.				80.00	50
11 Remove & install rear undercarriage.				280.00	230
12 Remove & install front undercarriage.				350.00	✓
13 Reset wheel camber alignment.				100.00	✓
14 Remove & install f/engine gear box.				280.00	✓
15 Remove & install all the damaged parts, knocking and restraighthen body & chassis.				3,500.00	2400
16 Spray painting.				2,799.00	2000
				9,269.00	

Total Labour

\$9,269.00

Nett Total Before Gst

\$68,950.21

Your faithfully

NPH AUTO SERVICE
(Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To remedy damaged part(s) during survey
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be surveyed and is subject to the approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P -
S.N - 1472
L - 6670

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	528G
Vehicle Details	
Vehicle No.:	SJY4717P
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Sep 2021
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 2.0 AUTO
Primary Colour:	Green
Manufacturing Year:	2010
Engine No.:	3ZRA487980
Chassis No.:	JTDGJ20W705002469
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$22,003.00
Original Registration Date:	06 Sep 2010
First Registration Date:	06 Sep 2010
Transfer Count:	1
Actual ARF Paid:	\$22,003.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2030
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$33,568.00
COE Rebate Amount:	\$29,521.00
Total Rebate Amount:	\$29,521.00

The information contained herein is correct as at 14 Sep 2021

OK

Singapore Reckless Drivers Part X

Unusual or Rare Cars - Part 2

Reckless Cyclist

Post an Advertisement
Sell it yourself. Advertise it at just
\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2017 Hyundai Elantra 1.6A GLS S



1688 Monthly, 1.18% P.A. By Gv
Cars Financing Up To 90% Loan.
No Admin Fees.
Gv Automobile Centre StarAd



Browse by Category

Sort by Date Posted

20 results/page

6 vehicles



toyota wish 2.0 2030

Advanced Search

Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection

toyota wish 2.0 2030

Any

Any

> 10 year(s)

Any

Any

Any

Available



Toyota Wish 2.0A (COE till 01/2030)

\$55,800

\$6,720 /yr

04-Jan-2010

1,987 cc

-

MPV

Available

\$0 Drive Away With Loan Approval Bonus! Very Good Condition! Bank/In-House Loan Available! Very Powerful And Responsive. Spaciou...

PREMIUM AD

Posted: 13-Sep-2021 Tags: 2010 Toyota Wish, Toyota Wish, Toyota, Wish



Toyota Wish 2.0A (COE till 09/2030)

\$62,787

\$6,940 /yr

05-Oct-2010

1,987 cc

152,000 km

MPV

Available

Well Maintained, In Good Condition. High Loan / Trade In Welcome, \$0 Drive-away! 100% Loan Available With Attractive Rates! Call In...

PREMIUM AD

Posted: 11-Sep-2021 Tags: 2010 Toyota Wish, Toyota Wish, Toyota, Wish



Toyota Wish 2.0A (COE till 03/2030)

\$59,800

\$7,040 /yr

12-Mar-2010

1,987 cc

-

MPV

Available

Full Loan Available! We Are sgCarMart Premium Dealer! Buy With Confidence! In House Loan Or Bank Loan Available! Fast And Easy Loa...

PREMIUM AD

88 Motor Trading

Posted: 11-Sep-2021 Tags: 2010 Toyota Wish, Toyota Wish, Toyota, Wish



Toyota Wish 2.0A (COE till 01/2030)

\$58,800

\$7,030 /yr

25-Jan-2010

1,987 cc

150,000 km

MPV

Available

Full Loan Available! We Are sgCarMart Premium Dealer! Buy With Confidence! In House Loan Or Bank Loan Available! Fast And Easy Loa...

88 Motor Trading

Posted: 11-Sep-2021 Tags: 2010 Toyota Wish, Toyota Wish, Toyota, Wish



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Wish 2.0A (COE till 08/2030)

\$64,000

\$7,140 /yr

30-Aug-2010

1,987 cc

181,000 km

MPV

Available

Very Well Maintained MPV Unit. Fuel Efficient With Spacious Legroom For Passengers. Wear & Tears Replaced Accordingly. Free Servic...

PREMIUM AD

Posted: 24-Aug-2021 Tags: 2010 Toyota Wish, Toyota Wish, Toyota, Wish



Toyota Wish 2.0A (COE till 02/2030)

\$63,500

\$7,550 /yr

08-Feb-2010

1,987 cc

141,552 km

MPV

Available

Very Well Maintained MPV Unit. Fuel Efficient With Spacious Legroom For Passengers. Wear And Tears Replaced Accordingly. Free Servi...

CONSIGNMENT

Posted: 20-Aug-2021 Tags: 2010 Toyota Wish, Toyota Wish, Toyota, Wish

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Compare

1, view Expired ads

20 results/page



CASH SALE/WORK ORDER

NO. 41887

東方拖車服務 ORIENTAL AUTOMOTIVE CENTRE

Regn. No: 50727900W

Blk 405 Ang Mo Kio Ave 10 #03-683 Singapore 560405

H/P : 9833 6132

24 HOURS TOWING SERVICES

Date. 6-9-21

宝号

Messrs

车号

Vehicle No.

由

From

时间(日/夜)

Time (day/night)

其他

Other

车型

Model No.

到

To

CASH \$

CHEQUE

注意：本公司对所拖之车辆，在进行中如有任何损失或破坏，一概由车主自行负责。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damage or other misdemeanor to your vehicle whilst being towed.

经手人

Authorised by

收货人

Received by

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/09/2021 17:14 (SGT)
Date of Accident	06/09/2021 18:10 (SGT)
Exact Location of Accident	SLE, Singapore
Additional Location Information	SELETAR EXPRESSWAY
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY4717P
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ZHUANG SHIRONG
NRIC No	SXXXX528G
Email Address	TERRY22R82@GMAIL.COM
Mobile Phone No	(Phone) +65-93399287
Alternative Phone No	(Home) +65-93399287

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Wish
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5117735284-01
Cover Note Number	-

DRIVER

Name of Driver	ZHUANG SHIRONG
NRIC No	SXXXX528G

Date Of Birth	10/11/1982
Occupation	Indoor
Date Of Driving Pass	02/10/2009
Driving experience	11 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93399287
Alt. Phone Number	(Home) +65-93399287
Email Address	TERRY22R82@GMAIL.COM
Address	BLK 608B TAMPINES NORTH DR 1
Address complement	#06-316
Postcode	522608
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Tampines Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18005871999
Alt. Police Station Phone No	(Fax) +65-65871699
Police Station Address	6 Tampines Ave 4 Singapore 529682
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

AS PER POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	NOT AVAILABLE
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMT1661B
Vehicle Manufacturer	Toyota
Vehicle Model	Sienta
Vehicle Variant	-
Vehicle Colour	-

Vehicle Category	Private car
Name of Driver	LOKE ZHI YONG
NRIC No	SXXXX011J
Contact Number	(Phone) +65-94872872
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	ZHUANG ZHIRONG
Gender	Male
Phone No	(Phone) +65-93399287
Address	BLK 608B TAMPNES NORTH DR 1
Address Complement	#06-316
Post Code	522608
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SJY4717P
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

IMPORTANT NOTICE

Witnessed by Reporting Centre
Personnel

Sketch Plan

⑤ SMP1661B

2



① 324 4717P

4

3

2

Lane

On date 6th Sept at 10:00 hrs estmally I was driving along JLE towards
TPE at Lenter Phover. I was driving straight in Lane 3. Suddenly
a Car SMT1661B in Lane 4 - On my left hand cut into my lane
and collide with my car causing my car to shift & cut to lane 1
and hit the safety barrier.


I was driving normally on my lane as shown in my Car Camera
footage. I wish to declare that the abrupt collision from SMT1661B
into my car was a huge impact from his dangerous driving
and swing to my lane.

Immediately, there was 2 touts who came over to push
me to go to their workshop and I suspected that they
might be involved in the accident. They have hand me their Name Card
- Jay Lin. & Transwork garage.
I suffered injuries on my shoulder, Neck and leg.

I was driving alone in my car and it was not running.

Declaration

I/We declare the foregoing particulars are true in every respect

 07th Sept.
Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel



Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/09/2021 16:19	Vide Report No.:	Station Diary No.: 33
--	------------------	--------------------------

Informant's Particulars

Name of Informant: ZHUANG ZHIRONG			Address: APT BLK 608B TAMPINES NORTH DRIVE 1 #06-316 SINGAPORE 522608		
ID Type / ID No.: NRIC NO / S8237528G			Contact No.: Home/Office: Mobile: 93399287		
Nationality: SINGAPORE CITIZEN			Email: terryzr82@gmail.com		
Sex: Male	Age: 38	Date of Birth: 10/11/1982	Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: OPERATIONS MANAGER			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 06/09/2021 18:10	Type of Location: Straight Road
Location: SELETAR EXPRESSWAY				
Weather: Sunny		Road Surface: Dry	Road Speed Limit: 90 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJY4717P	Car	TOYOTA	WISH 2.0 AUTO	Green	Seriously Damaged	0
SMT1661B	Car	TOYOTA	SIENNA HYBRID 1.5	Silver	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJY4717P	NTUC Income Insurance Co-Operative Limited	5117735284-01	06/09/2021	05/09/2022



**SINGAPORE
POLICE FORCE**



T/20210907/2075

2 of 3

Report No. T/20210907/2075

Police Station Of Origin:

Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999

CONTINUATION OF REPORT

Brief Details.

On 06/09/2021 @ 6:09pm I was driving along SLE towards TPE at a travelling speed of about 70km/h and just slightly after Exit 3 a car collided onto my left side near the passenger door. I then lost control and swerved from lane 3 to lane 1 and my car crashed into the divider. I became unconscious for a moment until I opened my eyes and tried to exit my car as I saw smoke coming out of my hood. The door on my side was unable to open due to it being block by the divider and I quickly got out of my car from the passenger side. I then called 999 for assistance, however they mentioned that since there was no serious injuries they would not dispatch any traffic police to scene and instead an LTA Office came to scene to assist me.

Afterwards some other drivers came forward to check on my however I mentioned that I was ok and do not need their help. EMAS then came and towed my vehicle to the road shoulder. I had met up with the other party (Loke Zhi Yong HP: 94872872). We then headed to Ang Mo Kio Industrial Park to check on my vehicle. We then exchanged particulars there and he headed off as he was rushing and told me to do insurance claims.

I then saw a doctor on the next day and had attained a 3 day MC from 07/09/2021-09/09/2021 as I suffered from some abrasions and soreness in my neck.

I am making this police report for insurance claims against the other party for dangerous driving and swerving to my lane.



Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

3 of 3

Report No. T/20210907/2075

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report
G /

Sgt 2 DARREN LAM KANG JUN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
07/09/2021 16:19

Officer In Charge Of Case:

TP / AEIT /
SI TAN JEOK LENG
Contact No.: 65476151

Classification Of Case:



SINGAPORE
POLICE FORCE

Authentication Stamp
NP168

SIGNATURE