

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21009522/AGA3Q2
Date: 29/03/2022

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210054941
Claimant Vehicle No :	SNB8999P	Insured Vehicle No :	SGT7800Z
Date of Loss:	19/08/2021	Nature of Claim:	TP
		Claim No:	9569035353SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB8999P	Engine No:	27492030371393
Make & Model:	MERCEDES-BENZ E200, 2.0 SEDAN (R17) (A)	Chassis No:	WDD2120342B146153
Reg. Date:	18/06/2015 (Man. Year: 2015)	Odometer:	57235 km
Colour:	Silver		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,529.00	3,942.60	6,586.40	62.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,520.00	1,280.00	45.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,329.00	5,462.60	7,866.40	59.02
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	13,329.00	4,300.00	9,029.00	67.74
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
Nett Liability (S\$)		4,800.00		

INSPECTION

Date of Assignment:	19/08/2021	
Date Inspected:	19/08/2021 Inspected At:	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,668.00 F	*1,668.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
3	2		*REAR BUMPER SIDE HOLDER	Not Necessary	190.00 F	*- FL
4	1		*REAR BUMPER LOWER GARNISH	Cut	369.00 F	*369.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	765.00 F	*765.00 FL
6	1		*REAR BUMPER HANDS FREE SENSOR BRACKET	Cracked	194.00 F	*194.00 FL
7	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	1,020.00 F	*510.00 FL
8	1		*REAR END PANEL	Repair	1,215.00 F	*- FL
9	1		*REAR END PANEL TOP GARNISH	Cracked	245.00 F	*245.00 FL
10	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	10.00 FS	*10.00 FS
11	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
12	1		*TAILLAMP	SERVICEABLE	1,370.00 F	*- FL
13	1		*BOOTLID	Repair	2,470.00 F	*- FL
14	1		*BOOTLID LOCK	Not Necessary	340.00 F	*- FL
15	1		*BOOTLID WEATHERSTRIP	Cut	268.00 F	*268.00 FL
16	1		*MERCEDES BENZ LOGO	Necessary	75.00 F	*75.00 FL
17	1		*E200 WORDING	Necessary	85.00 F	*85.00 FL
18	1		*CYCLE AND CARRIAGE LOGO	Necessary	45.00 F	*45.00 FL
19	1		*7G TRONIC WORDING	Necessary	90.00 F	*90.00 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	10,529.00	4,374.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	431.40
Total Parts (S\$)	10,529.00	3,942.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING	New	1,000.00	750.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	60.00
5	TO SPRAY TUFF COAT	New	150.00	40.00
6	TO REMOVE UPHOLSTERY	New	150.00	40.00
7	TO TRANSFER BOOTLID FITTINGS	New	150.00	0.00
Gross Labour Cost (S\$)			2,800.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >