



UT
RC
E

KIEN CHEONG AUTOMOTIVE

BLK 9 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-26 SINGAPORE 575644

H/P : 8125 9406 FAX : 64550902

The Motor Claims Dept.

India International Insurance Pte Ltd
(LKK)

Not Authorized
61 Day @ 2300

DATE : 13/9/2021

VEHICLE NO : SJQ 5107K

MAKE/MODEL : Hyundai Avante

ACC DATE : 4/9/2021

Painting After Rain
4 days

ESTIMATE

Page . 1 .

S/N	LIST ITEMS:	AMOUNT S\$
1	1 Rear bumper	<i>Re</i> 484.00 ✓
2	2 Rear bumper side retainer @\$48	<i>Re</i> 96.00 X
3	1 Rear bumper beam	<i>CM</i> 215.80 ✓
4	2 Rear LH tail lamp @\$298	<i>Re</i> 596.00 X
5	1 Rear Tailgate <i>851</i>	<i>Re</i> 1,391.00 ✓
6	1 Rear tailgate logo	<i>Re</i> 56.50 ✓
7	1 Rear tailgate emblem 'Aventa'	<i>Re</i> 48.50 ✓
8	1 Rear tailgate emblem 'S'	<i>Re</i> 24.60 ✓
9	1 Rear tailgate inner lock	<i>Re</i> 85.40 ✓
		2,997.80
	Less 20%	(599.56)
	List Item:	2,398.24
		<i>Re</i> 50.00 ✓
		<i>Ref/1st</i> 200.00 ✓
	Special Item:	250.00
		90.00 <i>501</i>
		50.00 <i>151</i>
		120.00 <i>501</i>
		150.00 <i>301</i>
		1,000.00 <i>5001</i>
		800.00 <i>6001</i>
		2,210.00
	Total Repair Cost	4,858.24

(S/D : Four Thousand Eight Hundred Fity-eight and Cents Twenty-four only.)



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: