| 14 | < | 1 | of 2 ? | > | Þ١ | Ö | <b>©</b> | 100% | ~ |  | d<br>d | Find   Next |
|----|---|---|--------|---|----|---|----------|------|---|--|--------|-------------|
|----|---|---|--------|---|----|---|----------|------|---|--|--------|-------------|



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

|     |                     | Affiliated to Federation Internation   | nale Des Experts En A | Automob | ile                  |  |  |
|-----|---------------------|--|-----------------------|---------|----------------------|--|--|
|     | LONPAC INSURAN      | NCE BHD  | -                     | Ref:    | CS3/LPC21009526/Vtf3 |  |  |
|     | 300 BEACH ROAD      | )  |                       | Date:   | 10/09/2021           |  |  |
|     | #17-04/07 THE CC    | NCOURSESINGAPORE 199555  |                       |         |                      |  |  |
|     |                     |  |                       | Code:   |                      |  |  |
| 1.  |                     | CLAIM  |                       |         |                      |  |  |
|     | Insured Veh.        | 5025S  | Veh. Inspected        |         | FBH 2962U            |  |  |
|     | Policy No.          |  | Coverage (\$)         |         | 0.00                 |  |  |
|     | Claim No.           | 20/21/21/VC40/024928   | Excess (\$)           |         | 0.00                 |  |  |
|     | Assign From         | ONG LI LI  | Assign Date           |         | 10/09/2021           |  |  |
| 2.  |                     | Vehicle Partic   | ulars & Conditio      | n       |                      |  |  |
|     | Make & Model        |  | c.c                   |         | 0                    |  |  |
|     | Engine No.          | HIDDEN   | Year of Reg.          |         |                      |  |  |
|     | Chassis No.         |  | Colour                |         |                      |  |  |
|     | Odometer            | Steering   |                       |         |                      |  |  |
|     | Brakes              |  | Modification          |         |                      |  |  |
|     | General             |  |                       |         |                      |  |  |
| 3.  |                     | Condition  | ons of Tyres          |         |                      |  |  |
|     |                     | Size   | Make                  |         | Balance              |  |  |
|     | R/H Front Tyre      |  |                       |         | mm                   |  |  |
|     | L/H Front Tyre      |  |                       |         | mm                   |  |  |
|     | R/H Rear Tyre       |  |                       |         | mm                   |  |  |
|     | L/H Rear Tyre       |  |                       |         | mm                   |  |  |
| 4.  |                     | Description  | on of Damages         |         |                      |  |  |
|     |                     |  |                       |         |                      |  |  |
| 5.  | General Information |  |                       |         |                      |  |  |
|     | Accident Date       | 06/09/2021   | Inspection Date       | 9       | 10/09/2021           |  |  |
|     | Survey held at      | EQUATOR BROTHERHOOD  |                       |         |                      |  |  |
|     |                     | 25 KAKI BUKIT ROAD 4<br>#03-19 SYNERGY @KB<br>SINGAPORE 417800   |                       |         |                      |  |  |
| 5a. | · ·                 | Remarks  |                       |         |                      |  |  |
|     | B) THE REPAIR ES    | ON WAS CONDUCTED ON A "WI<br>STIMATE WAS NOT PRESENTED<br>/AS TOLD TO PREPARE THE ES'<br>EASE FIND DAMAGED VEHICLE | AT THE TIME OF I      |         |                      |  |  |

|    | LONPAC INSURAN                            | NCE BHD                      |                    | Ref:  | CS3/LPC21009526/Vtf3 |  |  |  |
|----|---|------------------------------|--------------------|-------|----------------------|--|--|--|
|    | 300 BEACH ROAD<br>#17-04/07 THE CO        | )<br>NCOURSESINGAPORE 199555 |                    | Date: | 10/09/2021           |  |  |  |
|    |   |                              |                    | Code: | LPC2                 |  |  |  |
| 1. | Policy Particulars :- (THIRD PARTY CLAIM) |                              |                    |       |                      |  |  |  |
|    | Insured Veh.                              | 5025S                        | Veh. Inspected     | t     | FBH 2962U            |  |  |  |
|    | Policy No.                                |                              | Coverage (\$)      |       | 0.00                 |  |  |  |
|    | Claim No.                                 | 20/21/21/VC40/024928         | Excess (\$)        |       | 0.00                 |  |  |  |
|    | Assign From                               | ONG LI LI                    | Assign Date        |       | 10/09/2021           |  |  |  |
| 2. | 1   | Vehicle Partic               | culars & Condition |       |                      |  |  |  |
|    | Make & Model                              |                              | c.c                |       | 0                    |  |  |  |
|    | Engine No.                                | HIDDEN                       | Year of Reg.       |       |                      |  |  |  |
|    | Chassis No.                               |                              | Colour             |       |                      |  |  |  |
|    | Odometer                                  | =                            | Steering           |       |                      |  |  |  |
|    | Brakes                                    |                              | Modification       |       |                      |  |  |  |
|    | General                                   |                              |                    |       |                      |  |  |  |
| 3. | •   | Condition                    | ons of Tyres       |       |                      |  |  |  |
|    |   | Size                         | Make               |       | Balance              |  |  |  |
|    | R/H Front Tyre                            |                              |                    |       | mm                   |  |  |  |
|    | L/H Front Tyre                            |                              |                    |       | mm                   |  |  |  |
|    | R/H Rear Tyre                             |                              |                    |       | mm                   |  |  |  |
|    | L/H Rear Tyre                             |                              |                    |       | mm                   |  |  |  |
| 4. | •   | Description                  | n of Damages       |       | •                    |  |  |  |
|    |   |                              |                    |       |                      |  |  |  |
| 5. | -   | General                      | Information        |       |                      |  |  |  |
|    | 1   |                              | 1                  |       |                      |  |  |  |

9/10/21, 3:48 PM https://views.init.com.sg/report/reportserver? Report=LKKInspection & From = 339691 & rs: Command = Render & rc: Parameters = fa... + fa...

| 1   | Accident Date   | 06/09/2021   | Inspection Date | 10/09/2021 |  |  |  |
|-----|---|--|-----------------|------------|--|--|--|
|     | Survey held at  | EQUATOR BROTHERHOOD  |                 |            |  |  |  |
|     |   | 25 KAKI BUKIT ROAD 4<br>#03-19 SYNERGY @KB<br>SINGAPORE 417800 |                 |            |  |  |  |
| 5a. | Remarks   |  |                 |            |  |  |  |
|     | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |  |                 |            |  |  |  |