



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 1

Vehicle No. SJN5558H HYUNDIA AVANTE

Vehicle No.		SUN5558H HYUNDA AVANTE		
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Rear door RH / 00	Part Items Total: nn	1000.00	947 /
1	Rear door outer handle long RH x R		65.00	
1	Rear door outer handle small RH x R		22.00	
1	Rear fender RH / 00		1207.00	
1	Rear bumper x R		450.00	
1	Rear bumper side retainer LH/RH @2*\$35 x R		70.00	
			2814.00	
			-20% -562.80	
			2251.20	
<u>SPECIAL NETT ITEMS</u>				
1	Rear bumper clips x nn		35.00	40
1	Rear fender shield clips RH x nn		25.00	
1	Rear windscreen sealant - MC		60.00	
1	Rear fender sealant RH - MC		60.00	
1	Rear rim 15 inch RH - CUT		680.00	
SN Items Total:			860.00	
Total Parts			3111.20	250

2154
-20%
1723.20

LKK Auto Consultants hence notify the Repairer of the following:

- To securely before/after spray painting
- To display damaged part(s) during survey
- Part, necessary to be confirmed
- Third party vehicle on a "without prejudice" basis
- No illegal modification(s) to vehicle
- Supplementary item(s) must be surveyed and subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg
(199806235M)

Page No. 2

Vehicle No. SJN5558H HYUNDIA AVANTE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	700
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	600
3	To perform anti-rust treatment on affected areas	60.00	30
4	Check and wheel computerize alignment	80.00	60
5	To remove and refix front tyre and wheel balancing in order to rear rim LH	50.00	20
6	To remove and replace rear door RH fitting, trimmings, garnish, window glass and mechanism	100.00	50
7	To remove and replace rear windscreen	120.00	
8	To remove and refit rear seat in order to repair	100.00	50
9	To remove and refit/replace roots lining & upholster garnish	100.00	50
10	To remove and replace rear quarter glass RH	100.00	50
Labour Total :		2310.00	
TOTAL (PARTS & LABOUR):		5421.20	1730

P-1723.20

N-320

L-1730

3773.20

L/S-3918.56

= 3099

Steve (LKK)

13/9/11, 330pm

HL PL

L/S

My AL sy
7 days