

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG. NO. : 201316380R

Vehicle Number : JGJ 4651

Date : 13.09.2021

Vehicle Model : YAMAHA RXZ

Chassis : ZMC-263059

Accident Date : 30.08.2021

TP Ins.

CHINA TAIPING

Original Reg Date : 02.01.2002

ESTIMATE

1	2 pcs	Front Wing Mirror	82.00	cut	164.00
2	2 pcs	Handle Bar Assy	125.00	bt	250.00
3	2 pcs	Handle Bar Holder Rubber	56.00	cut	112.00
4	2 pcs	Handle Bar Holder Joint	16.00	cut	32.00
5	1 pc	Hand Brake Lever RH		cut	55.00
6	1 pc	Hand Clutch Lever LH		cut	55.00
7	1 pc	Hand Clutch Lever Cable LH		bt	85.00
8	1 pc	Brake Pump Assy		cut	255.00
9	1 pc	Brake Pump Pipe		cut	85.00
10	1 set	Front Horn		bt	120.00
11	1 set	Meter Assy		cut	460.00
12	1 pc	Meter Cable		cut	92.00
13	1 pc	Headlamp Assy		cut	290.00
14	1 pc	Headlamp Switch Assy		cut	165.00
15	2 pcs	Front Side Lamps	89.00	cut	178.00
16	1 pc	Front Cowling		cut	192.00
17	1 pc	Front Cowling Outer Garnish Cover		cut	115.00
18	1 set	Front Cowling Bracket		bt	106.00
19	1 pc	Front Fender		cut	149.00
20	2 pcs	Front Forks Assy	300 452.00	cut	904.00
21	1 pc	Front Fork Center Bracket		cut	136.00
22	1 pc	Front Fork Top Bracket		cut	159.00
23	2 pcs	Front Fork Wheel Bearing	90.00	cut	180.00
24	1 pc	Front Wheel Bearing Shaft		cut	125.00
25	1 pc	Front Brake Disc		cut	365.00
26	1 pc	Front Brake Caliper		cut	412.00
27	1 set	Front Brake Pad		cut	50.00
28	1 pc	Rear Exhaust Pipe		cut	325.00
29	1 pc	Side Stand LH		cut	105.00
30	1 pc	Foot Brake Level RH		bt	92.00

C/F

5,813.00

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG. NO. : 201316380R

Vehicle No : JGJ 4651

B/F

5,813.00

1	1 pc	Starter Bar RH		bb ✓	125.00
2	1 pc	Starter Bar Triangle Bracket Bolt		BB X	118.00
3	1 pc	Rear Side Body Cowling Cover RH		Am ✓	265.00

6,221.00

4388

Less 10% 622.10

5,598.90

3949.20

Special Nett

1	1 btl	Front Fork Assy Oil		Xun	50.00
2	1 set	Body Cowling Sticker	nec	120.	220.00
3	1 pc	Rear Number Plate	Bt	✓	12.00
4	1 btl	Engine Oil		Xun	80.00
5	1 pc	Rear Luggage Box		cut	400.00
6	1 pc	Starter Bar Triangle Bracket Bolt		bb ✓	20.00

350.

502.

Labour charge

Panel Beating		250.	700.00
Spray painting		300.	600.00
Check Wiring		✓	20.00
Remove and install front and rear under carriage		120.	250.00
Remove and install exhaust pipe		40	80.00
To jack and align body chassis frame	200	plumb?	500.00

8,530.90

730.

Less 20% 1,706.18

Lump sum 6,824.72

Tanpin 92495749

WP' 14/9/21 E 3pm

LB Resurvey after repair

tanpin C Khantun

06 days

3949.20

502

730

5181.20

20% 4144.96

Repair limit \$2900

Page 2 of 2

4542900, 06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: