



24 Peshurst Place, Singapore 556440  
Email: [clappraiser@yahoo.com](mailto:clappraiser@yahoo.com) Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## INVOICE

Terng Boh Chai  
C/o: 889 Car Servicing Pte Ltd  
10 Kaki Bukit Road 2 #03-34  
First East Centre, Singapore 417868

Invoice No: CL/191438  
Ref No: 889/11/1901/TP  
Date: 3 December 2019

DESCRIPTION	AMOUNT
<b>OUR SERVICE FEE CHARGES:</b>	
<ul style="list-style-type: none"><li>SURVEY INSPECTION FOR VEHICLE NO. <u>SGV 4868 M</u></li><li>RESURVEY INSPECTION</li><li>DIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)</li><li>TRANSPORTATION</li></ul>	
<b>GRAND TOTAL</b>	<b>S\$ 737.00</b>

E & O. E

All cheque payment should be "Crossed" and made payable to "CL APPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

# CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440  
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Terng Boh Chai  
C/o: 889 Car Servicing Pte Ltd  
10 Kaki Bukit Road 2 #03-34  
First East Centre, Singapore 417868

Date : 3 December 2019  
Our ref : 889/11/1901/TP

Accident Date : 15 November 2019  
Inspection Date : 20 November 2019  
Repairer Name : 889 Car Servicing Pte Ltd  
10 Kaki Bukit Road 2 #03-34  
First East Centre, Singapore 417868

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

Registration No : SGV 4868 M  
Make / Model : BMW 523i  
Chassis No : WBANU120X0CW23148  
Engine No : 78184000N52B25AE

Year / Capacity : 2007 / 2497 cc  
Colour : Silver  
Mileage : 132647

### CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Continental	225/50 R17	5 mm	Sport
Front Offside	: Continental	225/50 R17	5 mm	Sport
Rear Nearside	: Continental	225/50 R17	5 mm	Sport
Rear Offside	: Continental	225/50 R17	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the o/s portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: 67 copies

### REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis  
and we have not given authorization and instruction to the repairer to proceed with the repair

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle  
and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 10,400.00** on a contractual basis.

Under normal circumstances, the repair period would be about 8 (Eight) working days.

Vehicle Registration No: SGV 4868 M

Our Ref No: 889/11/1901/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

**SPARE PARTS - LIST ITEMS**

1	Front o/s door	Damage	\$ 1,605.00	\$ 1,605.00
1	Front o/s door outer handle	Damage	\$ 133.00	\$ 133.00
1	Front o/s door rubber	Necessary	\$ 197.00	\$ 197.00
1	Front o/s door side mirror	Repair	\$ 1,212.00	
1	O/s rocker panel side skirt	Repair	\$ 850.00	
1	Rear o/s door	Damage	\$ 1,655.00	\$ 1,655.00
1	Rear o/s door inner lock	Damage	\$ 295.00	\$ 295.00
1	Rear o/s door outer handle	Damage	\$ 239.00	\$ 239.00
1	Rear door regulator	Damage	\$ 345.00	\$ 345.00
1	Rear door regulator motor	Damage	\$ 305.00	\$ 305.00
1	Rear o/s door rubber	Necessary	\$ 197.00	\$ 197.00
1	Rear windscreen moulding	Necessary	\$ 263.10	\$ 263.10
1	Rear bumper	Damage	\$ 1,495.00	\$ 1,495.00
1	Rear bumper side retainer	Necessary	\$ 139.95	\$ 139.95
1	Rear o/s fender	Damage	\$ 1,550.00	\$ 1,550.00
1	Rear o/s alloy wheel rim	Damage	\$ 1,274.70	\$ 1,274.70
			<b>\$ 11,755.75</b>	<b>\$ 9,693.75</b>
			<i>Less 5%</i>	<i>\$ 587.79</i>
<b>Total Cost - List Items</b>			<b>\$ 11,167.96</b>	<b>\$ 9,209.06</b>

**SPECIAL NETT ITEMS**

1	Rear windscreen sealant	Necessary	\$ 80.00	\$ 50.00
1	Rear bumper clip ( 1set )	Necessary	\$ 60.00	\$ 60.00
1	Rear tyre ( Deprecation )	Damage	\$ 400.00	\$ 200.00
<b>Total Cost - Special Nett items</b>			<b>\$ 540.00</b>	<b>\$ 310.00</b>

**Total cost of parts**
**\$ 11,707.96 \$ 9,519.06**

Vehicle Registration No: SGV 4868 M

Our Ref No: 889/11/1901/TP

S/No	Description	Repairer's Estimate	Revised Amount
<b>Total cost of parts c/f</b>		<b>\$ 11,707.96</b>	<b>\$ 9,519.06</b>
<b><u>LABOUR</u></b>			
1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00
3	To remove and refit fuel tank assembly with all attachments, pipe and hoses.	\$ 150.00	\$ 120.00
4	To conduct wheel alignment.	\$ 150.00	\$ 150.00
5	To remove and refit rear windscreen glass.	\$ 180.00	\$ 120.00
6	To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$ 300.00	\$ 240.00
7	To apply undercoating on repaired and replaced panel.	\$ 180.00	\$ 120.00
8	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,500.00	\$ 1,250.00
9	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,600.00	\$ 1,320.00
<b>GRAND TOTAL</b>		<b>\$ 15,997.96</b>	<b>\$ 13,009.06</b>

Vehicle Registration No: SGV 4868 M

Our Ref No: 889/11/1901/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 10,400.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

**Disclaimer**

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

**CL APPRAISER PTE LTD**



---

Cheong K. H  
Automotive Appraiser