

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009538/AES3Q2**Date:** 11/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210031917
Claimant Vehicle No :	SLV2143A	Insured Vehicle No :	SMY8618E
Date of Loss:	10/09/2021	Nature of Claim:	TP
		Claim No:	6948354086SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV2143A	Engine No:	1NZX965505
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305129122
Reg. Date:	21/10/2009 (Man. Year: 2009)	Odometer:	199315 km
Colour:	Grey		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,115.95	11,116.00	3,999.95	26.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,520.00	3,520.00	2,000.00	36.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,635.95	14,636.00	5,999.95	29.08
Approved Total (Overridden) (S\$)		11,700.00		
(S\$)	20,635.95	11,700.00	8,935.95	43.30
+ GST 7.00/7.00% (S\$)	1,444.52	819.00	625.52	43.30
Nett Amount (S\$)	22,080.47	12,519.00	9,561.47	43.30
+ Loss of Use (13.0 x S\$60.00/day) (S\$)		780.00		
(S\$)		13,299.00		
Liabe Amount (50.00%) (S\$)		6,649.50		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,651.50		
Global Sum Settlement (S\$)		6,650.00		

INSPECTION

Date of Assignment:	10/09/2021	
Date Inspected:	10/09/2021	Inspected At: Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	11.0 days	

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	481.30 FL	*481.30 FL
2	1		*FRONT BUMPER SIDE HOLDER -LH & RH	N/S Damaged	133.40 FL	*66.70 FL
3	1		*FRONT BUMPER REINFORCEMENT	Dented	361.90 FL	*361.90 FL
4	1		*FRONT BUMPER REINFORCEMENT BRACKET -LH & RH	N/S Dented	462.80 FL	*231.40 FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	138.50 FL	*- FL
6	1		*FRONT BUMPER LOGO	Necessary	65.10 FL	*65.10 FL
7	2		*FRONT BUMPER FOG LAMP -LH & RH	Not Necessary	698.00 FL	*- FL
8	1		*FRONT BUMPER FOG LAMP COVER -LH & RH	N/S Cracked	157.80 FL	*78.90 FL
9	1		*FRONT BUMPER INNER TOP BRACKET	Cracked	258.80 FL	*258.80 FL
10	1		*FRONT GRILLE	Cracked	320.10 FL	*320.10 FL
11	1		*FRONT GRILLE OUTER MOULDING	Cracked	89.90 FL	*89.90 FL
12	1		*HEAD LAMP -LH & RH	N/S Cracked	916.00 FL	*458.00 FL
13	1		*HEAD LAMP TOP PANEL -LH & RH	N/S Bent	194.40 FL	*97.20 FL
14	1		*FRONT SUPPORT PANEL	Buckled	788.60 FL	*788.60 FL
15	1		*AIR CON CONDENSER	Dented	1,069.50 FL	*1,069.50 FL
16	1		*AIR CON CONDENSER GUIDE -LH & RH	N/S Deformed	170.40 FL	*85.20 FL
17	1		*RADIATOR	Not Necessary	1,606.70 FL	*- FL
18	1		*RADIATOR FAN COWLING	Not Necessary	235.00 FL	*- FL
19	1		*RADIATOR FAN BLADE	Not Necessary	169.70 FL	*- FL
20	1		*RADIATOR FAN MOTOR	Not Necessary	381.70 FL	*- FL
21	1		*BONNET	Repair	589.80 FL	*- FL
22	1		*BONNET LOCK	Not Necessary	101.20 FL	*- FL
23	2		*BONNET HINGES -LH & RH	Not Necessary	128.60 FL	*- FL
24	1		*FRONT FENDER -LH	Buckled	561.30 FL	*561.30 FL
25	1		*FRONT FENDER INNER SHIELD -LH	Torn	128.50 FL	*128.50 FL
26	1		*FRONT FENDER BRACKET -LH	Bent	60.20 FL	*60.20 FL
27	1		*FRONT FENDER QUARTER GARNISH -LH	Missing	48.60 FL	*48.60 FL
28	1		*AIR CLEANER BOX	Cracked	725.30 FL	*725.30 FL
29	1		*STEERING AIR BAG	Activated	1,655.10 FL	*1,655.10 FL
30	1		*STEERING AIR BAG SENSOR	Activated	322.40 FL	*322.40 FL
31	1		*STEERING WHEEL CLOCK SPRING	Activated	497.20 FL	*497.20 FL
32	1		*DASHBOARD	Torn	989.40 FL	*989.40 FL
33	1		*DASHBOARD AIR BAG	Activated	2,120.10 FL	*2,120.10 FL
34	1		*DASHBOARD AIR BAG SENSOR	Activated	322.40 FL	*322.40 FL
35	2		*SEAT BELT -LH & RH	Activated	1,489.20 FL	*1,489.20 FL
36	1		*AIR BAG ECU	Activated	635.70 FL	*635.70 FL
37	1		*FRONT NUMBER PLATE	Missing	30.00 FS	*30.00 FS
38	1		*FRONT NUMBER PLATE HOLDER	Cracked	30.00 FS	*30.00 FS
39	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
40	1		*FRONT BUMPER LOWER DIFFUSER	Deformed	600.00 FS	*400.00 FS
41	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
42	1		*AIR CON CONDENSER GUIDE CLIPS	Necessary	20.00 FS	*20.00 FS
43	1		*COOLANT	Necessary	50.00 FS	*50.00 FS
44	1		*FRONT FENDER INNER SHIELD CLIPS -LH	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,884.60	14,618.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,768.65	3,502.00
Total Parts (\$\$)	15,115.95	11,116.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT FRONT PORTION & RENEW ABOVE PARTS	New	1,800.00	1,200.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,800.00	1,100.00
3	TO CHECK WIRING	New	100.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	60.00
5	TO REMOVE CONDENSER AND TO TOP UP AIR CON GAS	New	120.00	60.00
6	TO REMOVE RADIATOR AND TO TOP UP COOLANT	New	120.00	60.00
7	TO REMOVE DASHBOARD	New	300.00	220.00
8	TO REPLACE DASHBOARD AIRBAG AND STEERING AIR BAG	New	500.00	350.00
9	TO REMOVE FRONT SEAT BELTS	New	250.00	160.00
10	TO RESET AIR BAG CONFIGURATION	New	380.00	280.00
Gross Labour Cost (\$\$)			5,520.00	3,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >