

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD	Quotation
Charts Building	DATE : 10.09.2021
78 Shenton Way #07-16	VEH NO : SLV2143A
Singapore 079120	MODEL : Toyota Vios
Tel : 6419 - 3000	D O A : 10.09.2021
Fax : 6835 - 7416	YR REF : SMY8618E

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLV2143A (TOYOTA VIOS)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>Distorted</i>	1	481.30 ✓
2	Front Bumper Side Holder - LH & RH <i>LH Damaged</i>	2	133.40 66.70 ✓
3	Front Bumper Reinforcement <i>Dented</i>	1	361.90 ✓
4	Front Bumper Reinforcement Bracket - LH & RH <i>LH Dented</i>	2	462.80 231.40 ✓
5	Front Bumper Lower Grille <i>Nre Nec</i>	1	138.50 x ✓
6	Front Bumper Logo <i>Nec</i>	1	65.10 ✓
7	Front Bumper Fog Lamp - LH & RH <i>Nre Nec</i>	2	698.00 x ✓
8	Front Bumper Fog Lamp Cover - LH & RH <i>LH cracked</i>	2	157.80 78.90 ✓
9	Front Bumper Inner Top Bracket <i>Cracked</i>	1	258.80 ✓
10	Front Grille <i>Cracked</i>	1	320.10 ✓
11	Front Grille Outer Moulding <i>Cracked</i>	1	89.90 ✓
12	Head Lamp - LH & RH <i>LH cracked</i>	2	916.00 458 ✓
13	Head Lamp Top Panel - LH & RH <i>LH Bent</i>	2	194.40 97.20 ✓
14	Front Support Panel <i>Buckled</i>	1	788.60 ✓
15	Air Con Condenser <i>Dented</i>	1	1,069.50 ✓
16	Air Con Condenser Guide - LH & RH <i>LH Deformed</i>	2	170.40 85.20 ✓
17	Radiator	1	1,606.70 x ✓
18	Radiator Fan Cowling <i>Not Nec</i>	1	235.00 x ✓
19	Radiator Fan Blade	1	169.70 x ✓
20	Radiator Fan Motor <i>Nre nec</i>	1	381.70 x ✓
21	Bonnet <i>Reps</i>	1	589.80 x ✓
22	Bonnet Lock <i>Nre nec</i>	1	101.20 x ✓
23	Bonnet Hinges - LH & RH <i>New</i>	2	128.60 x ✓
24	Front Fender - LH <i>Buckled</i>	1	561.30 ✓
25	Front Fender Inner Shield - LH <i>toen</i>	1	128.50 ✓
26	Front Fender Bracket - LH <i>Bent</i>	1	60.20 ✓
27	Front Fender Quarter Garnish - LH <i>Missing</i>	1	48.60 ✓
28	Air Cleaner Box <i>Cracked</i>	1	725.30 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SLV2143A (TOYOTA VIOS)

29	Steering Air Bag	1	1,655.10
30	Steering Air Bag Sensor	1	322.40
31	Steering Wheel Clock Spring	1	497.20
32	Dashboard <i>torn</i>	1	989.40
33	Dashboard Air Bag	1	2,120.10
34	Dashboard Air Bag Sensor	1	322.40
35	Seat Belt - LH & RH	2	1,489.20
36	Air Bag ECU	1	635.70

14008.

10506.

Less 25%
10%

19,074.60

(4,768.65)

\$ 14,305.95

S/NETT ITEMS

1	Front Number Plate <i>Missing</i>	1	\$ 30.00
2	Front Number Plate Holder <i>Cracked</i>	1	\$ 30.00
3	Front Bumper Clips <i>Nec</i>	1	\$ 30.00
4	Front Bumper Lower Diffuser <i>Deformed</i>	1	\$ 600.00 400
5	Front Grille Clips <i>Nec</i>	1	\$ 20.00
6	Air Con Condenser Guide Clips <i>Nec</i>	1	\$ 20.00
7	Coolant <i>Nec</i>	1	\$ 50.00
8	Front Fender Inner Shield Clips - LH <i>Nec</i>	1	\$ 30.00
			\$ 810.00

Total Parts

\$ 15,115.95

LABOUR CHARGE

1	To knocking & pull out front portion & renew above parts	\$ 1,800.00	1200
2	To putty & spray up paint works	\$ 1,800.00	1100
3	To check wiring	\$ 100.00	30
4	To spray tuff coat	\$ 150.00	60
5	To remove condenser and to top up air con gas	\$ 120.00	60
6	To remove radiator and to top up coolant	\$ 120.00	60
7	To remove dashboard	\$ 300.00	220
8	To replace dashboard <i>air bag</i> and steering air bag	\$ 500.00	350
9	To remove front seat belts	\$ 250.00	160

RE : ESTIMATE FOR ACCIDENT REPAIR SLV2143A (TOYOTA VIOS)

10 To reset air bag configuration

\$ 380.00 *280 -*

Total Labour

\$ 5,520.00

Grand Total

\$ 20,635.95

3520

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 14636

h/s : 11.7K.

11 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: