



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 9517U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	PANEL ASSEMBLY-FRONT DOOR,LEFT	DENTED	720.00	720.00
1	WEATHER STRIP-DOOR,OUT LH	NECESSARY	100.80	100.80
1	HANDLE-DOOR,OUTER	NOT NECESSARY	158.40	-
1	RUN CHANNEL-FRONT DOOR,LEFT	NOT NECESSARY	72.00	-
1	WEATHER STRIP-FRONT DOOR,LEFT	NOT NECESSARY	144.00	-
1	WEATHER STRIP-BODY SIDE,FLANGE FRONT	NOT NECESSARY	122.40	-
1	TAPE-FRONT DOOR SASH LEFT	NECESSARY	18.00	18.00
1	TAPE-FRONT DOOR SASH REAR LEFT	NECESSARY	18.00	18.00
1	TAPE-FRONT DOOR,LEFT	NECESSARY	5.40	5.40
1	GLASS ASSEMBLY-FRONT DOOR,LEFT	SCRATCHED	504.00	504.00
1	LAMP ASSEMBLY-SIDE TURN MIRROR,LEFT	SCRATCHED	102.00	102.00
1	DOOR MIRROR UNIT-LEFT	DISTORTED	475.20	475.20
1	COVER-CAP OUT MIRROR,LEFT	TO REPAIR SEE LABOUR	90.00	-
1	COVER-CAP OUT MIRROR,LEFT LOWER	BROKEN	36.00	36.00
1	LED SIDE MIRROR GLASS SET	CRACKED	500.00	500.00
	LESS 20% DISCOUNT		-	-495.88
			3,066.20	1,983.52
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00
<b><u>LABOUR</u></b>				
	REPAIR/REPLACE FRT LH DOOR,LF WING MIRROR & PANEL.INCLUSIVE OF THE REPAIR OF COVER-CAP OUT MIRROR,LEFT.		1,680.00	840.00
	RESPRAY FRT LH DOOR,LF WING MIRROR & PANEL.		1,260.00	630.00
	TRANSFER DOOR MECHANISM (LH FRT).		200.00	200.00
	CONDUCT FAULT DIAGNOSTIC AND RESET SYSTEMS.	NOT NECESSARY	280.00	-
	TO CONDUCT FRONT LIGHTING TEST.	NOT NECESSARY	50.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLY & INSTALL TINTED FILM (FRT LH WINDOW).		145.00	145.00
			3,615.00	1,815.00
GRAND TOTAL			6,781.20	3,818.52
RECOMMENDED COST OF REPAIRS				3,818.52

Report Ref No. CS/SMR21009541/Gqf3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.