



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21009541/Gqf3n2	
			Date: 07/03/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 96T	Veh. Inspected	SLT 9517U
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/09/21/2008	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	10/09/2021
2. Vehicle Particulars & Condition				
	Make & Model	SUBARU FORESTER 2.0I	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JF1SJ5KC5JG099650	Colour	WHITE
	Odometer	66268 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R17	BRIDGESTONE	6 mm
	L/H Front Tyre	205/60 R17	BRIDGESTONE	6 mm
	R/H Rear Tyre	205/60 R17	BRIDGESTONE	6 mm
	L/H Rear Tyre	205/60 R17	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/09/2021	Inspection Date	12/10/2021
	Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 . SINGAPORE 319255		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	