

PO #: QUOTATION:
SLT9517U

Account #: ESTIMATE

Date: 2021-09-07

Dealer Information	Customer Information
Name:	Name:
Address:	Address:
Phone:	Phone:
Fax:	Email:
Contact: FROM:MIE PARTS/MR NG/67038175	Contact:

Vehicle Information

VIN: JF1SJ5KC5JG099650

Vehicle: 2018 > FORESTER(JF1,2) (S13)

Part No.	Description	Qty	Unit Price	Price
60009SG0529P	PANEL ASSEMBLY-FRONT DOOR,LEFT / <i>DD</i>	1	720.00	720.00
61280SG031	WEATHER STRIP-DOOR,OUT LH <i>MEC</i>	1	100.80	100.80
61160FJ010E4	HANDLE-DOOR,OUTER <i>X</i>	1	158.40	158.40
63527SG111	RUN CHANNEL-FRONT DOOR,LEFT <i>X</i>	1	72.00	72.00
63511SG011	WEATHER STRIP-FRONT DOOR,LEFT <i>X</i>	1	144.00	144.00
63571SG001	WEATHER STRIP-BODY SIDE,FLANGE FRONT <i>X</i>	1	122.40	122.40
90422SG030	TAPE-FRONT DOOR SASH LEFT <i>/</i>	1	18.00	18.00
90422SG050	TAPE-FRONT DOOR SASH, REAR LEFT <i>/</i>	1	18.00	18.00
90422SG010	TAPE-FRONT DOOR,LEFT <i>/</i>	1	5.40	5.40
61011SG211	GLASS ASSEMBLY-FRONT DOOR,LEFT <i>/ Set</i>	1	504.00	504.00
84401AJ010	LAMP ASSEMBLY-SIDE TURN MIRROR,LEFT <i>/ Set</i>	1	102.00	102.00
91036SG854	DOOR MIRROR UNIT-LEFT <i>/ Div.</i>	1	475.20	475.20
91059AJ210	COVER-CAP OUT MIRROR,LEFT <i>X Repr</i>	1	90.00	90.00
91054AJ231	COVER-CAP OUT MIRROR,LEFT LOWER <i>/ BR.</i>	1	36.00	36.00
LPHSML-9005	LED SIDE MIRROR GLASS SET <i>/</i>	1	500.00	500.00

Labor Hours:

Labor Rate:

Labor:

Currency:

SIN \$

Shipping Method:

Shipping:

Subtotal: 3,066.20

Tax Rate: 7.00

Tax: 214.63

Total: 3,280.83



19 Looeng 8 Tia Pavoh
Singapore 319255



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SLT9517U	MODEL : FORESTER 2.0I-L AWD CVT
REF: INS/IC/CHI/0193/2021	YEAR: 17-NOV-2017
ENGINE NO: FB20YB31277	CHASSIS NO: JF1SJ5KC5JG099650
DOA: 06/09/2021	TOA: 2035HRS
TYPE OF CLAIM: TP	INS COMPANY: FIRST CAP

SN	NATURE OF JOB	AMOUNT
1	REPAIR/REPLACE FRT LH DOOR, LF WING MIRROR & PANEL 560	\$ 1680 00
2	RESPRAY FRT LH DOOR, LF WING MIRROR & PANEL 420	\$ 1260 00
3	TRANSFER DOOR MECHANISM (LH FRT)	\$ 200 00
4	CONDUCT FAULT DIAGNOSTIC AND RESET SYSTEMS	\$ 280 00
5	TO CONDUCT FRONT LIGHTING TEST	\$ 50 00
6	TO SUPPLY & INSTALL TINTED FILM (FRT LH WINDOW)	\$ 145 00
7	SUNDRIES	\$ 100 00
Total Labour		\$ 3715.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	Guo Qiang
HP / EMAIL:	82880282 GuoQiang@lkkauto.com
BEFORE PAINT:	Yes
DAYS GIVEN:	4

12/10/2021

After repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: