

AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : NG SI HUI

11 MOUNT SOPHIA, SOPHIA HILLS #03-38

Estimate No: MCS1900492

Date: 07 Sep 2021

Policy No: P10566701R00

Veh Reg No: SJX2317D

Make/Model: MAZDA 2

ATTN:

Your Ref No: SJX2317D

Claim Type: Third Party

Accident Date: 05/09/2021

TP Veh Reg No: SMM8472X

*Not Notified
11 Sep @ 2800h
Return After Pain*

4 days

Estimate Repair Cost to Vehicle No :SJX2317D

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR BUMPER	1 PC	1,033.20	✓
2 REAR BUMPER SIDE RETAINER	2 PC	36.40	✓
3 REAR BUMPER CLIP	10 PC	40.00	✓
4 REAR BUMPER REINFORCEMENT	1 PC	272.80	✓
5 TAILGATE	1 PC	1,243.50	✓
6 EMBLEM MAZDA	1 PC	29.20	✓
7 EMBLEM " 2 "	1 PC	20.50	✓
8 EMBLEM MAZDA BADGE	1 PC	44.20	✓
		2,719.80	
	Less 20%	543.96	2,175.84
Special Nett			
9 REVERSE SENSOR	1 PC	220.00	✓
10 NUMBER PLATE	1 PC	35.00	✓
11 WINDSCREEN SEALANT	2 PC	30.00	✓
		285.00	285.00
LABOUR			
12 TO CHECK WIRING AND INSTALL REVERSE SENSOR	1 PC	20.00	✓
13 TO DISMANTLE AND INSTALL REAR WINDSCREEN	1 PC	120.00	✓
14 TO DISMANTLE AND REPLACE TAILGATE TRANSFER TAIL GATE INNER PARTS, WIRING HANESS AND TRIM BOARD	1 PC	60.00	✓
15 TO DISMANTLE AND INSTALL DAMAGE PARTS, TO KNOCK AND REPAIR TAIL END PANEL AND AFFECTED AREA AND TO REFIT LISTED PARTS BACK SAME	1 PC	700.00	✓
16 TO SPRAY TAILGATE, REAR BUMPER, TAIL END PANEL AND REAR BUMPER REINFORCEMENT	1 PC	700.00	✓
		1,600.00	1,600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : NG SI HUI
11 MOUNT SOPHIA, SOPHIA HILLS #03-38

Estimate No: MCS1900492
Date: 07 Sep 2021
Policy No: P10566701R00
Veh Reg No: SJX2317D
Make/Model: MAZDA 2

ATTN:
Your Ref No: SJX2317D
Claim Type: Third Party
Accident Date: 05/09/2021
TP Veh Reg No: SMM8472X

Estimate Repair Cost to Vehicle No :SJX2317D

Description	Quantity	List Price	Amount
		SS	SS
		Total	S\$ 4,060.84
		Add GST @ 7%	284.26
		Total Amount Payable	S\$ 4,345.10

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND THREE HUNDRED FORTY FIVE AND CENTS TEN ONLY

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

