

ASS. REC. BY: TGum

REF:

CS/MSG21009552/Bqf3Hui Zhen

ASSIGNMENT

From: _____ Date: 14/9/2021

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SJP 39112at Workshop m/s Bifest Autoof 8 Keki Bt Ave 4 Premier # 01-49

Insured: _____

Policy No. _____

Claims No. 262447


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 19000/-

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJP 39112 Yr Regn: 23/3/2009Type: M / Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Fit 1.5 RS c.c. 1496Colour: white AC: Insured / Std / NI / NASp. Reading: Not batt power T/Radio: Insured / Std / NI / NAEng/No: L15A1568961C/No: GES1017122Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/55/15R: 195/55/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 10/9/2021 D.O.I. 14/9/2021Survey held at Bifest AutoDes. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Range 2000/- - 10,000/-</u>
11/11/2021	Revise to MSG via Merimen. Email to seek approval.
	<u>Recommended COR is LS \$ 9850.00</u> <u>TGum</u> <u>4/10/2021</u>
10/12/21	Christina ask offer LS \$9350.
06/04/22	Informed Christina, repairer refuse LS \$9350 & they request LS \$9850.
	<u>MV 19,000/-</u>
	<u>PV 6,429/-</u> 20/04/22 Christina appoved LS \$9850. <u>TGum</u> <u>15/9/2021</u>
	<u>MV 12,571/-</u>
20/04/22	Confirmed with Andrew LS \$9850, 12 days. (Red \$10708.01, 52%)

Date/Time, File Pass to? ☐ : Preli. Report1) 20/04 Typist ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: MER-TPLump Sum: 9850Days Of Repair: 12Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS: \$ _____

Photos

Others

TOTAL

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Estimate

Qty Spare parts

Vehicle No:
Make and model:
Chassis number:

SJP3911Z
Honda Fit RS
GE81017102

2009

1	Tailgate	\$	771.50	976.60 DDV
1	Tailgate "Fit" emblem	\$	28.60	31.64 NECV
1	Tailgate outer garnish	\$		130.90 NDX NDX
1	Tailgate centre emblem	\$	24.80	22.06 NECV
1	Tailgate windscreen glass rubber moulding	\$		✓ 136.20 NECV
1	Tailgate weatherstrip	\$		✓ 97.80 ? NDX
1	Tailgate lock	\$		✓ 186.30 JMV
1	Tailgate lock catch	\$		✓ 21.10 NDX
1	Tailgate inner trim board	\$		✓ 190.20 ? BRV
1	Tailgate inner pull handle	\$		22.10 NDX
1	Rear bumper	\$	460.30	578.10 BRV
1	Rear bumper lower garnish	\$	145.00	171.80 BRV
1	Rear bumper RH side retainer	\$	18.50	23.40 } NECV
1	Rear bumper LH side retainer	\$	18.50	23.40 }
1	End panel	\$	276.00	482.21 DDV
1	End panel inner garnish	\$		✓ 80.90 BRV
1	Rear LH fender	\$	685.00	706.90 DDV
1	Rear LH fender glass rubber seal	\$		22.60 NDX
1	Rear LH fender inner trim board	\$	203.20	280.70 ? BRV
1	LH taillamp assy	\$		✓ 353.40 BRV
1	LH taillamp panel	\$		93.20 ? NDX
1	RH taillamp assy	\$		✓ 353.10 ? BRV
1	Bonnet	\$	548.00	634.10 DDV
1	Bonnet RH hinge	\$		45.30 }
1	Bonnet LH hinge	\$		45.30 } ? NDX
1	Bonnet lock	\$		✓ 55.70 JMV
1	Front bumper	\$	523.00	582.20 BRV
1	Front bumper RH side retainer	\$		✓ 22.80 }
1	Front bumper LH side retainer	\$		✓ 22.80 } NECV
1	Front bumper reinforcement	\$		✓ 281.10 BTV
1	Front bumper towing cover	\$		✓ 18.30 BRV
1	Front bumper lower grille	\$		✓ 141.70 BRV
1	Front bumper RH side grille garnish	\$		✓ 27.50 ? } BRV
1	Front bumper LH side grille garnish	\$		✓ 27.50 ? }
1	Front grille	\$		✓ 183.70 BRV
1	Front grille emblem	\$		✓ 22.90 NECV
1	RH headlamp assy	\$	500.00	552.50 ? BRV
1	RH headlamp lower beam	\$		33.80 ? NDX
1	LH headlamp assy	\$	500.00	552.50 BRV

- 1 LH headlamp lower beam
- 1 Support panel
- 1 Aircon condenser
- 1 Aircon condenser fan assy
- 1 Aircon discharge pipe
- 1 Aircon suction pipe
- 1 Radiator assy
- 1 Radiator fan assy
- 1 Radiator upper hose
- 1 Radiator lower hose
- 1 Radiator RH side guide
- 1 Radiator LH side guide
- 1 Front RH fender
- 1 Front RH fender splash shield
- 1 Front RH fender
- 1 Front RH fender splash shield
- 2 Horns

\$	33.80	?NDX
\$	485.60	594.80 BTV
\$	660.00	704.40 } BRV
\$		759.30 } BRV
\$	117.00	231.80 } BI
\$	117.00	211.60 } BTV
\$	861.00	1,142.70 } BTV
\$	440.60	1,325.00 } BRV
\$	28.00	66.50 } TNV
\$	29.00	80.30 } TNV
\$		45.90 } NECV
\$		45.90 }
\$		364.80 NDX
\$		83.50 NDX
\$		364.80 } RPTX
\$		83.50 }
\$		87.60 NDX

\$	10,395.90	14,472.51
-20%	\$ 2,079.18	2,894.50
\$		11,578.01
	8,316.72	

Qty Spare parts

- 1 Tailgate windscreen glass sealant
- 1 Tailgate windscreen glass inner seal
- 1set Tailgate inner trim board clips
- 1 Tailgate reverse camera
- 1set Rear bumper clips
- 1set Rear bumper reverse sensor
- 1 End panel joint sealant
- 1set End panel inner garnish
- 1set Rear LH fender inner trim board clips
- 1 Rear LH fender joint sealant
- 1 Rear LH fender glass sealant
- 1 Rear LH fender glass inner seal
- 1 Exhaust silencer
- 1 Front number plate
- 1set Front bumper clips
- 1 Radiator coolant
- 1 Front RH fender splash shield clips
- 1 Front LH fender splash shield clips

\$	30.00	70.00 NECV
\$	30.00	50.00 NECV
\$	30.00	60.00 NECV
\$		550.00 ?NDX
\$	30.00	70.00 NECV
\$	200.00	280.00 SCV
\$	30.00	70.00 NECV
\$	30.00	50.00 NECV
\$	30.00	60.00 ?NECV
\$	30.00	70.00 NECV
\$	30.00	60.00 NECV
\$		50.00 ?NNX
\$		950.00 NDX
\$	30.00	70.00 BRV
\$	30.00	70.00 NECV
\$	30.00	60.00 }
\$	30.00	60.00 } ?NEC
\$	30.00	60.00 }
	620.00	

Labour and painting

(REAR PORTION)

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$	1,000.00	1,400.00
----	----------	----------

Spray painting on affected panels	\$ 600.00	1,200.00 ✓
Check wiring and lighting system	\$	80.00 NNX
Apply rust coating chemical on affected panels	\$	400.00 NNX
Remove and reinstall tailgate windscreen glass to assist repair	\$ 120.00	200.00 ✓
Remove and replace tailgate inner mechanism to new tailgate	\$ 80.00	100.00 ✓
Remove and replace tailgate reverse camera to assist repair	\$	100.00 NNX
Remove and replace rear bumper reverse sensors to assist repair	\$ 60.00	100.00 ✓
Remove and replace rear inner trims, garnish, roof lining, seats and boards to assist repair	\$ 150.00	350.00 ✓
Remove and reinstall LH rear fender glass to assist repair	\$	400.00 NNX
(FRONT PORTION)		
Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels	\$ 600.00	1,000.00 ✓
Spray painting on affected panels	\$ 600.00	1,000.00 ✓
Check wiring and lighting system	\$	50.00 NNX
Apply rust coating chemical on affected panels	\$	40.00 NNX
Remove and replace aircon condenser, pipes and fan assy to assist repair. To refill aircon gas	\$ 80.00	200.00 ✓
Remove and replace radiator assy, hoses and fan assy to assist repair. To refill coolant	\$ 80.00	200.00 ✓
Refocus and adjust headlamps assy	\$	50.00 NNX

3,370.00

Total: \$ 20,558.01

Survey
14/9/2021
1345 hrs

Resurvey
16/9/2021
1430 hrs

Lump sum repair
Repair days 12

T. Lim

T. Lim

Parts 8,316.72
SN 620.00
Labour 3,370.00

12,306.72
2,461.34

@20% 9845.38

LS 9850/2

T. Lim
4/10/2021

NV 12,571/2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	344B
Vehicle Details	
Vehicle No.:	SJP3911Z
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Sep 2021
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.5RSM
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	L15A1568961
Chassis No.:	GE81017102
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$13,850.00
Original Registration Date:	23 Mar 2009
First Registration Date:	23 Mar 2009
Transfer Count:	3
Actual ARF Paid:	\$13,850.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Mar 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$12,763.00
COE Rebate Amount:	\$6,429.00
Total Rebate Amount:	\$6,429.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Sep 2021

OK

MV 19,000/2
PV 6,429/2
NV 12,571/2

Rain Lin
15/9/2021

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

\$0 Down-payment, High Trade In Price In Market!!!



Bank Loan @ 1.88% & 100% In
House Financing @ 3.28%,
Approval Case Up To 99%!!!
SG Motors StarAd

KA-HUP

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997 [View our cars](#)

Browse by Category ▾

Sort by Reg. Date ▾ 20 results/page ▾

6 vehicles



Honda Fit 1.5

Advanced Search



Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Fit 1.5	Any	Any	> 10 year(s) old	Any	Any	Any	Available



Honda Fit 1.5A RS (COE till 12/2030)

\$56,888

\$6,120 /yr

14-Jan-2011

1,496 cc

105,210 km

Hatchback

Available

Very Well Maintained Unit. Keyless Entry. 2 Years Engine/Gearbox Warranty. Most Wear And Tear Done. Come Test Drive It Now. Own This Unit With A Peace Of Mind. High Loan Available With Flexible Interest Rate. Bank And In House Loan Supported. Buy And...

Posted: 08-Sep-2021 Tags: 2011 Honda Fit, Honda Fit, Honda, Fit

PREMIUM AD



Honda Fit 1.5M RS (COE till 09/2029)

\$56,800

\$7,120 /yr

04-Sep-2009

1,496 cc

128,888 km

Hatchback

Available

Small On The Outside, Big On The Inside! Be Surprised By The Amount Of Space This Hatchback Can Give You! Plenty Of Headroom & Legroom For The Adult In The Back! 1 AND ONLY MANUAL In The Market! Well Maintained By Previous Owner! View It To Believ...

Posted: 11-Sep-2021 Tags: 2009 Honda Fit, Honda Fit, Honda, Fit



Honda Fit 1.5A RS (COE till 04/2029)

\$51,800

\$6,790 /yr

29-Jun-2009

1,496 cc

-

Hatchback

Available

Full Loan Monthly At \$819 Only! One Of The Very Rare & Sought After RS Model In The Market! Very Difficult To Come By Once Missed This Opportunity! Bank/In House Loan At Low Interest Available! Responsive & Smooth Engine & Gearbox! No Headaches Fo...

Posted: 10-Sep-2021 Tags: 2009 Honda Fit, Honda Fit, Honda, Fit



Honda Fit 1.5A RS (COE till 03/2024)

\$21,800

\$8,760 /yr

12-Mar-2009

1,496 cc

140,000 km

Hatchback

Available

Pristine Condition! Pearl White! Full Service And All Wear And Tear Parts Done Up! 100% Loan Available From 1.88%P/A! 1 To 1 Exchange Without Cash Top Up! 2 Years Warranty/Service By Platinum Motoring In House Workshop. New 2k Metallic Paint Color...

Platinum Motoring

Posted: 15-Sep-2021 Tags: 2009 Honda Fit, Honda Fit, Honda, Fit

PREMIUM AD

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Honda Fit 1.5A RS (COE till 06/2023)

\$14,200

\$8,090 /yr

19-Jun-2008

1,496 cc

-

Hatchback

Available

Good Condition, Loan Available, Trade In Welcome.

Posted: 13-Sep-2021 Tags: 2008 Honda Fit, Honda Fit, Honda, Fit

DIRECT OWNER



Honda Fit 1.5A RS (COE till 11/2027)

\$45,800

\$7,370 /yr

27-Mar-2008

1,496 cc

134,300 km

Hatchback

Available

Full Loan Monthly At \$807 Only! One Of The Very Rare & Sought After RS Model In The Market! Very Difficult To Come By Once Missed This Opportunity! Bank/In House Loan At Low Interest Available! Responsive & Smooth Engine & Gearbox! No Headaches Fo...

Posted: 08-Sep-2021 Tags: 2008 Honda Fit, Honda Fit, Honda, Fit

Save this search criteria, to get email alerts whenever a match is found.

Compare

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Date of Accident : 10/9/2021 Accident Time: 07:35 (24-HR-FORMAT)
Accident Place : SLE towards CTE/TPE after Mandai Avenue Exit
Vehicle Reg. No (Car plate No.) : SJP 3011Z Vehicle Make/Model: Honda Fit
Insurance Company : NTUC Policy No. _____
Name of Registered Owner : Company / Individual Lam See Theng
ID of Registered Owner : Co Reg No: _____ Owner's NRIC No: S1245344B
: Co Contact No: _____ Owner's Contact No: _____
DRIVER'S Name : Lam Wan Cai, Willie DRIVER'S NRIC No: S4137298C
DRIVER'S Date of Birth : 10/10/1991 DRIVER'S License Pass Date 13 Jun 2019
Relationship bet. Owner & Driver : Spouse \ Parents Children \ Sibling \ Employee \ Others: _____
DRIVER'S Address : B1K 296 Choa Chu kang Avenue 2
DRIVER'S Contact No./ Alt No. : 1) 9231 8441 2) _____
DRIVER'S Occupation : INDOOR \ OUTDOOR (eg. working inside or outside of an ofc)
Email Address : solis_willie@hotmail.com
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance

Number of Passengers (including Driver): 1 Name & Gender; _____
Was the accident reported to the police? YES \ NO
Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any injuries, if yes (name of the injured person) Lam Wan Cai, Willie

Other Party Driver's Particulars (if any)

Vehicle Reg No: <u>SHC 2307S (C)</u>	Vehicle Reg No: <u>SLP 7844J (B)</u>
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name DRIVER: _____	Name DRIVER: _____
IC No. DRIVER: _____	IC No. DRIVER: _____
DRIVER'S Contact & add: _____	DRIVER'S Contact & add: _____

Describe Circumstances of the Accident

I was traveling along SLE towards CTE/TPE after Mandan Avenue EXH.

I noticed the vehicle SHC 2307S in front of me jammed brake and I

managed to stop in time. Suddenly, I felt a huge impact from the rear

which caused my vehicle to push forward and hit onto the vehicle in front.

I went down of my vehicle and realised I was involved in a chain collision

of 3 vehicle.

Declaration

I/We declare the foregoing particulars are true in every respect.





**SINGAPORE
POLICE FORCE**



T/20210910/7025

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20210910/7025

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/09/2021 13:42		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: LAM WEN CAI, WILLIE			Address: 296 CHOA CHU KANG AVENUE 2 #04-02 SINGAPORE 680296		
ID Type / ID No.: NRIC NO / S9137298C			Contact No.: Home/Office: Mobile: 92318441		
Nationality: SINGAPORE CITIZEN			Email: willie.lentorambulance@gmail.com		
Sex: Male	Age: 29	Date of Birth: 10/10/1991	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Paramedic			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 10/09/2021 07:20	Type of Location: Straight Road
Location: SELETAR EXPRESSWAY				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Conditio	No of
SHC2307S	Car	HYUNDAI				0
SJP3911Z	Car					0



**SINGAPORE
POLICE FORCE**



T/20210910/7025

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

2 of 3

Report No. T/20210910/7025

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LAM WEN CAI, WILLIE	ID No.	S9137298C
Related Vehicle	SJP3911Z (Car)	Contact No.	92318441
Hospital/Clinic	EVERCARE MEDICAL CLINIC	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	03	Degree of	Slight

Brief Details.

I was traveling along SLE towards CTE/TPE after Mandai Avenue Exit and i noticed the vehicle SHC2307S jammed brake and i managed to stop in time. Suddenly, i felt a huge impact from the rear which caused my vehicle to push forward and knocked onto the car in front. I got down of my vehicle and realised i was knocked by SLP7844J and was involved in a chain collision of 3 cars.



**SINGAPORE
POLICE FORCE**



T/20210910/7025

3 of 3

Report No. T/20210910/7025

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
SYED ZAYID MUHAMMAD BIN SYED ABDUL

Signature Of Informant:
The identity of the person making this report has
been authenticated by Singpass. No signature is
required.

Date/Time:
10/09/2021 13:42

Classification Of Case: