

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21009553/R1VF3E2

Date: 17/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070178736
Claimant Vehicle No :	SLQ1839J	Insured Vehicle No :	SMR3708Z
Date of Loss:	10/09/2021	Nature of Claim:	TP
		Claim No:	2733485093SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ1839J	Engine No:	R16B22000019
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650HT000006
Reg. Date:	29/06/2017 (Man. Year: 2017)	Odometer:	88002 km
Colour:	Black		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40Z R18	Rear Tyre Size:	235/40Z R18
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	13/09/2021	8 Paragon Pte Ltd (HQ)
Date Inspected:	14/09/2021 Inspected At:	71 WOODLANDS AVE 10 #01-10 WOODLANDS INDUSTRIAL XCHANGE
Estimated Period of Repair:	8.0 days	Singapore 737743

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT GRILLE	Cracked	0.00 F	*- F
3	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
4	1		*FRT GRILLE CHROME LOWER	Cracked	0.00 F	*- F
5	1		*FRT SUPPORT PANEL LH	Bent	0.00 F	*- F
6	1		*FRT LH HEADLAMP ASSY GARNISH	Scratched	0.00 F	*- F
7	1		*BONNET	Bent	0.00 F	*- F
8	1		*FRT GRILLE TOP BASE	Cracked	0.00 F	*- F
9	1		*REAR BUMPER	Deformed	0.00 F	*- F
10	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
11	1		*REAR BUMPER LOWER SPOILER	Deformed	0.00 F	*- F
12	1		*BOOTLID	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
--------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >