

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SJD2577A

Accident Date : 11/9/2021

Location : PIE TOWARDS TUAS BEFORE BRADDELL EXIT

TP A16
Justin

Model:

TOYOTA WISH 1.8

(14/3/2008)

3P:

SDJ8278M(AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Deformed</i>	881.66		
2	8 pcs	Rear bumper clips <i>new</i>		40.00	30
3	2 pcs	Rear bumper o/s & n/s stay <i>new</i>	85.80		
4	2 pcs	Rear bumper o/s & n/s retainer <i>new</i>	234.60		
5	2 pcs	Rear o/s & n/s reflector <i>new</i>	124.60	X	
6	1 pc	Rear tail gate <i>Deformed</i>	1217.3		
7	1 pc	Rear tail gate weatherstrip <i>new</i>	289.90		
8	1 pc	Rear tail gate emblem <i>new</i>	81.70		
9	1 pc	Rear tail gate moulding chrome <i>new</i>	387.72		
10	6 pcs	Rear tail gate moulding clips <i>new</i>		30.00	
11	1 pc	Rear tail gate inner trim <i>new</i>	591.75		
12	8 pcs	Rear tail gate inner trim clips <i>new</i>		40.00	30
13	1 pc	Rear tail gate lock (upper) <i>Deformed</i>	322.70		
14	1 pc	Rear tail gate lock (lower) <i>new</i>	124.80		
15	1 pc	Rear end panel <i>Deformed</i>	455.65		
16	1 pc	Rear end panel inner trim <i>Deformed</i>	289.90		
17	4 pcs	Rear end panel inner trim clips <i>new</i>		20.00	
18	2 pcs	Rear o/s & n/s tail lamp <i>n/s new</i>	845.98	409	
19	1 pc	Rear windscreen sealant <i>new</i>		30.00	
20	1 pc	Rear windscreen moulding <i>new</i>		80.00	
21	1 set	Rear reverse sensor <i>Damaged</i>		280.00	200 (50)
Sub Total:			5,934.06	520.00	0.00
25%				0%	0%
After Less %:			4,450.55	520.00	0.00
Labour					
1		To dismantle damaged portion, straighten & welding.	1,200.00	800	
2		To spray painting	800.00	700	
3		To remove and refit rear windscreen	140.00	120	
4		To remove and replace rear reverse sensor	50.00		
5		To remove and refit rear reverse camera	50.00		
6		To check wiring	80.00	30	
7		To re seal anti rust	80.00	60	
Sub Total:			2,400.00		
Total:			7,370.55		
After Less 20%:			5,896.44		

Chan San Choon
Director

DipEng, AAE MIMI,MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

Date:

Acknowledged by Repairer: SJD2577A ESTIMATE Pg1



Adrian
2/5 13/09/21
06 Days
Total: 5128.93
H/S: 4.11K