

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SJD64B

Accident Date : 11/9/2021

Location : CTE TOWARDS CITY BEFORE MOULMEIN EXIT

Model: TOYOTA COROLLA ALTIS
(20/2/2018)

3P: FBS8350M (III)

TP III
Ceiling.

MROS3REH60458605

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Dehnd</i>	585	681.40	
2	10pcs	Rear bumper clips <i>new</i>		30.00	✓
3	1pc	Rear bumper screw clips <i>new</i>		20.00	+
4	1pc	Rear bumper n/s reflector <i>new</i>	128.60		
5	1pc	Rear bumper n/s retainer <i>new</i>	55	98.60	
6	2pcs	Rear reverse sensor <i>new</i>		380.00	+
7	1pc	Rear n/s tail-lamp <i>new</i>	353	582.10	
8	1pc	Rear n/s tail-lamp retainer <i>new</i>	45	280.30	
9	1pc	Rear n/s tail-lamp panel <i>Dehnd</i>	374	563.80	
10	1pc	Rear n/s tail-lamp seal <i>new</i>		30.00	20
11	1pc	Rear n/s fender <i>Dehnd</i>	987	1,336.80	
12	1pc	Rear n/s fender wheel guard <i>Dehnd</i>	55	163.80	
13	1pc	Rear n/s fender wheel guard clips <i>new</i>		24.00	10
14	1pc	Rear n/s fender air vent <i>new</i>		205.60	X
15	1 pc	Rear windscreen sealant <i>new</i>		60.00	✓
16	1 pc	Rear windscreen inner seal <i>new</i>		50.00	✓
17	1 pc	Rear n/s rim <i>cut</i>		2,010.70	700 (SW)
		Sub-Total:	2470	6,081.70	564.00
			S/N: 850	25%	0%
		After Less %:	1852.50	4,561.28	564.00
		Labour			
1		To dismantle damaged parts, straighten & welding.		1,400.00	600
2		To spray painting.		1,000.00	600
3		To remove & refit rear windscreen, rear seats & roof lining.		280.00	120
4		To remove & replace rear reverse sensor camera.		50.00	✓
5		To remove & refit rear n/s tyre			X.
6		To check wiring.		60.00	30
7		To re-seal anti-rust.		60.00	40
		Sub-Total:	1440	2,850.00	
		Total:		7,975.28	
		After Less 20%:		6,380.22	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



SAFE 8778 1999
SJD64B ESTIMATE Pg 1

Mobil 1



total: 4142.50
h/s: 3.3K

Adrian Lij
L/S 13/09/21.
0 Sprays