



2 Kaki Bukit Ave 2, #02-19 / 02-22 @ Kaki Bukit Auto Hub, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

GST REG NUMBER: 201635107M

India International Insurance Pte Ltd

16/12/2021

64 Cecil Street

#04-02, #05-02, #06-02

IOB Building

Attn: CECILIA CHONG

Motor Claims Dept

TAX INVOICE

Our Ref : SJD64B (987) Your Ref : -

Dear Sir,

VEHICLE # : SJD64B

ACCIDENT INVOLVING : SJD64B & FBS8350M ALONG CTE TOWARDS CITY BEFORE MOULMEIN
EXIT ON 11/9/21

COST OF REPAIR \$3,300.00 (As agreed)

COST OF REPAIR ADD GST 7% \$231.00

TOTAL \$3,531.00

Three Thousand Five Hundred Thirty-One Singapore Dollars Only

Please arrange for DV to be signed by us (workshop) because we are authorised by client to sign on behalf. Please see attached Letter of authorisation (see note 5) .

For your prompt payment.
Thank you.

Yours faithfully,
Ryder Auto Pte Ltd

Chan San Choon

Director

DipEng, AAE MIMI, MSAE(Aust)

