

Ull Lspv

Not Award



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SJT9411P

Model : Daihatsu Terios

Damaged Area: (Rear Portion)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

13/9/21
4/5 \$6000/
7 days.

Parts / Material :

1	Rear bumper	20 / pc	850	\$	1,377.10	✓
2	Rear bumper side retainer @ SGD 84.20	2 / 5 Bent	49	\$	168.40	1 pc
3	Rear bumper clips (SET)	ner	50	\$	65.00	✓
4	Taillamp @ SGD 486.10	0 / 5 one	305	\$	972.20	1 pc
5	Tailgate	Bed by 20	885	\$	1,680.25	✓
6	Tailgate logo	ner	52	\$	98.50	✓
7	Tailgate emblem (Terios)	ner	66	\$	115.40	✓
8	Tailgate emblem (4WD)	ner	60	\$	128.10	✓
9	Tailgate emblem (Daihatsu)	ner	58	\$	125.40	✓
10	Tailgate inner lock	11		\$	118.20	X
11	Tailgate weather strip	7w1	222	\$	245.90	✓
12	Tailgate hinge @ SGD 121.50	11		\$	243.00	X
13	Tailgate inner trimboard	20 / 100	355	\$	780.10	✓
14	Spare tyre outer garnish cover	one	1215	\$	1,459.30	✓
15	Spare tyre inner garnish cover	one	499	\$	535.70	✓
16	Spare tyre garnish bracket	2		\$	385.60	X
17	Rear end panel top garnish trim	11		\$	368.40	X
18	Rear end panel inner	2		\$	1,089.20	X
19	Rear end panel outer	Bed by 20	485.00	\$	945.36	✓
20	Rear floor panel	2		\$	1,177.68	X
21	Rear fender inner trim board	0 / 5	405.00	\$	585.64	✓
22	Rear exhaust pipe	2		\$	937.80	X

15%

Parts : \$ 13,602.23
Less Parts 10% : \$ 1,360.22
Total Parts : \$ 12,242.00

Special Net Items :

Rear End Panel Sealant	ner	\$	80.00	50
Floor Panel Sealant	11	\$	80.00	X
Rear Tailgate Glass Inner Seal, Sponge Tape, clips	ner	\$	118.00	30
Rear Tailgate Glass Sealant	ner	\$	80.00	40
Reverse sensor	should	\$	280.00	200
Rear Number Plate 'lamp	one	\$	80.00	50
Total S/N Parts : \$				718.00

1 set

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas	\$ 1,200.00	1000
To Putty, Spray Paint on Affected Accident Areas	\$ 1,400.00	1100
To Check & Re-Connect all electrical wiring	\$ 50.00	30
To Remove & Install Rear Tailgate Components Trim & Garnish	\$ 150.00	80
To Remove & Install Rear Fenders Trim, Garnish, Spare Tyre Compartment	\$ 150.00	80
To Remove & Install Rear Tailgate Glass to Facilitate Repairs	\$ 150.00	120
To Re-position & Align Reverse Sensor	\$ 120.00	50
To Conduct Water Leakage Test	\$ 150.00	X
To Rust Proof Affected Areas	\$ 200.00	60
Total Labour :	\$ 3,570.00	

TOTAL PARTS :	\$ 12,424.00
TOTAL SPECIAL NET ITEM :	\$ 718.00
TOTAL LABOUR :	\$ 3,570.00
TOTAL REPAIR COST :	\$ 16,712.00

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-5556

152

9-4722-60

S.N-370-00

L-2520-00

7612-6