

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/GRB21009115/R1QF3E2-1**Date:** 24/01/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447  
**Claimant Vehicle No :** FBQ8365G **Insured Vehicle No :** SLV7029P  
 Date of Loss: 24/08/2021 Nature of Claim: TP Claim No: MFL2021D0003703

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBQ8365G**  
 Make & Model: HONDA CB 400 F3WYB, 399cc (M) Engine No: NC56E5000265  
 Reg. Date: 26/12/2019 (Man. Year: 2019) Chassis No: JH2NC569XKK000263  
 Colour: Black Odometer: 20245 km  
 Engine Capacity: 399 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80 R19 Rear Tyre Size: 160/60 R17  
 Front Left Side: MITAS 4 mm Rear Left Side: MITAS 4 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,105.00	1,571.50	1,533.50	49.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	250.00	150.00	100.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,355.00</b>	<b>1,721.50</b>	<b>1,633.50</b>	<b>48.69</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,350.00</b>		
<b>Nett Amount (S\$)</b>	<b>3,355.00</b>	<b>1,350.00</b>	<b>2,005.00</b>	<b>59.76</b>

INSPECTION

Date of Assignment: 13/09/2021  
 Date Inspected: 31/08/2021 Inspected At: Brother Motors (HQ)  
 BLK 1016 YISHUN INDUSTRIAL PARK A, #01-218  
 Singapore 768758  
 Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 24 Jan 2022)	
Parts:	N/A	HONDA CB 400 F3WYB 399cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBQ8365G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FRONT FORK	Bent	900.00 F	*450.00 FL
2	1		*FRONT WHEEL RIM	Scratched	480.00 FS	*100.00 FS
3	1		*FRONT BRAKE DISC	Not Necessary	380.00 F	*- FL
4	1		*HANDLE BAR	Bent	195.00 F	*195.00 FL
5	1		*HAND GUARD	Cut	380.00 F	*380.00 FL
6	1		*GEAR PEDAL	Bent	110.00 F	*110.00 FL
7	1		*ENGINE GUARD	Scratched	500.00 F	*500.00 FL
8	1		*STEERING CONE / BEARING	Not Necessary	160.00 F	*- FL
					<b>Sub Total (\$\$)</b>	<b>3,105.00 1,735.00</b>
					<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00 163.50</b>
					<b>Total Parts (\$\$)</b>	<b>3,105.00 1,571.50</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TRANSPORT COST + LABOUR CHARGES	New	250.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>250.00</b>	<b>150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >