



Blk 1016 Yishun Industrial Park A, #01-218, Singapore 768758

Tel / Fax : 67542558

Company Reg No: 53076955K

ASSESSMENT OF DAMAGE AND COSTS

VEHICLE NO: FBQ8365G

A SPARE PARTS

Description LIST ITEMS	Qty	Assessed Condition	Repairer's Amount S\$	Our revised Amount S\$
Front Fork Set <i>bt</i>	1	Bent	900.00	450.00
Front Wheel Rim <i>repair - h - 100</i>	1	Bent	1635	240.00 X
Front Brake Discs <i>Xm</i>	1	Bent	10%	290.00 X
Handle Bar <i>bt</i>	1	Bent	195.00	195.00
Hand Guard <i>cut</i>	1	Sliced	1471.50	380.00
Gear Pedal <i>bt</i>	1	Sliced	110.00	110.00
Engine Guard <i>see</i>	1	Broken	500.00	500.00
Steering Cone/ Bearing <i>Xm</i>	1	Broken	160.00	160.00 X

B) LABOUR

i) Transport cost + Labour Charges

Labour = 100 + 150 = 250

250.00

200.00 150

Total Cost of repairs (Total Cost of parts + labour cost): \$ 3,355.00 \$ 2,525.00

1471.50

250.00

1721.50

20%

81377.20

4/5 - \$1350

Paul

Hp 90010068

2 days

4/5

31/08/21 @ 1525

Resum after repair