

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21009573/UPS3Q2  
**Date:** 26/10/2021**REFERENCE**

|                              |                                      |                             |               |
|------------------------------|--------------------------------------|-----------------------------|---------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1700088989-03 |
| <b>Claimant Vehicle No :</b> | SMZ9206Z                             | <b>Insured Vehicle No :</b> | SLV2419E      |
| Date of Loss:                | 11/09/2021                           | Nature of Claim:            | TP            |
|                              |                                      | Claim No:                   | 7366125164SG  |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |              |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No:                     | <b>SMZ9206Z</b>                   |             |              |
| Make & Model:               | TOYOTA NOAH HYBRID, 1.8 X CVT (A) | Engine No:  | 2ZR2L65997   |
| Reg. Date:                  | 25/05/2021 (Man. Year: 2021)      | Chassis No: | ZWR800489509 |
| Colour:                     | White                             | Odometer:   | 9387 km      |
| Engine Capacity:            | 1797 cc                           |             |              |
| Market Value/New Car Price: | N/A                               |             |              |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |              |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195/65 R15    | Rear Tyre Size:  | 195/65 R15    |
| Front Left Side:  | Yokohama 8 mm | Rear Left Side:  | Yokohama 8 mm |
| Front Right Side: | Yokohama 8 mm | Rear Right Side: | Yokohama 8 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 13,245.40         | 5,070.51          | 8,174.89          | 61.72         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 3,570.00          | 1,830.00          | 1,740.00          | 48.74         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>16,815.40</b>  | <b>6,900.51</b>   | <b>9,914.89</b>   | <b>58.96</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>5,500.00</b>   |                   |               |

|                                                 |                  |                 |                  |              |
|-------------------------------------------------|------------------|-----------------|------------------|--------------|
| (S\$)                                           | 16,815.40        | 5,500.00        | 11,315.40        | 67.29        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 1,177.08         | 385.00          | 792.08           | 67.29        |
| <b>Nett Amount (S\$)</b>                        | <b>17,992.48</b> | <b>5,885.00</b> | <b>12,107.48</b> | <b>67.29</b> |
| <b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b> |                  | 300.00          |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                  | 2.00            |                  |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>6,187.00</b> |                  |              |
| <b>Global Sum Settlement (S\$)</b>              |                  | <b>6,180.00</b> |                  |              |

INSPECTION

Date of Assignment: 13/09/2021

Date Inspected: 13/09/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)  
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay  
 Singapore 417883

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                  | Condition       | Repairer's | Amount       |
|-----|-----|----------|----------------------------------------------|-----------------|------------|--------------|
| 1   | 1   |          | *SLIDING DOOR N/S                            | Dented / Bent   | 1,969.10 F | *1,861.25 FL |
| 2   | 1   |          | *SLIDING DOOR GLASS REGULATOR N/S            | Not Necessary   | 485.50 F   | *- FL        |
| 3   | 1   |          | *SET SLIDING DOOR FRAME BLACK STICKER N/S    | Necessary       | 105.00 F   | *100.00 FL   |
| 4   | 1   |          | *SLIDING DOOR INNER RUBBER N/S               | Not Necessary   | 288.20 F   | *- FL        |
| 5   | 1   |          | *SLIDING DOOR INNER TRIM BOARD N/S           | Deformed / Torn | 1,099.10 F | *945.10 FL   |
| 6   | 1   |          | *ROCKER PANEL GARNISH N/S                    | Torn / Cut      | 850.00 F   | *850.00 FL   |
| 7   | 1   |          | *ROCKER PANEL N/S                            | Repair          | 825.10 F   | *- FL        |
| 8   | 1   |          | *REAR FENDER N/S                             | Repair          | 1,466.20 F | *- FL        |
| 9   | 1   |          | *REAR FENDER UNDER TRIM N/S                  | Distorted       | 362.00 F   | *282.30 FL   |
| 10  | 1   |          | *REAR BUMPER                                 | Torn            | 1,685.10 F | *1,066.10 FL |
| 11  | 1   |          | *REAR BUMPER SIDE RETAINER N/S               | Not Necessary   | 105.00 F   | *- FL        |
| 12  | 1   |          | *REAR SHOCK ABSORBER N/S                     | Twisted         | 425.10 F   | *392.10 FL   |
| 13  | 1   |          | *REAR WHEEL HUB BEARING N/S                  | Damaged         | 850.00 F   | *450.50 FL   |
| 14  | 1   |          | *REAR AXLE BEAM                              | Not Necessary   | 1,450.00 F | *- FL        |
| 15  | 1   |          | *SET SLIDING DOOR INNER TRIM BOARD CLIPS N/S | Necessary       | 60.00 FS   | *60.00 FS    |
| 16  | 1   |          | *SET REAR BUMPER CLIPS                       | Necessary       | 60.00 FS   | *50.00 FS    |
| 17  | 1   |          | *REAR SPORT RIM N/S                          | Cut             | 900.00 FS  | *450.00 FS   |
| 18  | 1   |          | *REAR TYRE N/S                               | Serviceable     | 200.00 FS  | *- FS        |
| 19  | 1   |          | *SET ROCKER PANEL GARNISH CLIPS N/S          | Necessary       | 60.00 FS   | *50.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                         |                  |                 |
|---------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$)</b>                                   | <b>13,245.40</b> | <b>6,557.35</b> |
| <b>- List Item Discount on L Items 0.00/25.00% (\$)</b> | 0.00             | 1,486.84        |
| <b>Total Parts (\$)</b>                                 | <b>13,245.40</b> | <b>5,070.51</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                     | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------------|----------|-----------------|-----------------|
| <u>Labour Items</u>             |                                                 |          |                 |                 |
| 1                               | TO CHECK WIRING                                 | New      | 50.00           | 20.00           |
| 2                               | TO DISMANTLE & REFIX REAR BUMPER REVERSE SENSOR | New      | 80.00           | 50.00           |
| 3                               | TO TRANSFER SLIDING DOOR MECHANISM N/S          | New      | 120.00          | 60.00           |
| 4                               | TO DISMANTLE & REFIX CUSHION UPHOLSTERY         | New      | 150.00          | 80.00           |
| 5                               | TO CONDUCT WHEEL ALIGNMENT                      | New      | 120.00          | 80.00           |
| 6                               | TO DISMANTLE & REPLACED REAR UNDER CARRIAGE     | New      | 250.00          | 120.00          |
| 7                               | TO SPRAY RUST RPOOFING                          | New      | 100.00          | 40.00           |
| 8                               | LABOUR FOR PANEL BEATING & RPELACING PARTS      | New      | 1,200.00        | 580.00          |
| 9                               | TO PUTTY & SPRAY PAINTING                       | New      | 1,500.00        | 800.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                 |          | <b>3,570.00</b> | <b>1,830.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >